

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Keny Ong Thiam Beng

Date: 18 May 2020

Preliminary Advice

Insured Vehicle No	: SLP1992D	Accident Date	: 17/02/2020
TP Vehicle No	: FBD6952T	Assignment Date	: 02/03/2020
Make	: YAMAHA X-1R	Est. Duration of Repair	: 4.00
Date of Inspection	: 03/03/2020		
Inspection At	: JEC AUTO SERVICE (HQ) 1 KAKI BUKIT AVENUE 6 #02-11, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,981.00
Revised Amount	:S\$	3,002.90
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,002.90
Lump Sum Repair	:S\$	2,400.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.