



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail		Account No S1000013 /ICPI1	Customer Detail
Sampo Insurance Singapore Pte Ltd 50 Raffles Place #05-01/06 Singapore Land Tower Singapore 048623 Attn: Motor Claims Dept		Document No 0	Mr Lim Kim Choy 503 Sembawang Road #01-20 Singapore 757707
		Document Date 29/02/2020	Mobile: 96755785 <i>lkk</i> <i>Tue 3/2 - 2pm</i>

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	BEXGB	L3	AVV60R	15/07/2016	SLD0128C	0	18347 :10D/SLD0128C/280221

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBW1GGX02127471	2AR1512308	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:D19MTPV01010460 ACC DATE:28.02.2020 TOW/DRIVE IN: DRIVE IN EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50 100.00
2	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.				
3	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON FRONT BUMPER, RHS FRONT FENDER AND FIX NEW PARTS 866			1732	2598.00
4	B	BP-RES3 TO SPRAY PAINT ON FRONT BUMPER AND RHS FRONT FENDER 742			1484	2226.00
5	B	BP-LAB3 TO REMOVE AND REPLACE HEADLAMPS. CHECK AND FOCUS HEADLIGHTS (NETT)				216.50
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
<i>Steve CLKK</i> <i>8322 8813</i>	Please acknowledge receipt of vehicle <i>DD - NH Author (Remt)</i> <i>EXCESS - ?</i> <i>3/3/22, 2.20pm</i> <i>P/P</i>	Parts Labour Materials Lubrication/Fluid Others	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Amount Due

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 29/02/2020
TIME 10:05

VEHICLE NO SLD0128C

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
Sompo Insurance Singapore Pte Ltd 50 Raffles Place #05-01/06 Singapore Land Tower Singapore 048623 Attn: Motor Claims Dept	S1000013 / ICPI1	Mr Lim Kim Choy 503 Sembawang Road #01-20 Singapore 757707
	Document No 0	Mobile: 96755785
	Document Date 29/02/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	BEXGB	L3	AVV6OR	15/07/2016	SLD0128C	0	18347 10D/SLD0128C/280221

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBW1GGX02127471	2AR1512308	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
6	B	BP-LAB3 TO REMOVE AND TRANSFER FRONT PARKING SENSOR TO NEW BUMPER, REPLACE IF DAMAGE (NETT)				216.50 /
7	B	BP-ECU3 TO RESET ECU & REPROGRAMME (NETT)				216.50 /
8	1	L52119-3T910 COVER, FR BUMPER / BR	1.00	960.30		960.30
9	2	L53102-33080 GRILLE SUB-ASSY, / CH	1.00	879.60		879.60
10	3	L53155-33060 SEAL, RADIATOR / MC	1.00	100.70		100.70
11	4	L52611-33280 ABSORBER, FR BUMPER / ?	1.00	154.30		154.30
12	5	L52021-33210 REINFORCEMENT	1.00	498.80		498.80
13	6	L81481-33060 COVER, FOG LAMP, RH / BR	1.00	141.60		141.60
14	7	L52125-33120 BRACKET, FOG LAMP / ?	1.00	168.50		168.50
15	8	L53879-30040 RETAINER, FR FENDER / MC	2.00	12.30		24.60
16	9	L47749-50090 CLIP / MC	4.00	1.80		7.20
17	0	L52197-30040 BUMPER BRACKET, / MC	2.00	7.70		15.40
18	1	L52145-33070 STAY, FR BUMPER / BR	1.00	57.40		57.40
19	2	L52128-33210 COVER, FR BUMPER / ?	1.00	86.60		86.60
20	3	L53127-33020 GRILLE, RADIATOR, / ?	1.00	43.00		43.00
21	4	L53811-33230 FENDER, FR RH / DO	1.00	1339.60		1339.60

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 29/02/2020
TIME 10:05

VEHICLE NO SLD0128C

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Inchcape



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
Sompo Insurance Singapore Pte Ltd 50 Raffles Place #05-01/06 Singapore Land Tower Singapore 048623 Attn: Motor Claims Dept	S1000013 /ICPI1	Mr Lim Kim Choy 503 Sembawang Road #01-20 Singapore 757707
	Document No 0	Mobile: 96755785
	Document Date 29/02/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIPNo	Order No/Remarks
16	BEXGB	L3	15/07/2016	SLD0128C	0	18347	10D/SLD0128C/280221

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBW1GGX02127471	2AR1512308	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
22	5	L53875-33220 LINER, FR FENDER RH MC ?	1.00	278.20		278.20
23	6	T90467-07214 CLIP MC	12.00	2.60		31.20
24	7	L81106-33B80 HOUSING SUB-ASSY, MC CUT	1.00	6185.20		6185.20
25	8	L81210-48051 LAMP ASSY, FOG RH	1.00	516.00		516.00
26	9	L90975-02126 EMBLEM, SYMBOL MC	1.00	477.90		477.90
27	0	L89348-78020 RETAINER, ULTRASONIC MC	2.00	16.40		32.80
28	1	L89348-35030 CLIP, ULTRASONIC MC	2.00	4.30		8.60
29	2	L89341-78010 B2 SENSOR, ULTRASONIC, MC SL1	1.00	490.80		490.80
30	3	L85315-33461 JAR, WASHER, A ?	1.00	273.50		273.50
31	4	L85330-47010 MOTOR & PUMP ASSY	1.00	291.60		291.60
32	5	L53121-33080 MOULDING, RADIATOR MC CUT	1.00	372.10		372.10
33	6	L53111-33450 GRILLE, RADIATOR ?	1.00	1168.70		1168.70
34	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.				
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 14,604.20	20,177.70
		Labour 5,573.50	GST 7.00% 1,412.44
		Materials 0.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 21,590.14

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 29/02/2020
TIME 10:05

VEHICLE NO SLD0128C

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape