

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 2/3/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO.SLR274P

CHASSIS NO : GP71046221

MAKE / MODEL : Honda Shuttle 1.5 Hybrid

DATE OF ACCIDENT : 29/02/2020

YOUR INSURED VEHICLE NUMBER : GBC2904P

MILEAGE : 225952 Km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	Rear tailgate	1PC	\$ 1,850.00	\$ 1,850.00	bt ✓
2	Rear tailgate windscreen moulding	1PC	\$ 195.00	\$ 195.00	new ✓
3	Rear tailgate windscreen glass	1PC	\$ 2,850.00	\$ 2,850.00	br ✓
4	Rear back door Honda emblem	1PC	\$ 81.30	\$ 81.30	new ✓
5	Rear back door VEZEL emblem	1PC	\$ 86.80	\$ 86.80	new ✓
6	Rear tailgate HYBRID emblem	1PC	\$ 86.00	\$ 86.00	new ✓
7	Rear tailgate lock	1PC	\$ 380.00	\$ 380.00	bt ✓
8	Rear tailgate door lock catch	1PC	\$ 120.00	\$ 120.00	bt ✓
9	Rear tailgate weatherstrip	1PC	\$ 280.00	\$ 280.00	twi ✓
10	Rear tailgate rear inner trim cover	1PC	\$ 500.00	\$ 500.00	de ✓
11	Rear tailgate licence lamps	1PC	\$ 120.00	\$ 120.00	x
12	Rear tailgate chrome garnish	1PC	\$ 550.00	\$ 550.00	chr ✓
13	Rear wiper motor assy	1PC	\$ 600.00	\$ 600.00	x
14	Rear wiper blade	1PC	\$ 30.00	\$ 30.00	cut ✓
15	Rear wiper arm	1PC	\$ 130.00	\$ 130.00	cut ✓
16	Rear bumper	1PC	\$ 1,680.00	\$ 1,680.00	de ✓
17	Rear bumper lower skirt	1 PC	\$ 550.00	\$ 550.00	x
18	Rear bumper RH reflector	1PC	\$ 132.80	\$ 132.80	?
19	Rear bumper LH reflector	1PC	\$ 132.80	\$ 132.80	x
20	Rear end panel	1PC	\$ 830.00	\$ 830.00	bt ✓
21	Rear end panel top garnish	1PC	\$ 155.00	\$ 155.00	de ✓
22	Rear spare tyre panel	1PC	\$ 1,200.00	\$ 1,200.00	ro ✓
23	Rear spare toolkit compartment box	1PC	\$ 550.00	\$ 550.00	de ✓
24	R/L tail lamp	1PC	\$ 850.00	\$ 850.00	chr ✓
25	R/L tail gate reflector	1PC	\$ 720.00	\$ 720.00	chr ✓
26	R/R taillamp	1PC	\$ 850.00	\$ 850.00	chr ✓
27	R/R tail gate reflector	1PC	\$ 720.00	\$ 720.00	chr ✓
28	Rear smart buzzer	1PC	\$ 180.00	\$ 180.00	? photo
				LIST TOTAL S\$:	\$ 16,409.70
				20% DISCOUNT S\$:	\$ 3,281.94
					\$ 13,127.76

SPECIAL NETT

1	Bumper and end panel clips	1 SET	\$	200.00	40wa ✓
2	Reverse sensor	1 SET	\$	260.00	200nw ✓
3	Body sealant	1PC	\$	300.00	60wa ✓
4	Windscreen sealant	1PC	\$	100.00	60 ✓
5	Rear number plate	1PC	\$	50.00	end ✓ 45.
6	DECAL	1PC	\$	20.00	new ✓

Special Nett Total S\$: \$ 930.00

LABOUR CHARGES

- 1 To labour charge for removing rear back door, rear end panel, spare tyre panel, rear bumper to facilitate repairs and replacement of damaged parts \$ 1,750.00 1200
- 2 To respray rear bumper, rear back door, spare tyre panel and end panel \$ 1,400.00 0 1000
- 3 Transfer door mechanism to facilitate repairs and replacement of parts \$ 120.00 60
- 4 To remove & install rear windscreen glass \$ 180.00 120
- 5 To conduct a standard of operating procedures post repairs scan test as a requirements upon completion of collision repairs \$ 300.00 150
- 6 To deactivate and activate high voltage hybrid battery as a safety precautions \$ 300.00 150? plus
- 7 To provide transport for DECAL at VICOM \$ 100.00 60

LABOUR TOTAL S\$: \$ 4,150.00
TOTAL S\$: \$ 18,207.76
7% GST \$ 1,274.54
GRAND TOTAL S\$: \$ 19,482.30

Tanfilm 97495749
'wp'
2/3/2020 5:15pm
7 days

Tanfilm @ lkkauto.com
Lumpsum
Resurvey after repair.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: