

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMP 9119U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER SIDE HOLDER RH (CONSISTENT)	NECESSARY	68.00	68.00
1	FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
1	HEADLAMP RH (CONSISTENT)	CRACKED	1,195.00	1,195.00
1	FRONT RH FENDER (ALUMINIUM) (CONSISTENT)	DENTED	891.00	891.00
1	FRONT RH FENDER INNER SHIELD (CONSISTENT)	TORN	232.00	232.00
1	FRONT RH FENDER INNER SHIELD CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT RH LOWER ARM (CONSISTENT)	NOT NECESSARY	475.00	-
1	FRONT RH KNUCKLE ARM (CONSISTENT)	NOT NECESSARY	862.00	-
1	FRONT RH WHEEL HUB BEARING (CONSISTENT)	NOT NECESSARY	387.00	-
1	FRONT RH SHOCK ABSORBER (CONSISTENT)	NOT NECESSARY	598.00	-
	LESS 10% DISCOUNT		-	-244.60
			4,768.00	2,201.40
	SPECIAL NETT ITEMS			
1	FRONT BUMPER (AFTER MARKET)(CONSISTENT)(SN)	TORN	2,500.00	2,000.00
1	FRONT RH WHEEL RIM (CONSISTENT)(SN)	CUT	1,280.00	950.00
			3,780.00	2,950.00
	<u>LABOUR</u>			
	PANEL BEATING.		700.00	500.00
	SPRAY PAINTING.		600.00	500.00
	WIRING.		50.00	30.00
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
	TO DISMANTLE FRONT UNDERCARRIAGE.	NOT NECESSARY	380.00	-
			1,880.00	1,110.00
	GRAND TOTAL		10,428.00	6,261.40

RECOMMENDED COST OF LUMP SUM REPAIRS	5,000.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CC4/ASM20003451/Aga3q2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.