

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003453/DPA3Q2

Date: 23/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SJY3534G	Insured Vehicle No :	SHD3384G
Date of Loss: 28/02/2020	Nature of Claim: TP	Claim No: MCT20020583

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY3534G	Engine No:	F16D36069081
Make & Model:	CHEVROLET CRUZE, 1.6 L (A)	Chassis No:	KL1JA6961AK669515
Reg. Date:	24/08/2010 (Man. Year: 2010)	Odometer:	146095 km
Colour:	Blue		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Silverstone 5 mm	Rear Left Side:	Silverstone 5 mm
Front Right Side:	Silverstone 5 mm	Rear Right Side:	Silverstone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,621.52	1,406.72	214.80	13.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	700.00	400.00	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,721.52	2,106.72	614.80	22.59
Approved Total (Overridden) (\$\$)		1,650.00		
Nett Amount (\$\$)	2,721.52	1,650.00	1,071.52	39.37
+ Loss of Use (3.0 x S\$60.00/day) (\$\$)		180.00		
(\$\$)		1,830.00		
Liabile Amount (50.00%) (\$\$)		915.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		922.45		
Global Sum Settlement (\$\$)		920.00		

INSPECTION

Date of Assignment:	02/03/2020	
Date Inspected:	03/03/2020 Inspected At:	Rally Pitstop (HQ)
		176 SIN MING DRIVE #04-17
		SINMING AUTO CARE
		Singapore 787525

Estimated Period of Repair: 2.0 days

Adjuster: BRYAN TANI**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Aug 2020)
Parts:	143	CHEVROLET CRUZE 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY3534G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LEFT DOOR	Dented	879.20 FL	*879.20 FL
2	1		*FRONT LEFT DOOR WEATHER STRIP	Serviceable	134.30 FL	*- FL
3	1		*REAR LEFT DOOR	Dented	879.20 FL	*879.20 FL
4	1		*REAR LEFT DOOR WEATHER STRIP	Serviceable	134.20 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,026.90	1,758.40
- List Item Discount on L Items 20.00/20.00% (S\$)	405.38	351.68
Total Parts (S\$)	1,621.52	1,406.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO DISMANTLE AND CHARGE ALL DAMAGED PARTS	New	500.00	300.00
2	TO PUTTY AND SPRAY PAINT	New	600.00	400.00
Gross Labour Cost (\$\$)			1,100.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >