

RALLY PITSTOP

176 Sin Ming Drive
#04-17 Sin Ming Autocare
Singapore 575721
Tel: 64516985
Email: tar6985@hotmail.com

Date: 02/03/2020

To: Motor Claims Department
India Int'l Insurance

RE: Estimate repair cost of SJY3534G

Your Insured: SHD3384G

Dear Sir/Madam,
Vehicle No: SJY3534G
Make Model: Chervolet / Cruze
Date of accident: 28/02/2020

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Qty	Description	Unit Price	TOTAL
1	Front left door <i>Dentul</i>		879.20
1	Front left door weather stripe <i>SVL</i>		134.30
1	Rear left door <i>Dentul</i>		879.20
1	Rear left door weather stripe <i>SVL</i>		134.20
	Sub-total before discount		2026.90
	Parts percentage discount 20%		405.38
	PARTS TOTAL		1621.52
	LABOUR CHARGES & MISC		
1	Labour to dismantle and change all damaged parts		500.00
2	To putty and spray paint		600.00
	LABOUR TOTAL		1100.00
	LABOUR & PARTS TOTAL		2721.52

Regards,
Terrence Lim

03/03/2020 @ 10:00hrs
N/A Antenna
2/3mm 2 days.
Ryan
LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: