

Woon Meng Motor Pte Ltd (Co.Reg.No:200603678M)

50 Bukit Batok Street 23,, #01-06 Midview Building

Singapore 659578

Tel: 6316 1131 Fax: 6316 7050 Email: woonmeng@singnet.com.sg

INSURER: Lonpac Insurance Bhd (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	Z/19/VC00/104215	Date of Loss:	28/02/2020
Vehicle Reg. No.:	GBG5312G	Driveable?	
Driver Age/Info:	46 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LION CITY DISTRIBUTIONS PTE LTD		
Driver:	GAN TIEM HUAT		
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	25/08/2017
Vehicle Colour:	WHITE		
Engine No:	KDY2738181	Chassis No:	JTFAT35Y10K208721
Odometer:	72558 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		
Description of Accident/Loss	REFER TO ATTACHED SKETCH PLAN.		
Present Location:	WOON MENG MOTOR PTE LTD (BUKIT BATOK)		

COST OF CLAIMS	Amount
Parts	5,086.45
Miscellaneous Items	40.00
Labour	1,660.00
Paintwork Labour	1,100.00
Towing	0.00
Gross Total (\$\$)	7,886.45
+ GST 7.00% (\$\$)	552.05
Nett Amount (\$\$)	8,438.50

This claim is handled by: HENG SEW SOW

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Tan Jiah 97495749/674/8434
4/3/20 @ 1150

Not Authorise

Ex \$ 600

sure/khant.com

tanjiah@khant.com

07 days

Part by Part, Resurvey before paint

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 03 Mar 2020)
Parts:	N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	Woon Meng Motor Pte Ltd/GBG5312G/03/03/2020 15:06
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	de ✓ *250.00 F
2	2		*FRONT BUMPER BRACKET	0.00	RH 0.00	LH-? *210.00 F
3	1		*FRONT BUMPER REFORCEMENT	0.00	0.00	X *130.00 F
4	2		*FRONT FOG LAMP COVER	0.00	RH X 0.00	X *76.00 F
5	1		*FRONT CENTER GRILLE	0.00	0.00	ana ✓ *230.00 F
6	1		*EMBLEM	0.00	0.00	cyt ✓ *40.00 F
7	2		*FRONT HEADLAMP	0.00	RHX 0.00	LH ✓ *600.00 F
8	10		*FRONT CENTER GRILLE CLIPS	0.00	0.00	ana ✓ *25.00 F
9	2		*FRONT HEADLAMP LOWER SEAL	0.00	RHX 0.00	LH ✓ *36.00 F
10	1		*FRONT PANEL	0.00	0.00	bt ✓ *300.00 F
11	1		*DYNA	0.00	0.00	ana ✓ *35.00 F
12	2		*FRONT CORNER PANEL	0.00	RHX 0.00	LH ✓ *200.00 F
13	1		*FRONT SIDE MIRROR STAY N/S	0.00	0.00	bt ✓ *160.00 F
14	1		*FRONT WIPER PANEL	0.00	0.00	bt ✓ *160.00 F
15	2		*FRONT NOZZLE	0.00	RH X 0.00	LH-mis *50.00 F
16	2		*FRONT WIPER BLADE	0.00	RHX 0.00	LH ✓ *36.00 F
17	2		*FRONT WIPER ARM	0.00	RHX 0.00	LH ✓ *120.00 F
18	1		*FRONT WIPER LINK	0.00	0.00	? *140.00 F
19	1		*FRONT WIPER MOTOR	0.00	0.00	? *300.00 F
20	1		*FRONT WINDSCREEN GLASS	0.00	0.00	ana ✓ *500.00 F
21	1		*FRONT WINDSCREEN RUBBER	0.00	0.00	ana ✓ *90.00 F
22	1		*FRONT DOOR LH	0.00	0.00	Rx *550.00 F
23	1		*FRONT DOOR LOCK N/S	0.00	0.00	? *105.00 F
24	2		*FRONT DOOR HINGE	0.00	0.00	? *80.00 F

F=Franchise part.

Sub Total (\$\$)

4,423.00

+ Margin on L,N Items 15.00% (\$\$)

663.45

Total Parts (\$\$)

5,086.45

Woon Meng Motor Pte Ltd/GBG5312G/03/03/2020 15:06. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Auto Insured by Repairer

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	DOOR STICKER	net 25.00
2	1	FRONT ERP BRACKET	net 15.00

Sub Total (\$\$)

40.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Paintwork Labour

1	TO PUTTY & SPRAY PAINTING	New 800	1,100.00
---	---------------------------	---------	----------

Labour Items

2	TO REMOVE, REPLACE, REPAIR & INSTALL FRONT DAMAGED PARTS.	New 800	1,000.00
3	TO R & R FRONT WINDSCREEN GLASS	New ✓	120.00
4	TO R & R WIRING	New 30	60.00
5	TO REMOVE & INSTALL DOOR MECHANISM & CHECK FOR FUNCTION	New ? 60	150.00
6	TO R & R FRONT DASHBOARD	New plus ?	180.00
7	TO R & R AIR CON SYSTEM. TO REFILL & TOP UP AIR CON GAS.	New ?	150.00

Gross Labour Cost (\$\$)

2,760.00

Woon Meng Motor Pte Ltd/GBG5312G/03/03/2020 15:06. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >