

DING AUTOMOTIVE PTE LTD

Blk 10, #01-20

Sin Ming Industrial Est. Sec C

Singapore 575645

Tel: 6452 1208

Fax: 6452 0614

Vehicle:	SHB2275E
Model:	HYUNDAI I40
Chassis:	KMHLB41UMGU092609

PARTS SUPPLEMENTARY & QUOTATION FORM

	LABOUR	PRICE	SURVEYOR MARKING
1	RESPRAY REAR FENDER RH	\$ 200.00	/
2	RESPRAY REAR END PANEL	\$ 200.00	X Repaired
	TOTAL:	\$ 400.00	

Stew

5/3/20, 6.45pm