

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Mar 2020 Edit Reg		02 Mar 2020 00:00 Edit Adj Rpt	S\$2,120.20 Edit Estimates	S\$2,120.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: Leng Chee Keong , Co. Reg. No.: -									
Main Claimant: SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K									
Vehicle Reg. No.: SHB5185L		Date of Loss: 28/02/2020 14:00 - :59 [27 Months and 27 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4885627013SG		Policy/Cover Note No.: 2100456217 (Comprehensive)							
Vehicle Reg. No. (Insured): SKK8118D		Policy No. (Claimant):							
		Excess:							
Repairer: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 12/03/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (14/05/2020): Alert - Adj Mandate Approved (S\$2925.60) - SHB5185L - Claim Handler: MdNoor, Nor... - AIG_SG (04/03/2020): NO TP GIA REPORT									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHB5185L (4885627013SG)**
[SKK8118D]

TP

SMRT TAXIS PTE LTD

Feb 28 2020 2:00PM

[Leng Chee Keong]

SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio View View in Browser ▼				
Video				
		1 per page ▼	☒	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	04/03/20 12:38	Video - Accident	Load AVI	
2	04/03/20 12:38	Video - Accident	Load AVI	
3	04/03/20 12:39	Video - Accident	Load AVI	
4	04/03/20 12:39	Video - Accident	Load AVI	
5	04/03/20 12:39	Video - Accident	Load AVI	
Letters/Correspondences				
		1 per page ▼	☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Assessment Reports				
		1 per page ▼	☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/05/20 00:14	Adjuster Immediate Advice	Load HTM	
Photos/Images				
		3 per page ▼	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/03/20 11:42	Chassis Number	Load JPG	☒
2	17/03/20 11:42	General View	Load JPG	☒
3	17/03/20 11:42	General View	Load JPG	☒
4	17/03/20 11:42	General View	Load JPG	☒
5	17/03/20 11:42	General View	Load JPG	☒
6	17/03/20 11:42	General View	Load JPG	☒
7	17/03/20 11:42	General View	Load JPG	☒
8	17/03/20 11:42	General View	Load JPG	☒
9	17/03/20 11:42	General View	Load JPG	☒
10	17/03/20 11:42	General View	Load JPG	☒
11	17/03/20 11:42	General View	Load JPG	☒
12	17/03/20 11:42	General View	Load JPG	☒
13	17/03/20 11:42	General View	Load JPG	☒
14	17/03/20 11:42	General View	Load JPG	☒
15	17/03/20 11:42	General View	Load JPG	☒
16	17/03/20 11:42	General View	Load JPG	☒
17	17/03/20 11:43	Reinspection Photo	Load JPG	☒
18	17/03/20 11:43	Reinspection Photo	Load JPG	☒
19	17/03/20 11:43	Reinspection Photo	Load JPG	☒
20	17/03/20 11:43	Reinspection Photo	Load JPG	☒
21	17/03/20 11:43	Reinspection Photo	Load JPG	☒
22	17/03/20 11:44	Replacement Part Photo	Load JPG	☒
23	17/03/20 11:44	Replacement Part Photo	Load JPG	☒
24	17/03/20 11:44	Replacement Part Photo	Load JPG	☒
25	17/03/20 11:44	Replacement Part Photo	Load JPG	☒
Documentation				
		1 per page ▼	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print

Video				1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	23/03/20 15:10	TP ESTIMATE-MARKED		Load PDF	
2	23/03/20 15:10	TP GIA REPORT		Load PDF	
3	23/03/20 18:17	EMAIL TO OI		Load PDF	
4	05/05/20 23:52	MARKED ESTIMATE - FINALISED		Load PDF	
5	05/05/20 23:54	LOD		Load PDF	
6	05/05/20 23:56	FINAL REPAIR BILL, ATA, LTA SEARCH, RENTAL SUPP DOCS		Load PDF	
7	03/07/20 10:14	Authorisation to Act		Load PDF	
8	03/07/20 10:14	LTA SEARCH		Load PDF	
9	03/07/20 10:14	Release Voucher		Load PDF	
10	03/07/20 10:14	RENTAL MILEAGE		Load PDF	
11	03/07/20 10:14	RENTAL RECEIPT		Load PDF	
12	03/07/20 10:14	WORKSHOP INVOICE		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	04/03/20 12:37	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKK8118D (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHB5185L (TP veh)		
Date of Accident:	28/02/2020		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:\$	8,273.80	
Final Repair Cost	:\$	2,920.00	
Loss of Use	:\$	5.00 days at \$50.00 per day	
Rental (if any)	:\$	5 days	
LTA / GIA Search Fee	:\$		
Others:	:\$		
	:\$		
Final Settlement Sum (GLOBAL SUM)	:\$	2,920.00	
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 0 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:\$	2,920.00
2)		:\$	
3)		:\$	
4)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

03 Jul
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20003511/T1KS3S2**Date:** 03/07/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100456217
Claimant Vehicle No :	SHB5185L	Insured Vehicle No :	SKK8118D
Date of Loss:	28/02/2020	Nature of Claim:	TP
		Claim No:	4885627013SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB5185L		
Make & Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Engine No:	2ZRS099592
Reg. Date:	01/11/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FUX03573209
Colour:	Maroon	Odometer:	0 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,948.80	1,340.20	4,608.60	77.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,325.00	780.00	1,545.00	66.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	8,273.80	2,120.20	6,153.60	74.37
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$109.68/day) (S\$)		548.40		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		2,925.60		
Global Sum Settlement (S\$)		2,920.00		

INSPECTION

Date of Assignment:	02/03/2020	
Date Inspected:	02/03/2020	Inspected At: SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Khanchna Pothuraj*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) 10pcs	Necessary	15.00 F	*11.25 F
2	1	*GUARD, RR BUMPER, LOWER (DISC 25%)	Deformed	558.30 F	*418.73 F
3	1	*EMBLEM SUB-ASSY REAR (DISC 25%)	Necessary	46.30 F	*34.73 F
4	1	*NAME PLATE (HYBRID), LUGGAGE COMPARTMENT (DISC 25%)	Necessary	52.30 F	*39.23 F
5	1	*NAME PLATE (PRIUS), LUGGAGE COMPARTMENT (DISC 25%)	Necessary	52.30 F	*39.23 F
6	1	*COVER, RR BUMPER ASSY (DISC 25%)	Deformed	423.90 F	*317.93 F
7	1	*REAR BUMPER REINFORCEMENT (DISC 25%)	Necessary	318.80 F	*239.10 F
8	1	*SENSOR REVERSE (SN)	Not Working	180.00 F	*180.00 F
9	1	*PIXEL STICKER (SN)	Necessary	60.00 F	*60.00 F
10	1	*SEAL, RR BUMPER, RH	Not Necessary	85.20 F	*- F
11	1	*SEAL, RR BUMPER, LH	Not Necessary	85.20 F	*- F
12	1	*FILLER, RR BUMPER, RH	Not Necessary	119.90 F	*- F
13	1	*FILLER, RR BUMPER, LH	Not Necessary	119.90 F	*- F
14	1	*COVER, GUARD RR BUMPER LOWER	Not Necessary	14.80 F	*- F
15	1	*SPOILER SUB-ASSY, REAR	Not Necessary	1,322.10 F	*- F
16	1	*LENS & BODY ASSY, RR BUMPER, RH	Not Necessary	486.80 F	*- F
17	1	*LENS & BODY ASSY, RR BUMPER, LH	Not Necessary	486.80 F	*- F
18	1	*ANTENNA, ELECTRICAL KEY	Not Necessary	60.30 F	*- F
19	1	*REAR BUMPER REINFORCEMENT	Not Necessary	318.80 F	*- F
20	1	*PAD, RR BUMPER, RH & LH, 1	Not Necessary	3.80 F	*- F
21	1	*PAD, RR BUMPER, RH & LH, 2	Not Necessary	3.80 F	*- F
22	1	*PAD, RR BUMPER, RH & LH, 3	Not Necessary	3.80 F	*- F
23	1	*SEAL, RR BUMPER ARM, RH & LH	Not Necessary	11.00 F	*- F
24	1	*STOPPER, RR BUMPER, RH & LH	Not Necessary	4.30 F	*- F
25	1	*RETAINER, RR BUMPER, RH	Not Necessary	112.70 F	*- F
26	1	*RETAINER, RR BUMPER LH	Not Necessary	111.50 F	*- F
27	1	*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	Repair	891.20 F	*- F
F=Franchise part.					
Total Parts (\$\$)				5,948.80	1,340.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODYWORK.	New	507.00	300.00
2	SPRAY PAINT.	New	1,458.00	400.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	30.00
4	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	30.00
5	TO REPLACE SUNDRY PARTS.	New	100.00	20.00
6	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (\$\$)			2,325.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >