



Case Details

Case Reference Number : TAX/02/20/2093
Type of Repair : Accident Repair
Vehicle Registration Number : SHB5185L

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-10687-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
Accident Date and Time : 28/02/2020 06:35 AM
Vehicle Age(In Months) : 27

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			SEAL, RR BUMPER , RH	1	85.20	85.20	25.00	63.90	Replace	0	0.00	Check	?
One Time Key In	Main			SEAL, RR BUMPER , LH	1	85.20	85.20	25.00	63.90	Replace	0	0.00	Check	?
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	new
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	out
One Time Key In	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0.00	Check	?
One Time Key In	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0.00	Check	?
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0.00	Check	?
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	891.20	891.20	25.00	668.40	Replace	1	0.00	Repair	Ry
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72	Replace	new
One Time Key In	Main			NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	new
Total Spare Part Cost									4,437.57	Surveyor Total			1,101.05	
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)			0	
Final Spare Part Cost									4,437.57	Final Sur Total			1,101.05	

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT DOOR	1	52.30	52.30	25.00	39.22	Replace	1	39.22	Replace	ag
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	0	0.00	Not Give	X
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	0	0.00	Not Give	X
One Time Key In	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	0	0.00	Not Give	X
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0.00	Check	?
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	ah
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	ah
One Time Key In	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	de
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	0	0.00	Check	?
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 1	1	3.80	3.80	25.00	2.85	Replace	0	0.00	Check	?
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 2	1	3.80	3.80	25.00	2.85	Replace	0	0.00	Check	?
One Time Key In	Main			PAD, RR BUMPER, RH & LH , 3	1	3.80	3.80	25.00	2.85	Replace	0	0.00	Check	?
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	1	11.00	11.00	25.00	8.25	Replace	0	0.00	Check	?
One Time Key In	Main			STOPPER, RR BUMPER, RH & LH	1	4.30	4.30	25.00	3.22	Replace	0	0.00	Check	?
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0.00	Not Give	X
One Time Key In	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0.00	Not Give	X
Total Spare Part Cost									4,437.57	Surveyor Total				1,101.05
Lump Sum Discount (%)									0.00	Lump Sum Dis (%)				0
Final Spare Part Cost									4,437.57	Final Sur Total				1,101.05

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	507.00	300.00	
Total:			507.00	300.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200.00	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0.00	
3	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00	
4	Main	TO RESPRAY REAR SPOILER	180.00	0.00	
5	Main	TO RESPRAY FILLER RR BUMPER LH	180.00	0.00	
6	Main	TO RESPRAY FILLER RR BUMPER RH	180.00	0.00	
Total:			1,278.00	300.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00	
3	Main	TO REPLACE SUNDRY PARTS	100.00	20.00	
4	Main	TO WASH AND VACUUM	60.00	0.00	
Total:			360.00	80.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	4,437.57	1,101.05
Total Labour Cost	507.00	300.00
Total Spray Painting	1,278.00	300.00
Other	360.00	80.00
Overall Total	6,582.57	1,781.05
Lump Sum Repair Option		

Estimator Assessment(\$)

Lump Sum Total

0.00

Surveyor Approved Amount

No of Repair Days*

5

Remarks

-

Surveyor Name

Signature



Survey Date

02/03/2020

Surveyor Assessment(\$)

1,781.05

1,781.05

3

Resurvey before paint

Taufikh



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Taufikh 97495749
'wp'

2/3/20.

03 days

Resurvey before paint
swc.khant.com