

ASS. REC. BY:

Surveyor: Adnan

REF:

CE/AGI20003518 Ay 2021

Special Instruction:

ASSIGNMENT (Office)

From (Person): Ivy Rahlla

of AGI

Date/Time: 3/3/2020

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMF547D

Insured: 2685671Y

at Workshop n/s Vision Autowork

Tel: 63416789

of 8 Yaki Bukit Ave 4 #08-09

Policy No:

Claim No: C10005786

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 2.3.2020

CA / REV / REP. / REV 24 HRS ^{1up}

H.O.D. Endorsement:

Date/Time: 3/3

Person Contacted:

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate (✓)
	<u>SMF547D - NBA</u>	<u>AGI20003470</u>
	<u>2685671Y - X</u>	<u>DOA: 2/3/2020</u>
<u>1/4/20</u>	<u>L/S \$5800/-</u>	<u>(Red \$9039-70, 60%)</u>

ASS. REC. BY:

REF: AGI

ASSIGNMENT

From: _____ Date: 5.3.2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMF- 547D

at Workshop m/s Vision AutoWore

of 8 Kaki Bukit Ave 4 #108-09 Premier

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS *np*

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMFS47D Yr Regn: 2018 1 Oct.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Kia Cerato c.c 1591

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 39705 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAF3416MK5019275

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Continental

Front R/Bal. 06 mm Rear R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 05/03/20

Survey held at Vision

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Budget Direct.

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____
Date/Time, File Return to? 1/4/20 Typist

Rep. Format: Lump Sum / I.B.I. / \$5800f

Days Of Repair: 6 Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)

Survey Fee:	350
Transportation:	
\$ + RS. SI	
Photos	
Others	
TOTAL	350

Nivitha (LKK Auto)

From: Claims <claims@budgetdirect.com.sg>
Sent: Tuesday, 3 March 2020 3:47 PM
To: Nivitha (LKK Auto)
Cc: Julie Mangubat; SUR
Subject: Fw: SMF547D (Pre-inspection) / Your vehicle : SGS5671Y || C10005786
Attachments: TP Report.pdf

Hi Team,

We would like to arrange TP PRS for SMF547D.

Workshop information:

8 Kaki Bukit Avenue 4,
#08-09, Premier @ Kaki Bukit,
Singapore 415875
Tel: 6341 6789
Fax: 6341 6778

Please confirm. Thank you.

Regards,

Ivy Ratilla
Executive, Claims Admin

T +65 6540 2185
F +65 6725 0853
E ivvy.r@budgetdirect.com.sg



Customer Care +65 6221 2111
Claims +65 6221 2199
Claims (Int.) +65 6540 2199

190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
Singapore
239924
budgetdirect.com.sg

auto  general

Veh Out

From: Vision Autowork <visionautowork@gmail.com>
Sent: Tuesday, 3 March 2020 14:05
To: Claims <claims@budgetdirect.com.sg>; Justin Wong <justin.wong@budgetdirect.com.sg>; Albert Hong

<aibert.hong@budgetdirect.com.sg>; Ivy Ratilla <ivy.r@budgetdirect.com.sg>
Subject: SMF547D (Pre-inspection) / Your vehicle : SGS5671Y

Dear All,

Please refer attach file and arrange for pre-inspection.

To expedite the pre-inspection, please arrange **LKK AUTO CONSULTANT PTE LTD** to survey the above vehicle

**** PLEASE ADVISE LIABILITY ****

Thank You

Yours faithfully,

Michelle
Hp: 9856 4815

8 Kaki Bukit Avenue 4,
#08-09, Premier @ Kaki Bukit,
Singapore 415875
Tel: 6341 6789
Fax: 6341 6778

This email is sent by Auto & General Insurance (Singapore) Pte. Limited, Auto & General (SEA) Services Pte. Limited, Easy Compare (Thailand) Co., Ltd or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised. If you are not the intended addressee, please immediately notify the sender and then delete the email. Auto & General does not warrant that this email is error or virus free.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/03/2020 11:41
Date Of Accident	02/03/2020 18:20
Exact Location Of Accident	T-JUNCTION OF PASIR RIS DRIVE 1 AND LOYANG AVENUE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF547D
Insured/Policyholder	
Name Of Registered Owner	YVONNE LAU JIE LIN
NRIC No	SXXXX342B
Email Address	JOELTANJX@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90180412
Alternative Phone No	OTHERS-97862438

Vehicle Particulars

Manufacturer	KIA
Model	CERATO FORTE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800125362
Cover Note Number	

Driver

Name of Driver	TAN JIAXIANG, JOEL
NRIC No	SXXXX698Z
Date Of Birth	03/02/1989
Occupation	INDOOR
Date Of Driving Pass	06/03/2008
Driving Experience	11 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90180412
Fax Number	
Contact Number	OTHERS-97862438
EMail Address	JOELTANJX@GMAIL.COM

Address	BLK 446 TAMPINES STREET 42 #08-40
Postcode	520446
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH AND ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH OWNER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGS5671Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

ATTACHMENT

On 02.03.2020 at about 18:20 hours at T-Junction of Pasir Ris Drive 1 and Loyang Avenue. I was travelling straight on lane 2 (along Pasir Ris Drive 1 turning right to Loyang Avenue) and the traffic light was green, when my front vehicle slowed down and stopped hence I follow suit.

Suddenly I heard a loud bang from behind. When I alighted I realised vehicle (B) had collided onto rear portion of my vehicle (A).

Vehicle (A): SMF 547D

Vehicle (B): SGS 5671Y

Car

*car 03/03/2020
field horizon*

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)
 8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
 Singapore 415875
 Tel : 6341 6789 Fax: 6341 6778
 E-mail:visionautowork@gmail.com

DATE : 05.03.20

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMF547D**
 MODEL : **KIA CERATO** *Xonne.*
 DATE OF ACCIDENT : 02.03.20
 TIME OF ACCIDENT : 18:20HRS *KNAF3416MK5019275*

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BOOT LID <i>Dented</i>	1	\$ 1,297.00	\$ 1,297.00
2	BOOT LID CENTER LAMP <i>new</i>	1	\$ 186.00	\$ 186.00
3	BOOT LID LAMP <i>new</i>	2	\$ 608.00	\$ 1,216.00
4	BOOT LID LOGO <i>2 pc</i>	1	\$ 52.00	\$ 52.00
5	BOOT LID EMBLEM 'CERATO' <i>1 pc</i>	1	\$ 43.00	\$ 43.00
6	BOOT LID HINGE <i>new</i>	2	\$ 66.00	\$ 132.00
7	BOOT LID INSULATOR <i>Not New</i>	1	\$ 202.00	\$ 202.00
8	BOOT LID WEATHER STRIP <i>cut</i>	1	\$ 110.00	\$ 110.00
9	BOOT LID DETECTOR <i>could</i>	1	\$ 196.00	\$ 196.00
10	BOOT LID LOCK <i>Damaged</i>	1	\$ 117.00	\$ 117.00
11	BOOT LID CATCHER <i>new</i>	1	\$ 38.00	\$ 38.00
12	TAIL LAMP <i>could</i>	2	\$ 675.00	\$ 1,350.00
13	TAIL LAMP PANEL <i>Not New</i>	2	\$ 296.00	\$ 592.00
14	REAR BUMPER <i>Dented</i>	1	\$ 698.00	\$ 698.00
15	REAR BUMPER LOWER <i>Dented</i>	1	\$ 264.00	\$ 264.00
16	REAR BUMPER LAMP <i>could</i>	2	\$ 181.00	\$ 362.00
17	REAR BUMPER LAMP COVER GARNISH <i>2 pc</i>	2	\$ 98.00	\$ 196.00
18	REAR BUMPER LAMP WIREHARNES LH <i>1 pc</i>	1	\$ 367.00	\$ 367.00
19	REAR BUMPER SIDE INNER COVER GARNISH LH <i>2 pc</i>	2	\$ 65.00	\$ 130.00
20	REAR BUMPER BRACKET <i>new</i>	5	\$ 35.00	\$ 175.00
21	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 27.00	\$ 54.00
22	REAR BUMPER REINFORCEMENT <i>could</i>	1	\$ 318.00	\$ 318.00
23	REAR BUMPER REINFORCEMENT BRACKET <i>new</i>	2	\$ 65.00	\$ 130.00
24	REAR FENDER INNER COWLING <i>2 pc</i>	2	\$ 75.00	\$ 150.00
25	REAR FENDER INNER TRIM <i>1 pc</i>	2	\$ 200.00	\$ 400.00
26	REAR END PANEL <i>Dented</i>	1	\$ 375.00	\$ 375.00
27	REAR END PANEL TOP GARNISH <i>could</i>	1	\$ 84.00	\$ 84.00
28	REAR FLOOR PANEL TOP BOARD <i>returned</i>	1	\$ 210.00	\$ 210.00

TO : BUDGET DIRECT MOTOR CLAIMS DEPTS
 VEHICLE NO : SMF547D
 MODEL : KIA CERATO
 DATE OF ACCIDENT : 02.03.20
 TIME OF ACCIDENT : 18:20HRS

29	REVERSE CAMERA	<i>Not New</i>	1	\$ 689.00	\$ 689.00	+
----	----------------	----------------	---	-----------	-----------	---

5530
4977.

TOTAL PRICE	\$ 10,133.00
LESS 10%	\$ 1,013.30
SUB TOTAL PRICE	\$ 9,119.70

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Not New</i>	1	\$ 50.00	\$ 50.00	+
2	REAR BUMPER CLIPS (SET) <i>New</i>	1	\$ 80.00	\$ 80.00	30
3	REAR BUMPER SIDE INNER COVER GARNISH CLIP (SET) <i>Not New</i>	1	\$ 60.00	\$ 60.00	x
4	BOOT LID SEALANT <i>New</i>	1	\$ 80.00	\$ 80.00	+
5	BOOT LID INSULATOR CLIP (SET) <i>New</i>	1	\$ 50.00	\$ 50.00	+
6	BOOT LID EMBLEM 'C&C' <i>New</i>	1	\$ 120.00	\$ 120.00	45
7	TAIL LAMP CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00	20
8	TAIL LAMP PANEL SEALANT <i>Not New</i>	2	\$ 60.00	\$ 120.00	+
9	REAR FENDER INNER COWLING CLIP (SET) <i>Not New</i>	1	\$ 80.00	\$ 80.00	+
10	REAR FENDER INNER TRIM CLIP (SET) <i>Not New</i>	1	\$ 80.00	\$ 80.00	+
11	REAR END PANEL INSULATION SEAL <i>New</i>	1	\$ 150.00	\$ 150.00	60.
12	REAR END PANEL TOP GARNISH CLIP (SET) <i>New</i>	1	\$ 40.00	\$ 40.00	10.
13	REVERSE SENSOR (SET) <i>Damaged</i>	1	\$ 220.00	\$ 220.00	200.

365 TOTAL \$ 1,170.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS	\$ 1,600.00	<i>800</i>
2	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS	\$ 1,600.00	<i>800</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINNING TO FACILITATE REPAIR	\$ 350.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>50</i>
8	TRANSFER BOOTLID MECHANISM	\$ 80.00	<i>60</i>
9	CONDUCT WATER LEAKAGE TEST	\$ 150.00	<i>x</i>

TO : **BUDGET DIRECT** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMF547D**
 MODEL : **KIA CERATO**
 DATE OF ACCIDENT : 02.03.20
 TIME OF ACCIDENT : 18:20HRS

10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$	180.00	X
----	--	----	--------	---

TOTAL \$ **4,550.00** 1910

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,289.70
 TOTAL LABOUR COST : \$ 4,550.00
 TOTAL REPAIR COST : \$ 14,839.70

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Adrian Lj
h/s 05/03/20
ob pays.

total: 7252
h/s: S.8t

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS/AGI20003518/Ayf3e2	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 03-04-2020	
		Code : AGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGS 5671Y	Veh. Inspected	SMF 547D
Policy No.		Coverage (\$)	0.00
Claim No.	C10005786	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	03/03/2020
2. Vehicle Particulars & Condition			
Make & Model	KIA CERATO	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	KNAF3416MK5019275	Colour	BLUE
Odometer	39705	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	02/03/2020	Inspection Date	05/03/2020
Survey held at	VISION AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4, #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMF 547D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	DENTED	1,297.00	1,297.00
1	BOOT LID CENTER LAMP	NOT NECESSARY	186.00	-
2	BOOT LID LAMP @\$608.00	NOT NECESSARY	1,216.00	-
1	BOOT LID LOGO	NECESSARY	52.00	52.00
1	BOOT LID EMBLEM 'CERATO'	NECESSARY	43.00	43.00
2	BOOT LID HINGE @\$66.00	NOT NECESSARY	132.00	-
1	BOOT LID INSULATOR	NOT NECESSARY	202.00	-
1	BOOT LID WEATHER STRIP	CUT	110.00	110.00
1	BOOT LID REFLECTOR	CRACKED	196.00	196.00
1	BOOT LID LOCK	DAMAGED	117.00	117.00
1	BOOT LID CATCHER	NOT NECESSARY	38.00	-
2	TAIL LAMP @\$675.00	CRACKED	1,350.00	1,350.00
2	TAIL LAMP PANEL @\$296.00	NOT NECESSARY	592.00	-
1	REAR BUMPER	DEFORMED	698.00	698.00
1	REAR BUMPER LOWER	DEFORMED	264.00	264.00
2	REAR BUMPER LAMP @\$181.00	CRACKED	362.00	362.00
2	REAR BUMPER LAMP COVER GARNISH @\$98.00	NOT NECESSARY	196.00	-
1	REAR BUMPER LAMP WIREHARNES LH	NOT NECESSARY	367.00	-
2	REAR BUMPER SIDE INNER COVER GARNISH LH @\$65.00	NOT NECESSARY	130.00	-
5	REAR BUMPER BRACKET @\$35.00	NOT NECESSARY	175.00	-
2	REAR BUMPER SIDE RETAINER @\$27.00	NECESSARY	54.00	54.00
1	REAR BUMPER REINFORCEMENT	CRACKED	318.00	318.00
2	REAR BUMPER REINFORCEMENT BRACKET @\$65.00	NOT NECESSARY	130.00	-
2	REAR FENDER INNER COWLING @\$75.00	NOT NECESSARY	150.00	-
2	REAR FENDER INNER TRIM @\$200.00	NOT NECESSARY	400.00	-
1	REAR END PANEL	DENTED	375.00	375.00
1	REAR END PANEL TOP GARNISH	CRACKED	84.00	84.00
1	REAR FLOOR PANEL TOP BOARD	DEFORMED	210.00	210.00
1	REVERSE CAMERA	NOT NECESSARY	689.00	-

Report Ref No. CS/AGI20003518/Ayf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 10% DISCOUNT		-1,013.30	-553.00
			9,119.70	4,977.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
1	SET REAR BUMPER SIDE INNER COVER GARNISH CLIP (SN)	NOT NECESSARY	60.00	-
1	BOOT LID SEALANT (SN)	NOT NECESSARY	80.00	-
1	SET BOOT LID INSULATOR CLIP (SN)	NOT NECESSARY	50.00	-
1	BOOT LID EMBLEM 'C&C' (SN)	NECESSARY	120.00	45.00
1	SET TAIL LAMP CLIP (SN)	NECESSARY	40.00	20.00
2	TAIL LAMP PANEL SEALANT @\$60.00 (SN)	NOT NECESSARY	120.00	-
1	SET REAR FENDER INNER COWLING CLIP (SN)	NOT NECESSARY	80.00	-
1	SET REAR FENDER INNER TRIM CLIP (SN)	NOT NECESSARY	80.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NECESSARY	150.00	60.00
1	SET REAR END PANEL TOP GARNISH CLIP (SN)	NECESSARY	40.00	10.00
1	SET REVERSE SENSOR (SN)	DAMAGED	220.00	200.00
			1,170.00	365.00
	<u>LABOUR</u>			
	PANEL BEATING, WELDING GRAZING, CUT, JOIN, STRAIGHTEN ALL AFFECTED PARTS.		1,600.00	800.00
	TO PUTTY, POLISH, SPRAY PAINT, WAX ALL AFFECTED PANELS.		1,600.00	800.00
	TUFF COAT.		250.00	60.00
	WIRING CHECK.		180.00	30.00
	REMOVE AND REFIX CUSHION SEAT / UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR.		350.00	60.00
	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING.		80.00	50.00
	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.		80.00	50.00
	TRANSFER BOOTLID MECHANISM.		80.00	60.00
	CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-

Report Ref No. CS/AGI20003518/Ayf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	NOT NECESSARY	180.00	-
			4,550.00	1,910.00
GRAND TOTAL			14,839.70	7,252.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,800.00

Report Ref No. CS/AGI20003518/Ayf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.