

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003526/T1ES3Q2

Date: 15/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100452498

Claimant
Vehicle No : SJZ5823D **Insured Vehicle No :** SKZ9953Z

Date of Loss: 26/02/2020 Nature of Claim: TP Claim No: 8015276037SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ5823D	Engine No:	CAL077269
Make & Model:	AUDI Q5, 3.2 FSI Quattro (A)	Chassis No:	WAUZZZ8R6BA037522
Reg. Date:	08/12/2010 (Man. Year: 2010)	Odometer:	78758 km
Colour:	Black		
Engine Capacity:	3197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/45 R20	Rear Tyre Size:	255/45 R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,152.00	4,313.00	14,839.00	77.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,320.00	1,230.00	3,090.00	71.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	23,472.00	5,543.00	17,929.00	76.38
Approved Total (Overridden) (\$\$)		4,400.00		
(\$\$)	23,472.00	4,400.00	19,072.00	81.25
+ GST 7.00/7.00% (\$\$)	1,643.04	308.00	1,335.04	81.25
Nett Amount (\$\$)	25,115.04	4,708.00	20,407.04	81.25
+ Loss of Use (4.0 x \$120.00/day) (\$\$)		480.00		
(\$\$)		5,188.00		
Liabile Amount (50.00%) (\$\$)		2,594.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		2,601.45		
Global Sum Settlement (\$\$)		2,600.00		

INSPECTION

Date of Assignment: 03/03/2020

Date Inspected: 09/03/2020 Inspected At:

Maximus Racing Pte Ltd (HQ)
7 Soon Lee Street, #05-05 MR

Performance Centre
Singapore 627608

Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*AUDI GENUINE FRONT BUMPER	Deformed	1,800.00 FL	*1,800.00 FL
2	1		*AUDI GENUINE BUMPER SPOILER	Not Necessary	350.00 FL	*- FL
3	1		*AUDI GENUINE GRILLE	Not Necessary	950.00 FL	*- FL
4	1		*AUDI GENUINE RIGHT FOG LAMP	Not Necessary	150.00 FL	*- FL
5	1		*AUDI GENUINE RIGHT FENDER	Bent	500.00 FL	*500.00 FL
6	1		*AUDI GENUINE RIGHT SCREW & CLIPS	Necessary	50.00 FL	*50.00 FL
7	1		*AUDI GENUINE MOUNT KIT	Not Necessary	50.00 FL	*- FL
8	1		*AUDI GENUINE BRACKET	Not Necessary	50.00 FL	*- FL
9	1		*AUDI GENUINE BRACKET	Not Necessary	50.00 FL	*- FL
10	1		*AUDI GENUINE SUPPORT	Not Necessary	60.00 FL	*- FL
11	1		*AUDI GENUINE END PLATE	Not Necessary	70.00 FL	*- FL
12	1		*AUDI GENUINE SEAL	Not Necessary	50.00 FL	*- FL
13	1		*AUDI GENUINE PLATE	Not Necessary	120.00 FL	*- FL
14	1		*AUDI GENUINE FRONT RIGHT COVER	Missing	150.00 FL	*150.00 FL
15	1		*AUDI GENUINE HEADLAMP	Cracked	1,800.00 FL	*1,800.00 FL
16	1		*AUDI GENUINE GAS BULB	Not Necessary	350.00 FL	*- FL
17	1		*AUDI GENUINE HID HEADLIGHT BALLAST	Not Necessary	850.00 FL	*- FL
18	1		*AUDI GENUINE CONTROL UNIT	Not Necessary	500.00 FL	*- FL
19	1		*AUDI GENUINE POWER MOD	Not Necessary	1,000.00 FL	*- FL
20	1		*AUDI GENUINE RETAINING PLATE	Not Necessary	50.00 FL	*- FL
21	1		*AUDI GENUINE RETAINING PLATE	Not Necessary	50.00 FL	*- FL
22	1		*AUDI GENUINE RANGE CONTROL BRACKET	Not Necessary	80.00 FL	*- FL
23	1		*AUDI GENUINE HEADLAMP BRACKET	Not Necessary	80.00 FL	*- FL
24	1		*AUDI GENUINE HEADLAMP REPAIR KIT	Not Necessary	80.00 FL	*- FL
25	1		*AUDI GENUINE MOUNTING FOR HEADLAMP	Not Necessary	80.00 FL	*- FL
26	1		*AUDI GENUINE BOLT	Not Necessary	10.00 FL	*- FL
27	1		*AUDI GENUINE END PLATE PLATE	Not Necessary	500.00 FL	*- FL
28	1		*AUDI GENUINE REINFORCEMENT BAR	Not Necessary	1,900.00 FL	*- FL
29	1		*AUDI GENUINE HELPER REINFORCE RIGHT REINFORCEMENT	Not Necessary	100.00 FL	*- FL
30	1		*AUDI GENUINE CENTER UPPER REINFORCE REINFORCEMENT	Not Necessary	180.00 FL	*- FL
31	1		*AUDI GENUINE CARRIER FOR RADIATOR		550.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*AUDI GENUINE PLATE	Not Necessary	50.00 FL	*- FL
33	1		*AUDI GENUINE RIGHT CROSS SUPPORT	Not Necessary	50.00 FL	*- FL
34	1		*AUDI GENUINE RADAR SYSTEM	Not Necessary	5,800.00 FL	*- FL
35	1		*AUDI GENUINE BRACKET WITH RADAR	Not Necessary	150.00 FL	*- FL
36	1		*AUDI GENUINE COVER FRAME FOR RADAR	Not Necessary	50.00 FL	*- FL
37	1		*AUDI GENUINE FOG LAMP	Not Necessary	150.00 FL	*- FL
38	1		*AUDI GENUINE TRIM FOR WHEEL ARCH	Not Necessary	80.00 FL	*- FL
39	1		*AUDI GENUINE WHEEL PROTECTOR COVER	Deformed	180.00 FL	*180.00 FL
40	1		*AUDI GENUINE WHEEL PROTECTOR COVER CLIPS	Necessary	60.00 FL	*60.00 FL
41	2		*AUDI GENUINE PARKING SENSOR	Not Necessary	300.00 FL	*- FL
42	1		*AUDI GENUINE FRONT RADIATOR COVER	Not Necessary	100.00 FL	*- FL
43	1		*AUDI GENUINE IMPACT BAR	Not Necessary	450.00 FL	*- FL
44	1		*AUDI GENUINE MOUNTING CLIPS	Not Necessary	140.00 FL	*- FL
45	1		*AUDI GENUINE FRONT BUMPER GRILLE LOWER COVER	Not Necessary	40.00 FL	*- FL
F=Franchise part. L=ListItemDisc.						
				Sub Total (\$\$)	20,160.00	4,540.00
				- List Item Discount on L Items 5.00/5.00% (\$\$)	1,008.00	227.00
				Total Parts (\$\$)	19,152.00	4,313.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND RENEW DAMAGED PARTS ,STRAIGHTEN AND REALIGN AFFECTED AREAS	New	1,600.00	500.00
2	RESPRAY AFFECTED AREAS	New	1,600.00	500.00
3	REMOVE AND REFIT REAR UPHOLSTERY AND TRIMS TO ASSIST WORKLOAD	New	500.00	0.00
4	TO CHECK FRONT LIGHTS PARKING SENSOR	New	120.00	40.00
5	GENERAL DIAGNOSIS AND CHECKING	New	300.00	150.00
6	WIRING FOR PARKING SENSOR CAMERA & SENSORS	New	200.00	40.00
Gross Labour Cost (\$\$)			4,320.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >