

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, iSpace, Singapore 627608.

Enquiry Hotline : +65 6250 1198 / Fax : +65 6250 1081

Company Registration No. : 200507694R

**ESTIMATION FOR SJZ5823D**

Reference No: Q-20-108

Date: 9/3/2020

Terms: Cash

Requested By: American International Group

78 Shenton Way #07-16

Singapore 079120

Tel: 6419 3000

Item	Description	Qty	Unit Price	Disc %	Total Price	
	Policy No // Accident Date: MT/00620631 // 28/2/2020					
	Drive In: 28/1/2020					
	Vehicle Make/Model: Audi Q5 3.2 FSI Quattro					
	Vehicle Number: SJZ5823D					
	Manufacturing Year: 2010					
	Engine: CALB					
	Chassis No :WAUZZZ8R6BA037522					
	Audi Genuine Front Bumper 807-020	1 unit	\$ 1,800.00	5%	\$ 1,710.00	de
	Audi Genuine Bumper Spoiler	1 unit	\$ 350.00	5%	\$ 332.50	X
	Audi Genuine Grille 553-030	1 unit	\$ 950.00	5%	\$ 902.50	man
	Audi Genuine Right Fog Lamp 941-090	1 unit	\$ 150.00	5%	\$ 142.50	X
	Audi Genuine Right Fender 821-000	1 unit	\$ 500.00	5%	\$ 475.00	bt
	Audi Genuine Right Screw & Clips	1 unit	\$ 50.00	5%	\$ 47.50	re
	Audi Genuine Mount Kit	1 unit	\$ 50.00	5%	\$ 47.50	X
	Audi Genuine Bracket	1 unit	\$ 50.00	5%	\$ 47.50	X
	Audi Genuine bracket	1 unit	\$ 50.00	5%	\$ 47.50	X
	Audi Genuine Support	1 unit	\$ 60.00	5%	\$ 57.00	X
	Audi Genuine End Plate	1 unit	\$ 70.00	5%	\$ 66.50	X
	Audi Genuine Seal	1 unit	\$ 50.00	5%	\$ 47.50	X
	Audi Genuine Plate	1 unit	\$ 120.00	5%	\$ 114.00	X
	Audi Genuine Front Right Cover 807-035	1 unit	\$ 150.00	5%	\$ 142.50	mis
	Audi Genuine Headlamp 941-010	1 unit	\$ 1,800.00	5%	\$ 1,710.00	man
	Audi Genuine Gas Bulb	1 unit	\$ 350.00	5%	\$ 332.50	X
	Audi Genuine HID Headlight Ballast	1 unit	\$ 850.00	5%	\$ 807.50	X
	Audi Genuine Control Unit	1 unit	\$ 500.00	5%	\$ 475.00	X
	Audi Genuine Power Mod	1 unit	\$ 1,000.00	5%	\$ 950.00	X
	Audi Genuine Retaining Plate	1 unit	\$ 50.00	5%	\$ 47.50	man
	Audi Genuine Retaining Plate	1 unit	\$ 50.00	5%	\$ 47.50	X
	Audi Genuine Range Control Bracket	1 unit	\$ 80.00	5%	\$ 76.00	X
	Audi Genuine Headlamp Bracket	1 unit	\$ 80.00	5%	\$ 76.00	X
	Audi Genuine Headlamp Repair Kit	1 unit	\$ 80.00	5%	\$ 76.00	man
	Audi Genuine Mounting for Headlamp 805-000	1 unit	\$ 80.00	5%	\$ 76.00	man
	Audi Genuine Bolt	1 unit	\$ 10.00	5%	\$ 9.50	X
	Audi Genuine End Plate Plate	1 unit	\$ 500.00	5%	\$ 475.00	X
	Audi Genuine Reinforcement Bar	1 unit	\$ 1,900.00	5%	\$ 1,805.00	X
	Audi Genuine Helper Reinforce Right Reinforcement	1 unit	\$ 100.00	5%	\$ 95.00	X
	Audi Genuine Center Upper reinforce Reinforcement	1 unit	\$ 180.00	5%	\$ 171.00	X
	Audi Genuine Carrier For Radiator	1 unit	\$ 550.00	5%	\$ 522.50	X
	Audi Genuine Plate	1 unit	\$ 50.00	5%	\$ 47.50	X
	Audi Genuine Right Cross Support	1 unit	\$ 50.00	5%	\$ 47.50	X
	Audi Genuine Radar System 907-005	1 unit	\$ 5,800.00	5%	\$ 5,510.00	X
	Audi Genuine Braket with Radar	1 unit	\$ 150.00	5%	\$ 142.50	X
	Audi Genuine Cover Frame For Radar	1 unit	\$ 50.00	5%	\$ 47.50	X
	Audi Genuine Fog Lamp 941-090	1 unit	\$ 150.00	5%	\$ 142.50	X
	Audi Genuine Trim For Wheel Arch 853-010	1 unit	\$ 80.00	5%	\$ 76.00	X

Audi Genuine Wheel Protector Cover	821-050	1 unit	\$ 180.00	5%	\$ 171.00	✓
Audi Genuine Wheel Protector Cover clips		1 Set	\$ 60.00	5%	\$ 57.00	X
Audi Genuine Parking Sensor		1 unit	\$ 300.00	5%	\$ 285.00	X
Audi Genuine Front Radiator Cover	807-000	1 unit	\$ 100.00	5%	\$ 95.00	X
Audi Genuine Impact Bar		1 unit	\$ 450.00	5%	\$ 427.50	✓
Audi Genuine Mounting Clips		1 unit	\$ 140.00	5%	\$ 133.00	X
Audi Genuine Front Bumper Grill Lower Cover		1 unit	\$ 40.00	5%	\$ 38.00	X
Remove and renew damaged parts, straighten and realign affected areas		1			\$ 1,600.00	500
Respray affected areas.		1			\$ 1,600.00	500
Remove and refit rear upholstery and trims to assist workload		1			\$ 500.00	X
To check Front lights, Parking sensor		1			\$ 120.00	40
General diagnosis and checking		1			\$ 300.00	150
Wiring for Parking Sensor Camera & Sensors		1			\$ 200.00	40
PRICE BEFORE GST					\$ 23,472.00	
ADD GST 7%					\$ 1,643.04	
Grand Total:					\$ 25,115.04	

Taufik 97495749 / 67418434
WP

9/3/20 @ 220 pm

Lumpsum

Resurvey after repair

4 days

Taufik @ khantow.com

Sur @ khantow.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: