

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 54660**
Date Estimated : **03/03/2020**
Prepared By : **Han Kwan Yong**

- ESTIMATE REPAIR FOR -
Goh Ser Kwang, Mark
64-1 SPOTTISWOODE PARK ROAD

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

SINGAPORE 088653

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFC6698K	WBATR120209A50528	31/10/2019	X3 sDrive20i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachment, rear right wheel arch cover including remove attachments to facilitate repair.	850.00		850.00
To respray rear bumper.	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER PANEL PRIMED (X LINE PM	1,555.40	1.00		1,555.40
EXPANDING RIVET BLACK	1.40	10.00		14.00
REAR RH WHEEL ARCH TRIM	189.70	1.00		189.70

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,759.10
Total Labour & Parts :	3,773.10
Deduction for Excess :	0.00
Total Repair Costs less Excess:	3,773.10
GST @7%:	264.12
Grand Total :	4,037.22