



**Diplomat Parts Pte. Ltd.**

Company Reg No. 196400304H  
GST Reg No. MR-8500111-X

## ESTIMATE

Invoice Name & Address		Owner Name & Vehicle Info	
CYCLE & CARRIAGE INDUSTRIES PTE LTD		Reg No/Reg Date	SMC6811S / 25/03/2015
Singapore		Date In/Mileage	/ 0
		Chassis No	WAUZZZ8V3F1032135
		Engine No	CZC205525
Contact No	Home: 0	Make/Model	AUDI A3 SEDAN 1.4 TFSI AMBIENTE MY 15

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
CSM00061	Cash	02/03/2020/ 14:47	TLC	442 / CocoLu	23835				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
E	PNT88000 RENEW FRT BUMPER, FRT GRILLE								640.00
E	PNT98000 SPRAY PAINT FOR FRT BUMPER								320.00
M	SUNDRY FRT NUMBER PLATE WITH FRAME								50.00
A	54900099 CHECK WIRING & ELECTRICAL SYSTEM								20.00
A	10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M	SUNDRY Sundry								20.00
M	SUNDRY FRT BUMPER								1825.00
M	SUNDRY FRT GRILLE WITH LOGO								750.00
M	SUNDRY SCREW SET								150.00
M	SUNDRY FRT FOGLAMP COVER LH								128.00
M	SUNDRY FRT BUMPER REINFORCEMENT								580.00

Confirm & accepted by

Authorized signatory and company stamp

Nett	4,603.00
7% GST on	4603.00
	322.21
<b>Total Payable</b>	<b>4,925.21</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.