



Diplomat Parts Pte. Ltd.

Company Reg No. 196400304H
GST Reg No. MR-8500111-X

ESTIMATE

Invoice Name & Address

Owner Name & Vehicle Info

CYCLE & CARRIAGE INDUSTRIES PTE LTD

Singapore

Contact No Home: 0

Reg No/Reg Date SMC6811S / 25/03/2015
 Date In/Mileage / 0
 Chassis No WAUZZZ8V3F1032135
 Engine No CZC205525
 Make/Model AUDI A3 SEDAN 1.4 TFSI AMBIENTE MY 15

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00061	Cash	02/03/2020/ 14:47	TLC	442 / CocoLu	23835			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

E	PNT88000							370 / 640.00
	RENEW FRT BUMPER, FRT GRILLE	390						
E	PNT98000							280 / 320.00
	SPRAY PAINT FOR FRT BUMPER	280						
M	SUNDRY							50.00 /
	FRT NUMBER PLATE WITH FRAME	NFC						20.00 /
A	54900099							120.00 /
	CHECK WIRING & ELECTRICAL SYSTEM							
A	10028901							20.00 X
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
	USING HI-SCAN PRO TEST							1825.00
M	SUNDRY							
	Sundry							
M	SUNDRY							750.00 /
	FRT BUMPER	x R						
M	SUNDRY							150.00
	FRT GRILLE WITH LOGO	/ CUT						
M	SUNDRY							128.00
	SCREW SET	? x N/A						
M	SUNDRY							580.00
	FRT FOGLAMP COVER LH	X N/A						
M	SUNDRY							
	FRT BUMPER REINFORCEMENT	? x N/A						

Estimate

750
 - 5%
 712.50

17/3/20, 11:45am

SURVEYOR NAME: Steve (LKK)

SURVEYOR SIGNATURE: [Signature]

DATE: 17/3/20

REMARKS: 3 days P/P Rj BOL SY

Confirm & accepted by

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Authorized signatory with company stamp
 • Third party survey is on a "Without Prejudice" basis

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 • No other modification or is allowed
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we are subject to final approval from Insurance Company. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the replacement of the windscreen.

Signature:

Date:

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4558 Fax: (65) 6567 5258

7% GST on Nett 4,603.00 322.21
 Total Payable 4,925.21