

Attn: Adrian

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 #01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

India International Insurance Pte Ltd

64, Cecil Street #04 - 05

IOB Building

Singapore 049711

Tel : 6347 - 6100

Fax : 6224 - 4174

Quotation

DATE : 06.03.2020

VEH NO : SLT9044S

MODEL : Suzuki Vitara

D O A : 03.03.2020

YR REF : GBD1820Z

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLT9044S (SUZUKI VITARA)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Defend</i>	1	971.50 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	58.00 ✓
4	Rear Bumper Reflector - LH <i>Not new</i>	1	35.40 X
5	Rear Bumper Reinforcement <i>Best</i>	1	225.60 ✓
6	Rear Bumper Lower Garnish <i>Defend</i>	1	282.05 ✓
7	Rear Bumper Lower Garnish Centre Lamp <i>Not new</i>	1	35.30 X
8	Rear End Panel <i>Defend</i>	1	414.85 ✓
9	Rear End Panel Top Garnish <i>Defend</i>	1	126.15 ✓
10	Rear End Panel Air Vent <i>LH cancelled</i>	2	76.00 38
11	Tailgate <i>Distorted</i>	1	955.45 ✓
12	Tailgate Lock <i>Defend</i>	1	168.95 ✓
13	Tailgate Weatherstripe <i>not</i>	1	143.55 ✓
14	Tailgate Inner Trim Board <i>new</i>	1	325.80 X
15	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00 ✓
16	Tailgate Outer Garnish <i>cancelled</i>	1	321.45 ✓
17	Tailgate Outer Garnish Clips <i>new</i>	1 set	20.00 ✓
18	Tailgate Damper <i>Not new</i>	2	207.30 X
19	Tailgate Glass Moulding <i>new</i>	1	85.40 ✓
20	Tailgate Lamp <i>LH not</i>	2	509.10 254.55
21	Suzuki Logo <i>2</i>	1	45.40 ✓
22	Suzuki Wording <i>new</i>	1	50.50 ✓
23	Vitara Wording <i>new</i>	1	54.10 ✓
24	Tailgate Top Spoiler <i>new</i>	1	1,192.00 ✓
25	Tailamp <i>LH cancelled</i>	2	723.90 361.95
26	Rear Fender Inner Trim Board - LH <i>Defend</i>	1	464.20 ✓
27	Rear Fender Inner Trim Board Clips <i>new</i>	1 set	30.00 ✓
28	Rear Fender Inner Shield - LH <i>Not new</i>	1	109.25 X

RE: ESTIMATE FOR ACCIDENT REPAIR SLT9044S (SUZUKI VITARA)

29	Rear Fender Inner Shield Clips - LH <i>NPM</i>	1 set	20.00 X
30	Spare Tyre Panel Top Board <i>NPM</i>	1	620.40 X
			<u>8,331.60</u>
			(833.16)
			<u>\$ 7,498.44</u>

6313.65

5375.10

Less 10%

15%

S/NET ITEMS

1	Rear Number Plate <i>{ NPM }</i>	1	30.00 X
2	Rear Number Plate Holder <i>{ NPM }</i>	1	30.00 X
3	Reverse Sensor <i>Dengd</i>	4	728.00 350.
4	Rear End Panel Sealant <i>{ NPM }</i>	1	60.00 ✓
5	Tailgate Glass Sealant <i>{ NPM }</i>	1	60.00 ✓
6	Rear Camera <i>Dengd</i>	1	550.00 450
			<u>1,458.00</u>

Total Parts

\$ 8,956.44

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00 1000
2	To putty & spray up paint works	\$	1,200.00 900
3	To check wiring	\$	50.00 30
4	To underseal	\$	150.00 80
5	To remove reverse sensor	\$	100.00 60
6	To remove tailgate glass	\$	180.00 120
7	To transfer tailgate fittings	\$	150.00 80
8	To remove upholstery	\$	150.00 80
9	To remove rear camera	\$	100.00 50
10	To remove video recorder	\$	100.00 50

Total Labour

\$ 3,380.00

Grand Total

\$ 12,336.44

total: 8745.10

L/S: TK.

OT Dengs.