

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to prior approval from Insurance Company

Acknowledged by Repairer

Signature:

GST REG. NO : M2-0020081 - X

03 MAR 2020



ESTIMATE

Estimate No. : b1 54644
Date Estimated : 02/03/2020
Prepared By : Joseph Yaguel

Page No. : 1 of 4

- ESTIMATE REPAIR FOR -
LIM EE PENG, LINA (LIN YIPING)
381 TAMPINES STREET 32
#02-115

SINGAPORE 520381

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME9490D	WBATR12050LC94449	24/10/2018	X3 sDrive20i	0

DESCRIPTION

Replacing rear bumper panel and attachment
replace damaged part

850 1,275.00

Spray rear bumper

934 1,038.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 177.00

Sundries

80 ✓ ? 80.00

Total Labour 1: 2,570.00

DESCRIPTION

REAR BUMPER CARRIER ? X NN
REAR BUMPER BOTTOM REINFORCEMENT ? X NN
REAR BUMPER PANEL PRIMED (M/PMA) ✓ 00
REAR BUMPER BOTTOM TRIM PANEL (M) ✓ 00

QTY	PRIC	VALUE
1	743.50	743.50
1	78.85	78.85
1	1,555.40	1,555.40
1	370.35	370.35

Total Parts : 2,748.10

Stone (LKK) with Air
16/3/20, 11:39am
3 days
P/P

By Bel sy

Labour 1	:	2,570.00
Parts	:	2,748.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	372.27
Grand Total	:	5,690.37



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **