



SINGAPORE CIVIL DEFENCE FORCE

FIRE REPORT

1. GENERAL INFORMATION			
INCIDENT NO. : /20200225/0802	LOCATION OF FIRE:		
FIRE REPORTED ON : 25 February 2020	Along Upper Changi Road North		
TIME OF CALL : 20:43:35 hrs	Towards TPE before junction of Jalan Bena		
STATION COVERAGE : Changi Fire Station	Near lamp post no. 35, Singapore		
2. INCIDENT INFORMATION			
FIRE INVOLVED: The engine of a Hyundai i40 taxi (SHC688E).			
METHOD OF EXTINGUISHMENT: By SCDF crew using a hose reel and a 38mm compressed air foam hose line jet from fire appliances.			
PROBABLE CAUSE OF FIRE: Accidental (Overheating at the engine compartment)			
DAMAGE SUSTAINED: As a result of the fire, the engine was damaged. The front part of the taxi, including the windscreen, were also damaged. The interior of the car sustained heat, smoke and water damage.			
3. FATALITY/INJURY INFORMATION			
NAME	PIN/FIN	ADDRESS	DEAD/INJURIES SUSTAINED
NIL	NIL	NIL	NIL
REPORT CERTIFIED TRUE AND CORRECT BY:			
RASHID B MD NOOR for COMMISSIONER SINGAPORE CIVIL DEFENCE FORCE			

This is a computer generated Fire Report. No signature is required.