

TO : MS First Capital Insurance Limited

FAX NO:

ESTIMATE REPORT 1ST Quotation

28/02/2020 15:05

OWNER'S PARTICULARS

JOB-NO: 50112469

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC0683E

TRANS: AUTO

CHASSIS: KMHLB41UMEU057874

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDEU440376

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: OD

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREAS	1.00	6,500.00	0.00	6,500.00		Y	_____
2 RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	_____
3 RESPRAY BONNET	1.00	250.00	0.00	250.00		Y	_____
4 RESPRAY FRONT RHS FENDER	1.00	250.00	0.00	250.00		Y	_____
5 RESPRAY FRONT LHS FENDER	1.00	250.00	0.00	250.00		Y	_____
6 RESPRAY FRONT CHASSIS (WHEEL HOUSE PANEL, SIDE MEMBER AND COMPLETE PANEL)	1.00	450.00	0.00	450.00		Y	_____
7 R&R ENGINE ASSY	1.00	450.00	0.00	450.00		Y	_____
8 R&R GEARBOX ASSY	1.00	550.00	0.00	550.00		Y	_____
9 R&R FRONT WINDSCREEEN	1.00	200.00	0.00	200.00		Y	_____
10 R&R DASHBOARD	1.00	500.00	0.00	500.00		Y	_____
11 R&R REPLACE ENGINE NEC PARTS	1.00	650.00	0.00	650.00		Y	_____
TOTAL:		10,300.00	0.00	10,300.00			_____
<u>MATERIALS</u>							
1 FRONT BUMPER	1.00	699.30	139.86	559.44	L	Y	_____
2 FRONT BUMPER REINFORCEMENT	1.00	590.30	118.06	472.24	L	Y	_____
3 FRONT BUMPER REINFORCEMENT SPONGE	1.00	108.30	21.66	86.64	L	Y	_____
4 FRONT SUPPORT PANEL	1.00	986.30	197.26	789.04	L	Y	_____
5 FRONT BUMPER GRILLE	1.00	1,230.30	246.06	984.24	L	Y	_____
6 RADIATOR ASSY	1.00	1,892.30	378.46	1,513.84	L	Y	_____
7 CONDENSER	1.00	1,145.30	229.06	916.24	L	Y	_____
8 HEADLAMP RHS	1.00	1,808.10	361.62	1,446.48	L	Y	_____
9 HEADLAMP LHS	1.00	1,808.10	361.62	1,446.48	L	Y	_____
10 FUSE BOX ASSY X 2	1.00	6,820.30	364.06	5,456.24	L	Y	_____
11 ABS PUMP ASSY	1.00	2,489.60	497.92	1,991.68	L	Y	_____
12 COOLANT TANK ASSY	1.00	856.30	171.26	685.04	L	Y	_____
13 WIPER WASHER TANK ASSY	1.00	450.00	90.00	360.00	L	Y	_____
14 WIPER WASHER MOTOR	1.00	580.30	116.06	464.24	L	Y	_____
15 VEHICLE BATTERY	1.00	280.30	56.06	224.24	L	Y	_____
16 ENGINE ASSY	1.00	17,850.30	570.06	14,280.24	L	Y	_____
17 TRANSMISSION GEAR BOX ASSY	1.00	8,560.30	712.06	6,848.24	L	Y	_____
18 ENGINE MOUNTING -ENGINE	1.00	420.30	84.06	336.24	L	Y	_____
19 ENGINE MOUNTING- GEAR BOX	1.00	256.30	51.26	205.04	L	Y	_____
20 ENGINE MOUNTING -REAR	1.00	359.30	71.86	287.44	L	Y	_____
21 FRONT RHS WHEEL RIM	1.00	895.30	179.06	716.24	L	Y	_____

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
22 FRONT RHS WHEEL CAP	1.00	259.30	51.86	207.44	L	Y	_____
23 FRONT LHS WHEEL RIM	1.00	895.30	179.06	716.24	L	Y	_____
24 FRONT LHS WHEEL CAP	1.00	259.30	51.86	207.44	L	Y	_____
25 ABS PUMP ASSY	1.00	3,560.30	712.06	2,848.24	L	Y	_____
26 FRONT RHS AND LHS BRAKE CALIPER SET X2	1.00	4,800.00	960.00	3,840.00	L	Y	_____
27 FRONT LHS FENDER	1.00	659.30	131.86	527.44	L	Y	_____
28 FRONT RHS FENDER	1.00	659.30	131.86	527.44	L	Y	_____
29 DASHBOARD ASSY	1.00	2,489.30	497.86	1,991.44	L	Y	_____
30 DASHBOARD METER PANEL	1.00	1,880.30	376.06	1,504.24	L	Y	_____
31 ENGINE WIRE HARNESS	1.00	5,720.00	144.00	4,576.00	L	Y	_____
32 WIRE HARNESS ASSY	1.00	1,856.30	371.26	1,485.04	L	Y	_____
33 FRONT WINDSCREEN	1.00	820.30	164.06	656.24	L	Y	_____
34 FRONT RHS SHOCK ABSORBER ASSY	1.00	680.30	136.06	544.24	L	Y	_____
35 FRONT LHS SHOCK ABSORBER ASSY	1.00	680.30	136.06	544.24	L	Y	_____
36 DRIVESHAFT ASSY RHS	1.00	2,203.00	440.60	1,762.40	L	Y	_____
37 DRIVESHAFT ASSY LHS	1.00	2,203.00	440.60	1,762.40	L	Y	_____
38 BRAKE BOOSTER	1.00	1,560.00	312.00	1,248.00	L	Y	_____
39 ALTERNATOR ASSY	1.00	1,320.00	264.00	1,056.00	L	Y	_____
40 COMPRESSOR ASSY	1.00	980.00	196.00	784.00	L	Y	_____
41 TURBO ASSY	1.00	2,960.00	592.00	2,368.00	L	Y	_____
42 ABS HARNESS	1.00	1,450.60	290.12	1,160.48	L	Y	_____
43 BONNET DAMPER LHS	1.00	186.30	37.26	149.04	L	Y	_____
44 BONNET DAMPER RHS	1.00	186.30	37.26	149.04	L	Y	_____
45 ALTERNATOR BELT	1.00	156.30	31.26	125.04	L	Y	_____
46 BATTERY TRAY	1.00	156.30	31.26	125.04	L	Y	_____
47 GEARBOX SELECTOR SWITCH	1.00	456.30	91.26	365.04	L	Y	_____
48 FRONT BUMPER CLIPS	1.00	60.00	0.00	60.00	S	Y	_____
49 FRONT NUMBER PLATE WITH CASING	1.00	120.00	0.00	120.00	S	Y	_____
50 FRONT RHS WHEEL TYRE	1.00	280.00	0.00	280.00	S	Y	_____
51 FRONT LHS WHEEL TYRE	1.00	280.00	0.00	280.00	S	Y	_____
TOTAL:		89,864.60	824.92	72,039.68			_____
TOTAL PARTS & LABOUR :		00,164.60	7,824.92	82,339.68			_____

EXCESS/LOADING: S\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$ _____

DATE OF SURVEY: ___ / ___ / ___

SURVEYED BY: _____

CONTACT NO: _____ FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002
Ding Auto User 2

ESTIMATOR
STA AUTOCENTRE
TEL: _____ FAX: _____

*28/2/2020 @ 1430.
Not Authorise. By cars TBA.
Total Loss.*

*Shariwin
Sharwinboh@lkkauto.com.
Pending investigation on cause of fire.*