



TP CLAIM
INDIA
LKL- Steve Chen

VEHICLE NO : SKS 9037E

MODEL : KIA/CERATO 1.6 A SX

WIP : 11648

Material	:	\$	<u>5,399.00</u>
Labour	:	\$	<u>5,360.00</u>
Sub-Total	:	\$	<u>10,759.00</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>—</u>
Total	:	\$	<u>10,759.00</u>
GST 7%	:	\$	<u>753.13</u>
Grand Total	:	\$	<u>11,512.13</u>
Finalise By/Date	:	<u>Lanny ON 31/03/20</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 08 WORKING DAYS + 2 days (wk. end)

* TP VEHICLE No : SHD3834A

* claim loss of RENTAL.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
SEE JUN HONG, MASON	Cust No/Name LCV10324/SEE JUN HONG, MASON
BLK 997B BUANGKOK CRESCENT	Reg No/Reg Date SKS9037E / 27/06/2019
#13-851	Date In/Mileage 17/03/2020/ 11162
SINGAPORE 532997	Chassis/Package KNAF3416MK5049702 / KC17P
Contact No Mobile: 96733823	Engine No G4FGKH744158
17/03/2020	Make/Model KIA/CERATO 1.6 A SX SR G518
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CTP00080	Cash	31/03/2020/ 15:39	TLC	884 / Lauro Songcuan	11648		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							1925.00✓
RENEW FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH, REPAIR SIDE SILL RH, REAR FENDER RH							
E PNT98000							2100.00✓
SPRAY PAINT FOR FRONT FENDER RH, FRONT DOOR RH, REAR DOOR RH, REAR FENDER RH, SIDE SILL RH							
E PNT88000							275.00✓
REMOVE & INSTALL FRONT DOOR TRIMS AND GLASS							
E PNT88000							275.00✓
REMOVE & INSTALL REAR DOOR TRIMS AND GLASS							
M SUNDRY							80.00✓
APPLY SEALANT FOR AFFECTED PORTIONS							
A 90000001							30.00✓
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901							200.00✓
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
B WHEELALIGNMENT							120.00✓
To Conduct Computerize Full Wheel Alignment							
M SUNDRY							20.00✓
SUNDRIES							
A 90000001							275.00✓
RENEW FRONT UNDER CARRIAGE → <i>Supp</i>							
S SPECIALISTJOB							60.00✓
LABOUR TO TRANSFER TWO TYRES FROM RIM AND RENEW VALVE HEAD D/N NO:114477							
X PANEL-FENDER,RH✓					1.00	430.00 00.00	430.00✓
X PANEL ASSY-FRONT DOOR,RH✓					1.00	1277.00 00.00	1277.00✓
X PANEL ASSY-REAR DOOR,RH✓					1.00	1377.00 00.00	1377.00✓
X BLACK TAPE-FR DR RR,RH✓					1.00	13.00 00.00	13.00✓
X BLACK TAPE-RR DR FR,RH✓					1.00	13.00 00.00	13.00✓
X BLACK TAPE-RR DR FRAME RR OTR,✓					1.00	8.00 00.00	8.00✓
X WHEEL ASSY-ALUMINIUM✓					1.00	926.00 00.00	926.00✓

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
SEE JUN HONG, MASON	Cust No/Name LCV10324/SEE JUN HONG, MASON
BLK 997B BUANGKOK CRESCENT	Reg No/Reg Date SKS9037E / 27/06/2019
#13-851	Date In/Mileage 17/03/2020/ 11162
SINGAPORE 532997	Chassis/Package KNAF3416MK5049702 /KC17P
Contact No Mobile: 96733823	Engine No G4FGKH744158
17/03/2020	Make/Model KIA/CERATO 1.6 A SX SR G518
	Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CTP00080	Cash	31/03/2020/ 15:39	TLC	884 / Lauro Songcuan	11648

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X WHEEL ASSY-ALUMINIUM	1.00	926.00	00.00	926.00
X MOULDING ASSY-FRT DR FRAME,RH	1.00	72.00	00.00	72.00
X MOULDING ASSY-RR DR FRAME,RH	1.00	50.00	00.00	50.00
X FILM-ANTI CHIPPG RH	1.00	27.00	00.00	27.00
X STRUT ASSY-FR,RH	1.00	280.00	00.00	280.00

Z TEXT

TP CLAIM INDIA - SHD3834A

DOA: 14.02.2020

SURVEY: STEVE (LKK) 17.03.20

08 DAYS

Pro Forma

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	5,399.00	Nett	10,759.00
Labour	5,200.00	7% GST on	753.13
Standard Menu	0.00		
Specialist Job	60.00	Total Payable	11,512.13
Diagnostics Job	0.00		
Sundry/Others	100.00		
Total(w/o GST)	10,759.00		

This is not an official tax invoice.

This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : INDIA

Supplementary Parts For Registration No.: SKS 9037 E

	<u>Materials</u>	<u>Cost</u>
1	Moulding Assy- FRT DR Frame, RH <i>nk</i>	72.00
2	Moulding Assy- RR DR Frame, RH <i>nk</i>	50.00
3	Film- Anti Chippg RH <i>nk</i>	27.00
4	Strut Assy- FR, RH <i>BT</i>	280.00
		<u>429.00</u>

	<u>Labour</u>	
1	Renew Front Under Carriage	<u>275.00</u>
		<u>704.00</u>
	7% GST	<u>49.28</u>
	Total	<u>753.28</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE KIA PTE LTD

LARRY SONGCUAN
CUSTOMER SERVICE OFFICER
TEL: 6568 4554
FAX : 6567 5258



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
SEE JUN HONG, MASON BLK 997B BUANGKOK CRESCENT #13-851 SINGAPORE 532997 Contact No	Cust No/Name	LCV10324/SEE JUN HONG, MASON
	Reg No/Reg Date	SKS9037E / 27/06/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5049702
	Engine No	G4FGKH744158
	Make/Model	KIA/CERATO 1.6 A SX SR G518
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV10324	CRDVCH	14/02/2020/ 14:07	BLC	442 / CocoLu	11648			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1915 2200.00
RENEW FRT FENDER RH, FRT DOOR RH, REAR DOOR RH, REPAIR 550								
SIDE SILL RH, REAR FENDER RH,								
E PNT98000								2190 2520.00
SPRAY PAINT FOR FRT FENDER RH, FRT DOOR RH, REAR DOOR RH 410								
REAR FENDER RH, SIDE SILL RH,								
E PNT88000								275 300.00
REMOVE & INSTALL FRT DOOR TRIMS AND GLASS								
E PNT88000								275 300.00
REMOVE & INSTALL REAR DOOR TRIMS AND GLASS								
M SUNDRY								80.00
APPLY SEALANT FOR ACCIDENT PORTION								
A 90000001								30.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
B WHEELALIGNMENT								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								30.00
TRANSFER FRT RIM								
M SUNDRY								30.00
TRANSFER REAR RIM								
M SUNDRY								20.00
Sundry								
M GUARD ASSY-FRONT WHEEL,RH					1.00	95.00	00.00	95.00
M PANEL-FENDER,RH					1.00	430.00	00.00	430.00
M PANEL ASSY-FRONT DOOR,RH					1.00	1277.00	00.00	1277.00
M PANEL ASSY-REAR DOOR,RH					1.00	1377.00	00.00	1377.00
M BLACK TAPE-FR DR RR,RH					1.00	13.00	00.00	13.00
M BLACK TAPE-RR DR FR,RH					1.00	13.00	00.00	13.00
M BLACK TAPE-RR DR FRAME RR OTR,					1.00	8.00	00.00	8.00
M WHEEL ASSY-ALUMINIUM					1.00	926.00	00.00	926.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
SEE JUN HONG, MASON BLK 997B BUANGKOK CRESCENT #13-851 SINGAPORE 532997 Contact No	Cust No/Name	LCV10324/SEE JUN HONG, MASON
	Reg No/Reg Date	SKS9037E / 27/06/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5049702
	Engine No	G4FGKH744158
	Make/Model	KIA/CERATO 1.6 A SX SR G518
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV10324	CRDVCH	14/02/2020/ 14:07	BLC	442 / CocoLu	11648			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M WHEEL ASSY-ALUMINIUM (front RH) ✓ cut					1.00	926.00	00.00	926.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Estimate

SURVEYOR NAME : Steve (LKK) wml PL

SURVEYOR SIGNATURE : _____

DATE : _____

REMARKS : _____

17/3/20, 12.30pm
P/P
By Bal SLJ
8 days

Confirm & accepted by

	Nett	10,895.00
7% GST on	10895.00	762.65
Total Payable		11,657.65

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.