

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Mar 2020 Edit Reg		17 Mar 2020 00:00 Edit Adj Rpt	S\$10,759.00 Edit Estimates	S\$10,759.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R									
Main Claimant: SEE JUN HONG MASON									
Vehicle Reg. No.: SKS9037E		Date of Loss: 14/02/2020 07:00 - :59 [7 Months and 18 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MCT20020272		Policy/Cover Note No.: MCOM0015							
Vehicle Reg. No. (Insured): SHD3834A		Policy No. (Claimant):							
		Excess:							
Repairer: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens, 609339 West Coast - Tel:									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Bhargavi Purushothaman Dhanya]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 13/03/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
- III_SG (02/07/2020): Alert - Adj Mandate Approved (S\$12689.13) - SKS9037E - Claim Handler: Bhargavi P... - III_SG (19/03/2020): Alert - Adj Mandate Approved (S\$0.00) - SKS9037E - Claim Handler: Bhargari Purus...									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKS9037E (MCT20020272)**
[SHD3834A]
TP
SEE JUN HONG MASON
Feb 14 2020 7:00AM
[COMFORT TRANSPORTATION PTE LTD]
Cycle & Carriage KIA Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)
☐

Video					
			1 per page	☐	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	30/06/20 09:24	Video - Accident-Tp		Load MP4	
2	30/06/20 09:29	Video - Accident-IV-FAF		Load MP4	

Photos/Images					
			3 per page	☐	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	17/03/20 20:02	General View		Load JPG	☒
2	17/03/20 20:02	General View		Load JPG	☒
3	17/03/20 20:02	General View		Load JPG	☒
4	17/03/20 20:02	Odometer Reading		Load JPG	☒
5	17/03/20 20:02	Chassis Number		Load JPG	☒
6	17/03/20 20:02	General View		Load JPG	☒
7	17/03/20 20:02	General View		Load JPG	☒
8	17/03/20 20:02	General View		Load JPG	☒
9	17/03/20 20:02	General View		Load JPG	☒
10	17/03/20 20:02	General View		Load JPG	☒
11	17/03/20 20:02	General View		Load JPG	☒
12	17/03/20 20:02	General View		Load JPG	☒
13	17/03/20 20:02	General View		Load JPG	☒
14	17/03/20 20:02	General View		Load JPG	☒
15	17/03/20 20:02	General View		Load JPG	☒
16	17/03/20 20:02	General View		Load JPG	☒
17	17/03/20 20:02	General View		Load JPG	☒
18	17/03/20 20:02	General View		Load JPG	☒
19	17/03/20 20:02	General View		Load JPG	☒
20	17/03/20 20:02	General View		Load JPG	☒
21	17/03/20 20:02	General View		Load JPG	☒
22	17/03/20 20:02	General View		Load JPG	☒
23	17/03/20 20:02	General View		Load JPG	☒
24	17/03/20 20:02	General View		Load JPG	☒
25	17/03/20 20:02	General View		Load JPG	☒
26	17/03/20 20:02	General View		Load JPG	☒
27	17/03/20 20:02	General View		Load JPG	☒
28	17/03/20 20:02	General View		Load JPG	☒
29	17/03/20 20:02	General View		Load JPG	☒
30	17/03/20 20:02	General View		Load JPG	☒
31	17/03/20 20:02	General View		Load JPG	☒
32	17/03/20 20:02	General View		Load JPG	☒
33	17/03/20 20:02	General View		Load JPG	☒
34	17/03/20 20:02	General View		Load JPG	☒
35	17/03/20 20:02	General View		Load JPG	☒
36	17/03/20 20:02	General View		Load JPG	☒

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
37	17/03/20 20:02	General View		Load JPG	☒
38	17/03/20 20:02	General View		Load JPG	☒
39	31/03/20 18:13	Reinspection Photo		Load JPG	☒
40	31/03/20 18:13	Reinspection Photo		Load JPG	☒
41	31/03/20 18:13	Reinspection Photo		Load JPG	☒
42	31/03/20 18:13	Reinspection Photo		Load JPG	☒
43	31/03/20 18:13	Reinspection Photo		Load JPG	☒
44	31/03/20 18:13	Reinspection Photo		Load JPG	☒
45	31/03/20 18:13	Reinspection Photo		Load JPG	☒
46	31/03/20 18:13	Reinspection Photo		Load JPG	☒
47	31/03/20 18:13	Reinspection Photo		Load JPG	☒
48	31/03/20 18:13	Reinspection Photo		Load JPG	☒
49	31/03/20 18:13	Reinspection Photo		Load JPG	☒
50	31/03/20 18:13	Reinspection Photo		Load JPG	☒
51	31/03/20 18:13	Reinspection Photo		Load JPG	☒
52	31/03/20 18:13	Reinspection Photo		Load JPG	☒
53	31/03/20 18:13	Reinspection Photo		Load JPG	☒
54	31/03/20 18:13	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/03/20 11:39	TP ESTIMATE		Load PDF	
2	04/03/20 11:39	TP GIA REPORT		Load PDF	
3	04/03/20 11:39	Certificate of Insurance		Load PDF	
4	18/03/20 15:35	TP ESTIMATE-MARKED		Load PDF	
5	30/06/20 08:59	LOD		Load PDF	
6	30/06/20 08:59	Authorisation to Act		Load PDF	
7	30/06/20 08:59	Workshop Invoice		Load PDF	
8	30/06/20 08:59	Rental Receipt & Agreement		Load PDF	
9	29/07/20 10:58	DISCHARGE VOUCHER		Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	05/03/20 09:00	Singapore Accident Statement		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/III20003542/EPS3S2**Date:** 29/07/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SKS9037E	Insured Vehicle No :	SHD3834A
Date of Loss:	14/02/2020	Nature of Claim:	TP
		Claim No:	MCT20020272

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKS9037E	Engine No:	G4FGKH744158
Make & Model:	KIA CERATO, 1.6 SX (A)	Chassis No:	KNAF3416MK5049702
Reg. Date:	27/06/2019 (Man. Year: 2019)	Odometer:	11162 km
Colour:	Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Kumho 5 mm	Rear Left Side:	Kumho 5 mm
Front Right Side:	Kumho 5 mm	Rear Right Side:	Kumho 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,514.00	5,419.00	95.00	1.72
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,085.00	5,340.00	745.00	12.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,599.00	10,759.00	840.00	7.24
+ GST 7.00/7.00% (\$\$)	811.93	753.13	58.80	7.24
Nett Amount (\$\$)	12,410.93	11,512.13	898.80	7.24
+ Car Rental (10.0 x S\$100.00/day + 7.00% GST) (\$\$)		1,070.00		
Nett Liability (\$\$)		12,582.13		

INSPECTION

Date of Assignment:	17/03/2020	
Date Inspected:	17/03/2020	Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	8.0 days	

Adjuster: CHEN TSUE YEE**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2020)
Parts:	143	KIA CERATO 1.6 SX (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKS9037E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GUARD ASSY-FRONT WHEEL, RH	Not Necessary	95.00 FS	*- FS
2	1		*PANEL - FENDER, RH	Dented	430.00 FS	*430.00 FS
3	1		*PANEL ASSY - FRONT DOOR, RH	Dented	1,277.00 FS	*1,277.00 FS
4	1		*PANEL ASSY - REAR DOOR, RH	Dented	1,377.00 FS	*1,377.00 FS
5	1		*BLACK TAPE - FR DR RR, RH	Necessary	13.00 FS	*13.00 FS
6	1		*BLACK TAPE - RR DR FR, RH	Necessary	13.00 FS	*13.00 FS
7	1		*BLACK TAPE - RR DR FRAME RR OTR,	Necessary	8.00 FS	*8.00 FS
8	1		*WHEEL ASSY - ALUMINIUM (REAR RH)	Cut	926.00 FS	*926.00 FS
9	1		*WHEEL ASSY - ALUMINIUM (FRONT RH)	Cut	926.00 FS	*926.00 FS
10	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
11	1		*MOULDING ASSY - FRT DR FRAME, RH	Necessary	72.00 FS	*72.00 FS
12	1		*MOULDING ASSY - RR DR FRAME, RH	Necessary	50.00 FS	*50.00 FS
13	1		*FILM - ANTI CHIPPG RH	Necessary	27.00 FS	*27.00 FS
14	1		*STRUT ASSY, - FR, RH	Bent	280.00 FS	*280.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	5,514.00	5,419.00
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT FENDER RH, FRT DOOR RH, REAR DOOR RH, REPAIR SIDE SILL RH, REAR FENDER RH.	New	2,200.00	1,925.00
2	SPRAY PAINT FOR FRT FENDER RH, FRT DOOR RH, REAR DOOR RH REAR FENDER RH, SIDE SILL RH,	New	2,520.00	2,100.00
3	REMOVE & INSTALL FRT DOOR TRIMS AND GLASS.	New	300.00	275.00
4	REMOVE & INSTALL REAR DOOR TRIMS AND GLASS.	New	300.00	275.00
5	APPLY SEALANT FOR ACCIDENT PORTION.	New	80.00	80.00
6	CHECK WIRING & ELECTRICAL SYSTEM.	New	30.00	30.00
7	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	New	200.00	200.00
8	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT.	New	120.00	120.00
9	TRANSFER FRT RIM.	New	30.00	30.00
10	TRANSFER REAR RIM.	New	30.00	30.00
11	RENEW FRONT UNDER CARRIAGE.	New	275.00	275.00
Gross Labour Cost (S\$)			6,085.00	5,340.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >