

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K	ESTIMATE	GST Reg No : MR-8500111-X		
Invoice Name & Address	Owner Name & Vehicle Info			
CEE MIN HONG MASON	Cust No/Name	LCV10324/SEE JUN HONG, MASON		
SEE JUN HONG, MASON	Reg No/Reg Date	SKS9037E / 27/06/201		
BLK 997B BUANGKOK CRESCENT	Date In/Mileage	/ 0		
#13-851	Chassis No	KNAF3416MK5049702		
SINGAPORE 532997	Engine No	G4FGKH744158		
Contact No	Make/Model	KIA/CERATO 1.6 A SX SR G518		
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK		

Account No	Terms	Date/Time Pr	inted	CSE	Operator		WIP No			12000
CV10324	CRDVCH	14/02/2020/	14:07	BLC	442 / CocoLu		11648			
2000	SERVICE REPORTS	Description	of Good	s / Service	es a la l	Qty	Unit Price	Disc%		nount
SIDE SIL		RH, FRT DOOR AR FENDER RH,		AR DOOR F	H, REPAIR SSO					2200.0
		FRT FÉNDER RH SIDE SILL RH,		OOR RH, F	EAR DOOR RH 479				2190	2520.0
PNT88000		FRT DOOR TRI		GLASS					275	300.0
	INSTALL	REAR DOOR TR	IMS AND	GLASS					275	300.0
	ALANT FOR	R ACCIDENT PO	RTION	24	ima	品	\			80.0
90000001 CHECK WI	RING & EL	LECTRICAL SYS	TEM (5)[7			30.0
10028901 TO CARRY USING HI		GNOSTIC CHECK								200.0
WHEELALIG	NMENT	terize Full W	heel Al	ianment						120.0
SUNDRY TRANSFER				3						30.0
SUNDRY TRANSFER		4								30.0
SUNDRY Sundry		0								20.0
GUARD AS						1.00 1.00	95.00 430.00	00.00		95.0 430.0
PANEL AS	SY-FRONT	DOOR, RH	00			1.00	1277.00 1377.00	00.00		1277.0
BLACK TA	PE-FR DR	RR,RH/ N/C FR,RH / N/C				1.00	13.00	00.00	1	13.0
BLACK TA	PE-RR DR	FRAME RR OTR	, / Nº			1.00		00.00		926.0

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K	ESTIMATE	GST Reg No : MR-8500111-)		
Invoice Name & Address	Owner Name & Vehicle Info			
CEE JUN HONG MACON	Cust No/Name	LCV10324/SEE JUN HONG, MASON		
SEE JUN HONG, MASON	Reg No/Reg Date	SKS9037E / 27/06/201		
BLK 997B BUANGKOK CRESCENT	Date In/Mileage	/ 0		
#13-851	Chassis No	KNAF3416MK5049702		
SINGAPORE 532997	Engine No	G4FGKH744158		
Contact No	Make/Model	KIA/CERATO 1.6 A SX SR G518		
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK		

Account No	Terms	Date/Time Printed	d CSE	Operator		WIP No	
_CV10324	CRDVCH	14/02/2020/ 14:	07 BLC	442 / CocoLu		11648	
	10 A	Description of G	oods / Services		Qty	Unit Price Disc%	Amount
the Repa To resum To displa Parts pri Third par No illega Supplem is subjec	o Consultar airer of the vey before/afte by damaged paces are subject rty survey is on il modification mentary item(s) tt to final appro-	nts hence notify following: er spray painting art(s) during resurvey ct to confirmation n a "Without Prejudice" bas (s) is allowed) must be resurveyed and oval from Insurance Compa					926.00
Confirm & a	ccepted b	у			7% GST on	Nett 10895.00	10,895.0 762.0
					, , 401 011		
						otal Payable	11,657.6

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.