



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
SEE JUN HONG, MASON BLK 997B BUANGKOK CRESCENT #13-851 SINGAPORE 532997 Contact No	Cust No/Name	LCV10324/SEE JUN HONG, MASON
	Reg No/Reg Date	SKS9037E / 27/06/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5049702
	Engine No	G4FGKH744158
	Make/Model	KIA/CERATO 1.6 A SX SR G518
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV10324	CRDVCH	14/02/2020/ 14:07	BLC	442 / CocoLu	11648		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT FENDER RH, FRT DOOR RH, REAR DOOR RH, REPAIR SIDE SILL RH, REAR FENDER RH,							2200.00
E PNT98000 SPRAY PAINT FOR FRT FENDER RH, FRT DOOR RH, REAR DOOR RH REAR FENDER RH, SIDE SILL RH,							2520.00
E PNT88000 REMOVE & INSTALL FRT DOOR TRIMS AND GLASS							300.00
E PNT88000 REMOVE & INSTALL REAR DOOR TRIMS AND GLASS							300.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION							80.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							200.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY TRANSFER FRT RIM							30.00
M SUNDRY TRANSFER REAR RIM							30.00
M SUNDRY Sundry							20.00
M	GUARD ASSY-FRONT WHEEL,RH			1.00	95.00	00.00	95.00
M	PANEL-FENDER,RH			1.00	430.00	00.00	430.00
M	PANEL ASSY-FRONT DOOR,RH			1.00	1277.00	00.00	1277.00
M	PANEL ASSY-REAR DOOR,RH			1.00	1377.00	00.00	1377.00
M	BLACK TAPE-FR DR RR,RH			1.00	13.00	00.00	13.00
M	BLACK TAPE-RR DR FR,RH			1.00	13.00	00.00	13.00
M	BLACK TAPE-RR DR FRAME RR OTR,			1.00	8.00	00.00	8.00
M	WHEEL ASSY-ALUMINIUM			1.00	926.00	00.00	926.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
SEE JUN HONG, MASON BLK 997B BUANGKOK CRESCENT #13-851 SINGAPORE 532997 Contact No	Cust No/Name	LCV10324/SEE JUN HONG, MASON
	Reg No/Reg Date	SKS9037E / 27/06/201
	Date In/Mileage	/ 0
	Chassis No	KNAF3416MK5049702
	Engine No	G4FGKH744158
	Make/Model	KIA/CERATO 1.6 A SX SR G518
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV10324	CRDVCH	14/02/2020/ 14:07	BLC	442 / CocoLu	11648

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M WHEEL ASSY-ALUMINIUM	1.00	926.00	00.00	926.00
<div align="center" style="font-size: 100px; opacity: 0.3;">Estimate</div>				

Confirm & accepted by

	Nett	10,895.00
7% GST on	10895.00	762.65
Total Payable		11,657.65

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.