

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 31225

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0225/2020/KS
Date : 03-Mar-20

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lee Hwee Hoon, Karen
Address : Blk 226 Simei Street 4
#04-84
Singapore 520226
Telephone : HP +65 97567585
Type of Claim : Own Damage Claims
Policy No. :
Vehicle No : **SMG 5361 J**
Model Code : Audi A3 SEDAN 1.4 TFSI
Model / Year : 24-12-18
Engine No : CZE 847105
Chassis No : WAUZZZ8V8K1010268
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Dec-18
Place of Accident : Spottiswoode Residences

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMG 5361]

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and reinstall rear parking aid. Check function.	S/N \$ 280.00 /	
2	To renew lhs 1/4 glass and rear windscreen to facillitate fender renewal.	S/N \$ 600.00 /	
3	To remove and transfer lhs rear door's multi-lock system and power window devices.	S/N \$ 350.00 /	
4	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N \$ 1,400.00 /	(photo)
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims, seat belts. Dislodge roof liner and disengage curtain airbag etc.	S/N \$ 1,400.00 /	(photo)
6	To dismantle lhs rear door, rear bumper and rear lid. Cut out and weld lhs rear fender. Renew lhs rear door and align to positon. Reinstall all parts removed. <i>500</i>	\$ 6,300.00 <i>4000</i>	
SUB TOTAL LABOUR CHARGES		: \$ 10,330.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMG 5361]

<u>S/n</u>	<u>Nature of Jobs</u>	<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
7	To respray lhs rear door, lhs rear fender, lhs sill panel, door entrance, drain panel, roof channel and end panelling. To carry out stone chip treatment and joint sealer work. <i>SS0 x 5.5</i>	\$ 4,600.00	3025
8	To dismantle lhs rear suspension. Inspect for damages and renew if necessary.	S/N \$ 1,200.00	?
9	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	/
10	To carry out diagnostic check.	S/N \$ 192.00	/
TOTAL LABOUR CHARGES		: <u>\$ 16,602.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 5361]

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	REAR DOOR LH / <i>OK</i>	\$	2,375.00
2	REAR DOOR OUTER SEAL LH / <i>NC</i>	\$	151.00
3	BONDING AGENT / <i>NC</i>	\$	46.00
4	CLEANING SOLUTION / <i>nc</i>	\$	64.00
5	REAR DOOR CATCH LH <i>X</i>	\$	89.00
6	REAR DOOR WINDOW REGULATOR LH <i>?</i>	\$	234.00
7	REAR DOOR WINDOW GUIDE RAIL LH <i>X</i>	\$	49.00
8	REAR DOOR ATTACHMENT PARTS / <i>nc</i>	\$	121.00
9	REAR FENDER LH / <i>OK</i>	\$	2,195.00
10	REAR WHEEL HOUSING LINER LH <i>?</i>	\$	226.00
11	WHEEL HOUSING LINER ATTACHMENT PARTS <i>?</i>	\$	84.00
12	REAR QUARTER GLASS LH / <i>nc</i>	\$	537.00
13	REAR WINDSCREEN / <i>nc</i>	\$	766.00
14	REAR WINDSCREEN PRIMER / <i>nc</i>	\$	37.00
15	REAR WINDSCREEN SEALANT / <i>nc</i>	S/N \$	200.00
16	QUARTER GLASS SEALANT / <i>nc</i>	S/N \$	100.00
17	ARYCLIX SEALER / <i>nc</i>	S/N \$	180.00
18	CAVITY WAX / <i>nc</i>	S/N \$	140.00
19	STONECHIP / <i>nc</i>	S/N \$	180.00
20	METAL FILLER POWDER / <i>nc</i>	S/N \$	280.00
21	ALUMINIUM RIM REAR LH / <i>cm</i>	\$	666.00
22	WHEEL BEARING ASSEMBLY <i>?</i>	\$	448.00
23	SUNDRIES <i>?</i>	\$	600.00

TOTAL SPARE PARTS	:	\$ 9,768.00
TOTAL LABOUR CHARGES	:	\$ 16,602.00
GRAND TOTAL	:	\$ 26,370.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Store (LKK)

3/3/90, 10.30am
DD - NH Auth
EXCESS - ?

Surveyed Date

:

Authorised Date

:

12 days

Excess Cost

:

P/P

Liability

:

Remarks

:

Ry Be sy

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

- LKK Auto Consultants hence notify the Repairer of the following:**
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant