

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

first

Owner : Lim Hock Siong

Accident Date : 24-Feb-20

Vehicle No : FW 180 X

Vehicle Model : Honda FJS400A

Estimated Repair Costs

Qty	Description	Amount S(\$)
List Items		
2	Fork inner tubes	\$ 11 570.00 X
2	Fork outer tubes	\$ 17 590.00 X
1	Front rim shaft	\$ 17 38.00 X
1	Front brake disc	\$ 17 150.00 X
1	Front sport rim	\$ 17 450.00 X
1	Front signal	\$ 115 120.00
1	Headlamp	\$ one 320.00
1	Side mirror -L/H	\$ 147 85.00
1	Handle bar	\$ 17 150.00 X
1	Handle bar end	\$ 17 45.00 X
1	Brake lever	\$ 512 32.00
1	Footstep panel	\$ 147 145.00
1	Mainstand	\$ 147 185.00
1	Transmission outer cover	\$ 147 350.00
1	Fairing cover (1 set)	\$ one 1150.00
		\$ 4,380.00
Less 10%		\$ 438.00
		\$ 3,942.00

not added
Lim
4/3/20
2600
4/3/20
4/3/20
4/3/20

LPR Auto Consultants hence notify
Repairer of the following:

- Repairs before/after spray painting
- Repairs to damaged part(s) during resurvey
- Repairs are subject to confirmation
- Repairs survey on a "Without Prejudice" basis
- Repairs notification(s) is allowed
- Repairs (item(s) must be resurveyed and
- Repairs to final approval from Insurance Company

Known by Repairer
Signature:

2312
107
2020-8

Special Nett Items

1	Number plate (1 set)	\$ 17	28.00	X
2	Fork oils	\$ 17	30.00	X
2	Fork oil seals	\$ 17	56.00	X
1	Steering cone (1 set)	\$ 17	120.00	X
1	Rear box	\$ 657	650.00	400
1	Rear box bracket	\$ 17	150.00	X
		\$	1,034.00	

S/No. Labour

1	To provide towing service.	\$ 17 X	45.00
2	To check wiring and reset headlamp focusing	\$ 17 X	80.00
3	To provide labour.	\$ 300	480.00
4	To respray painting .	\$ 500	600.00
		\$	1,205.00

Grand Total

\$ 6,181.00

32808



EROFIA MOTOR TRADING PTE LTD