



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Tey Chin Tiong 118A Jalan Pari Burong Singapore 488761 Work: 67440312
	Document No 0	
	Document Date 25/02/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	18/04/2017	SGG0118A	0	53676 72/DS/SGG0118A
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MRO53REH104561426	1ZRY343526	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: CHINA TAIPING INSURANCE TP VEH: SMJ6730E DATE OF ACC: 25.02.2020			new ✓	50. 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)			new ✓ ✓	200.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR			✓ ✓	180.00
4	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST			✓ ✓	122.40
5	B	BP-LAB2 REMOVE AND TRANSFER BOOTLID COMPONENTS ONTO NEW BOOTLID			✓ ✓	360.00
6	B	BP-LAB2 R/I REAR REVERSE CAMERA TO FAC REPAIR			✓ ✓	180.00
7	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR			✓ 360	720.00
8	B	BP-ECU2 TO RESET ECU AND REPROGRAMME			✓ ✓	180.00
9	L	BP-LPO SUPPLY REGN PLATE (PO#)			✓ Ad	80.00
10	B	BP-LAB2 REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS			✓ 2880	3600.00
11	B	BP-RES2 RESPRAY ACC AFFECTED AREAS			✓ 2950	3540.00
12	1	SPZ061-12021 76 BACK SENSOR 1F9 310A	1.00	159.75	new ✓	159.75
13	2	SPZ067-12006 BACK CAMERA	1.00	628.90	x mn ✓	628.90
14	3	S52159-0Z904 COVER, RR BUMPER	1.00	556.40	de ✓	556.40
15	4	S52575-02140 RETAINER, RR BUMPER R	1.00	109.30	new ✓	109.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Tauhid 97495749/674184 WP 9/3/2020 1130. Resurvey type paint Less tauhid@ikanto.com sur@ikanto.com 8-9 days.
			Amount Due

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

Acknowledged by Repairer

DATE

25/02/2020

PLEASE ALLOW THE UNDERMENTIONED

TIME

16:34

VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO

SGG0118A

CUSTOMER

SIGNATURE

FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking :

www.toyota.com.sg

Toyota Bodycare Centre

No. 2 Pandan Crescent

Singapore 128462

Tel no.: 6631 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	Mr Tey Chin Tiong 118A Jalan Parli Burong Singapore 488761 Work: 67440312
	Document No 0	
	Document Date 25/02/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	18/04/2017	SGG0118A	0	53676 72/DS/SGG0118A
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MRO53REH104561426	1ZRY343526	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	5	S52562-02250 RETAINER, RR BUMPER R	1.00	60.40	✓	✓ 60.40
17	6	S52576-02140 RETAINER, RR BUMPER L	1.00	109.30	✓	✓ 109.30
18	7	S52563-02250 RETAINER, RR BUMPER L	1.00	60.40	✓	✓ 60.40
19	8	S52161-0K040 PIECE, RR BUMPER	10.00	4.10	✓	✓ 41.00
20	9	S52591-02301 SEAL, RR BUMPER RH	1.00	55.10	X	55.10
21	0	S52592-02301 SEAL, RR BUMPER	1.00	55.10	X	55.10
22	1	T90189-06013 GROMMET,	10.00	2.20	X	22.00
23	2	T90467-05170 CLIP	10.00	2.50	X	25.00
24	3	S52023-02190 REINFORCEMENT, RR	1.00	399.50	✓	✓ 399.50
25	4	S52181-02190 ARM, RR BUMPER RH	1.00	68.20	✓	✓ 68.20
26	5	S52182-02160 ARM, RR BUMPER LH	1.00	68.20	✓	✓ 68.20
27	6	S58307-02380 PANEL, LAMP LOWER	1.00	670.00	✓	✓ 670.00
28	7	S64401-02B71 PANEL SUB-ASSY, LUGG	1.00	793.20	✓	✓ 793.20
29	8	S64461-02220 WEATHERSTRIP, LUGGAGE	1.00	175.80	✓	✓ 175.80
30	9	S64503-02181 ARM SUB-ASSY, LUG CO	1.00	69.90	✓	✓ 69.90
31	0	S64503-02181 ARM SUB-ASSY, LUG CO	1.00	69.90	✓	✓ 69.90
32	1	S64600-02080 LOCK ASSY, LUGGAGE	1.00	399.50	✓	✓ 399.50
33	2	S58387-02240 PLATE, RR FLOOR	1.00	241.90	✓	✓ 241.90
34	3	T90467-08186 CO CLIP	2.00	2.80	✓	✓ 5.60
35	4	S75431-02090 LUGGAGE COMP EMBLEM,	1.00	61.60	✓	✓ 61.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

4195200

TO SECURITY GUARD

4195200

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 25/02/2020
TIME 16:34

VEHICLE NO SGG0118A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motors

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
www.toyota.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail		Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mr. Tey Chin Tiong 118A Jalan Pari Burong Singapore 488761 Work: 67440312
		Document No	
		0	
		Document Date	
		25/02/2020	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
16	GEXGKZ	S3	ZRE171R	18/04/2017	SGG0118A	0	53676 72/DS/SGG0118A
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
MRO53REH104561426	1ZRY343526	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
36	5	S75442-02330 PLATE, LUGGAGE COMPT	1.00	41.00	new	✓ 41.00
37	6	S75442-02340 PLATE, LUGGAGE COMPT	1.00	45.60	new	✓ 45.60
38	7	S76801-02E30 GARNISH SUB-ASSY	1.00	243.70	X ny	243.70
39	8	S81550-02780 LAMP ASSY, RR COMB RH	1.00	379.80	new	✓ 379.80
40	9	S81560-02780 LAMP ASSY, RR COMBIN	1.00	379.80	new	✓ 379.80
41	0	S81580-02551 LAMP ASSY, RR, RH	1.00	394.50	new	✓ 394.50
42	1	S81590-02551 LAMP ASSY, RR, LH	1.00	394.50	? X	394.50
43	2	S81910-02170 REFLECTOR ASSY, REFL	1.00	59.80	X	59.80
44	3	S81920-02110 REFLECTOR ASSY, REFL	1.00	59.80	X	59.80
45	4	T89997-30070 ELECTRICAL ANTENNA,	1.00	192.20	new	✓ 192.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	16,359.05
	Please acknowledge receipt of vehicle	Parts 7,096.65	GST 7.00%	1,145.13
		Labour 9,182.40	Less	0.00
		Materials 80.00		
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	17,504.18

PLEASE TEAR ALONG PERFORATED LINE

4195201

TO SECURITY GUARD

4195201

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 25/02/2020
TIME 16:34

VEHICLE NO SGG0118A

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors