



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2005705
INV Date 19/08/2020
Reference CC6/CTI20003562/Gda3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SLL 3237J
Insured Veh. GBA 9577P
Claim No. SNM20D201131
Policy No. DMCVSN1810381901
Accident Date 28/02/2020
Inspection Date 03/03/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI20003562/Gda3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 19-08-2020		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBA 9577P	Veh. Inspected	SLL 3237J	
Policy No.	DMCVSN1810381901	Coverage (\$)	0.00	
Claim No.	SNM20D201131	Excess (\$)	0.00	
Assign From		Assign Date	03/03/2020	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE 1.6	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMH DU41BR9U729375	Colour	MAROON	
Odometer	280579	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	NEUTON	5 mm	
L/H Front Tyre	195/65 R15	NEUTON	5 mm	
R/H Rear Tyre	195/65 R15	NEUTON	5 mm	
L/H Rear Tyre	195/65 R15	NEUTON	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/02/2020	Inspection Date	03/03/2020	
Survey held at	GREEN FOREST AUTOMOBILE PTE LTD 8 KAKI BUKIT AVENUE 4 #05-25 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 3237J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAIL LAMP - LH	NOT NECESSARY	285.20	-
4	REAR TAIL LAMP CLIPS @\$6.50	NOT NECESSARY	52.00	-
1	REAR TAIL LAMP PANEL	NOT NECESSARY	158.00	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	437.00	-
2	REAR BUMPER SIDE BRACKET @\$35.00	NOT NECESSARY	70.00	-
10	REAR BUMPER CLIPS @\$6.50	NOT NECESSARY	65.00	-
1	REAR BUMPER REVERSE SENSOR	NOT NECESSARY	350.00	-
1	REAR FENDER - LH	TO REPAIR SEE LABOUR	1,250.00	-
1	REAR FENDER INNER TRIM BOARD	NOT NECESSARY	397.20	-
10	REAR FENDER INNER TRIM BOARD CLIPS @\$6.50	NOT NECESSARY	65.00	-
1	REAR TYRE - LH	NOT NECESSARY	300.00	-
1	REAR SHOCK ABSORBER	NOT NECESSARY	325.00	-
1	REAR WHEEL BEARING	NECESSARY	155.00	155.00
1	REAR TRADING ARM	NOT NECESSARY	215.00	-
1	REAR LOWER ARM	BENT	261.00	261.00
1	REAR DOOR - LH	TO REPAIR SEE LABOUR	1,020.00	-
1	REAR DOOR GLASS GEAR MOTOR ASSY - LH	NOT NECESSARY	320.00	-
1	REAR DOOR PROTECTOR	NOT NECESSARY	240.00	-
1	REAR DOOR OUTER HANDLE - LH	TO REPAIR SEE LABOUR	52.60	-
1	REAR DOOR RUBBER - LH	NOT NECESSARY	75.80	-
1	REAR DOOR INNER LOCK - LH	NOT NECESSARY	228.60	-
	LESS 20% DISCOUNT		-	-83.20
			6,322.40	332.80
<u>SPECIAL NETT ITEMS</u>				
1	REAR RIM - LH (SN)	CUT	450.00	250.00
			450.00	250.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE & RE-FIX CUSHION.		120.00	60.00
	TO REMOVE & RE-FIX / LH REAR DOOR.		200.00	40.00
	TO CHECK WIRING SYSTEM.	NOT NECESSARY	60.00	-
	REMOVE AND REFIX REAR UNDERCARRIAGE.		250.00	150.00
	TUFF KOTE.	NOT NECESSARY	150.00	-
	TOWING CHARGES.		100.00	40.00
	WHEEL ALIGNMENT (COMPUTER)		120.00	60.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER, REAR FENDER - LH, REAR DOOR - LH AND REAR DOOR OUTER HANDLE - LH.		800.00	600.00
	SPRAY PAINTING.		800.00	600.00
			2,600.00	1,550.00
GRAND TOTAL			9,372.40	2,132.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,700.00

Report Ref No. CC6/CTI20003562/Gda3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 3237J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 3237J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

