

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

THE CARHUB
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

02nd MARCH 2020

Accident date: 28th FEBRUARY 2020

Estimated repair cost for vehicle no: SLL3237J HYUNDAI HD AVANTE 1.6 A '09

S/n	Qty	Items	U/price	Amount
1	1	Rear Tail Lamp -LH X NN		\$285.20
2	4	Rear tail lamp clips X NN	\$6.50	\$52.00
3	1	Rear Tail Lamp Panel X NN		\$158.00
4	1	Rear Bumper X Repair		\$437.00
5	2	Rear Bumper Side Bracket X NN	\$35.00	\$70.00
6	10	Rear Bumper Clips X NN	\$6.50	\$65.00
7	1	Rear Bumper Reverse Sensor X NN		\$350.00
8	1	Rear Fender-LH x Repair		\$1,250.00
9	1	Rear Fender Inner Trim Board X NN		\$397.20
10	10	Rear Fender Inner Trim Board Clips X NN	\$6.50	\$65.00
11	1	rear tyre -LH X NN		\$300.00
12	1	Rear rim -LH / cut		\$450.00
13	1	Rear shock absorber X NN		\$325.00
14	1	rear wheel bearing - rec. - photo.		\$155.00
15	1	Rear trading arm X NN		\$215.00
16	1	Rear lower arm - BT - photo.		\$261.00
17	1	Rear door -LH X Repair		\$1,020.00
18	1	Rear door glass gear motor assy -LH X NN		\$320.00
19	1	Rear door protector X NN		\$240.00
20	1	rear door outer handle -LH Repair X		\$52.60
21	1	rear door rubber LH X NN		\$75.80
22	1	rear Door Inner Lock LH X NN		\$228.60
Subtotal :-				\$6,772.40

Labour charges

To remove & re-fix cushion

To remove & re-fix /LH rear door

To Check Wiring System

Remove and refix rear undercarriage

Tuff Kote

Towing charges

WHEEL alignment (computer)

Panel beating

Spray painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$120.00 60.

\$200.00 40.

\$60.00 X

\$250.00 150

\$150.00 X

\$100.00 40.

\$120.00 60.

\$800.00 600.

\$800.00 600

Subtotal :- \$2,600.00

Total :- \$9,372.40

2132.8
20%: 1700

416
20%: 332.8

60.

40.

X

150

X

40.

60.

600.

600

1550