

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A**AAD2003-014***Not Authored
11/1/2020*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

03 MAR 2020

SHC 5831A

VF1ABL15AUC281402

RENAULT

LATITUDE

29.2.2020

AIG

6/3/2015

PART	LIST
1 DOOR PANEL FRT LH	\$ R 2,844.66
1 DOOR HINGE UPPER LH	\$ R 274.50
1 DOOR HINGE LOWER LH	\$ R 300.55
1 DOOR CHECK FRT LH	\$ R 90.90
1 DOOR REGULATOR FRT LH	\$ R 758.10
1 DOOR REGULATOR MOTOR FRT LH	\$ R 501.40
1 DOOR REGULATOR GUIDE FRT LH	\$ R 69.00
1 DOOR WHEATHESTRIP FRT LH	\$ R 316.00
1 DOOR SEAL FRONT LH	\$ R 69.60
1 DOOR SEAL FRONT LH	\$ R 63.10
1 DOOR SEAL LOWER FRT LH	\$ R 93.90
1 DOOR MOULDING BLACK FRT LH	\$ R 100.50
1 DOOR FINISHER FRT LH	\$ R 258.90
1 DOOR FINISHER CLIP KIT FRT LH	\$ R 94.00
1 DOOR FINISHER INNER FRT LH	\$ R 197.10
1 DOOR GLASS RUNNER SEAL FRONT LH	\$ R 332.00
1 DOOR HANDLE OUTER FRONT LH	\$ R 169.50
1 DOOR HANDLE CAP FRONT LH	\$ R 17.30
1 DOOR HANDLE MODULE FRT LH L70Y	\$ R 133.40
1 DOOR LOCK FRT LH	\$ R 453.80
1 DOOR WAIST SEAL OUTER FRT LH	\$ R 92.20
1 DOOR MIRROR ASSY LH	\$ R 727.90
1 DOOR MIRROR LAMP LH	\$ R 134.10
1 DOOR HARNESS WIRE LH	\$ R 2,670.00
1 ROCKER PANEL INNER GARNISH LH	\$ R 466.51
1 ROCKER PANEL INNER LH	\$ R 1,024.79
1 ROCKER PANEL OUTER LH	\$ R 1,184.99
1 ROCKER PANEL CENTER LH	\$ R 990.25

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A**AAD2003-014**

1 FENDER PANEL FRT LH	\$	<i>Bz</i>	414.40	✓
1 WHEELARCH FRT LH	\$	<i>Zn</i>	112.30	✓
1 FENDER BRACKET LOWER LH	\$	<i>my</i>	11.80	✓
1 FENDER INSULATOR LH	\$	<i>SL</i>	65.50	X
1 FENDER BRACKET FRT LH	\$	<i>n</i>	38.90	X
1 FENDER PANEL INNER FRT LH	\$	<i>n</i>	858.30	X
1 BUMPER COVER FRT	\$	<i>CM</i>	747.20	✓
1 BUMPER RETAINER FRT LH	\$	<i>CM</i>	101.40	✓
1 BUMPER SPOILER FRT	\$	<i>DI</i>	344.70	✓
1 BUMPER ABSORBER FRT	\$	<i>CM</i>	394.68	✓
1 BUMPER SUPPORT FRT	\$	<i>SL</i>	10.70	X
1 BUMPER UNDERTRAY FRT	\$	<i>SL</i>	292.50	X
1 BUMPER GRILLE LOWER FRT	\$	<i>SL</i>	147.00	X
1 BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i>	207.21	X
1 BUMPER BEAM FRT	\$	<i>n</i>	663.70	X
1 HEADLAMP LH	\$	<i>my Bz</i>	743.60	✓
1 HEADLAMP PANEL FRT LH	\$	<i>n</i>	127.70	X
1 FRONT BRACE PANEL	\$	<i>n</i>	177.22	X
1 RADIATOR GRILLE	\$	<i>SL</i>	969.90	X
1 RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i>	225.36	X
1 RADIATOR GRILLE FRAME	\$	<i>SL</i>	686.00	X
1 FRAME FULL SUPPORT PANEL	\$	<i>SL</i>	592.70	X
1 FRAME FULL SUPPORT BRACKET	\$	<i>n</i>	41.60	X
1 BONNET	\$	<i>Bz</i>	1,312.70	✓
1 BONNET INSULATOR	\$	<i>SL</i>	294.30	} X
1 BONNET STRUT LH	\$	<i>SL</i>	53.30	
1 BONNET HINGE LH	\$	<i>n</i>	236.50	
1 BONNET LOCK	\$	<i>n</i>	152.80	
1 SUBFRAME OUTER FRNT	\$	<i>SL</i>	1,094.20	
1 SUBFRAME BRACKET OUTER LH	\$	<i>SL</i>	49.00	
1 DOOR PANEL REAR LH	\$	<i>n</i>	758.70	
1 DOOR GUIDE REAR LH	\$	<i>SL</i>	136.40	
1 DOOR HINGE UPPER REAR LH L70Y	\$	<i>n</i>	180.70	}
1 DOOR HINGE LOWER REAR LH L70Y	\$	<i>n</i>	169.90	
1 DOOR CHECK REAR LH	\$	<i>SL</i>	114.90	
1 DOOR REGULATOR REAR LH L70Y	\$	<i>SL</i>	657.10	
1 DOOR REGULATOR MOTOR REAR LH L70Y	\$	<i>SL</i>	450.60	

Trans-cab Auto Services Pte Ltd**AAD2003-014**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A

1 DOOR HANDLE OUTER REAR LH L70Y	\$	42.10	
1 DOOR HANDLE CAP REAR LH L70Y	\$	57.90	
1 DOOR HANDLE MODULE REAR LH L70Y	\$	133.40	
1 DOOR SEAL REAR LH	\$	119.40	
1 DOOR WHEATHERSTRIP REAR LH	\$	240.50	
1 DOOR LOCK REAR LH L70Y	\$	468.20	X
1 FENDER PANEL REAR LH	\$	1,933.20	
1 FENDER PANEL INNER TRIM REAR LH	\$	671.45	
1 WHEELARCH REAR LH	\$	181.60	
1 AIR CLEANER BOX	\$	464.20	
1 AIR CLEANER HOSE	\$	175.85	
1 AIR CLEANER LOWER	\$	271.26	✓
1 LOWER ARM LH L70Y	\$	192.70	?
1 KNUCKLE ARM LH L70Y	\$	481.50	✓
1 KNUCKLE HUB+BEARING LH/RH	\$	272.30	✓
1 ABSORBER FRT LH L70Y	\$	274.10	?
1 ABSORBER MOUNTING KIT	\$	273.60	?
1 ABSORBER DUST COVER	\$	52.40	X
1 DRIVESHAFT LH	\$	1,355.70	?
1 FRT STABILIZER BAR	\$	427.90	X
1 STABILIZER LINK FRT	\$	69.50	?
1 INJECTION COMPUTER	\$	2,706.30	?
1 AUTO COMPUTER	\$	1,287.30	?
1 STEERING PUMP ELECTRIC	\$	2,026.70	?
1 STEERING PINION RACK	\$	3,765.30	?

TOTAL	\$	46,008.77
10%	\$	4,600.88
	\$	41,407.90

Special Nett

1 FRONT DOOR STICKER 'Trans-Cab'	\$	80.00	60% ✓
1 FRONT DOOR STICKER 'Classic'	\$	80.00	15% ✓
1 REAR DOOR STICKER '6555-3333'	\$	100.00	60% ✓
1 LH SIDE RENAULT TYRE 215/60/16	\$	300.00	80% ✓
1 LH SIDE RENAULT TYRE RIM	\$	380.00	✓
1 LH SIDE RENAULT TYRE RIM COVER	\$	60.00	X

Trans-cab Auto Services Pte Ltd

AAD2003-014

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A

1	WHEELARCH CLIP FRT LH	\$	na	30.50	✓
1	FRONT WINDSCREEN MOULDING	\$	na	160.00	}
2	WINDSCREEN SEALANT	\$	na	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
1	DOOR CHECK BOLT	\$	sh	10.20	
1	DOOR CHECK NUT	\$	sh	10.20	
1	DOOR GUIDE SCREW	\$	sh	10.85	
1	DOOR HINGE BOLT	\$	sh	10.85	
1	DOOR HINGE NUT LH	\$	sh	7.20	
1	DOOR LOCK SCREW L70Y	\$	sh	3.60	
1	DOOR SEAL CLIP LH	\$	na	4.90	}
1	BUMPER CLIP FRT	\$	na	66.00	
1	BUMPER BRACKET CLIP FRT LH	\$	na	12.00	}
1	BUMPER SUPPORT CLIP FRT LH	\$	na	10.50	
1	BUMPER GRILLE LOWER CLIP	\$	na	69.00	
1	FRAME FULL SUPPORT PANEL CLIP	\$	na	70.00	
1SET	FRAME FULL SUPPORT PANEL NUT	\$	na	20.00	
2	FRAME FULL SUPPORT PANEL STUD	\$	na	30.00	
1SET	RADIATOR GRILLE SCREW	\$	na	16.00	
1SET	RADIATOR GRILLE FRAME CLIP	\$	na	52.00	
1SET	Front licence plate with holder	\$	sh	80.00	}
1	FENDER INNER TRIM CLIP LH	\$	na	28.00	
1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	
TOTAL		\$		1,956.81	

TOTAL PARTS	\$	43,364.70
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$	7,500.00	600
----	----------	-----

To check steering geometry and computer wheel alignment

\$	220.00	60
----	--------	----

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$	na	380.00	X
----	----	--------	---

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A**AAD2003-014**

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>mn</i> 380.00	<i>X</i>
To rust-proofing of the affected areas.	\$	170.00	<i>B 601</i>
Putty and spray painting of the affected portion.	\$	7,500.00	<i>11001</i>
To transfer of tire, rim and on wheel balancing.	\$	170.00	<i>201</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
To transfer of Front door fittings, attachment and perform water seepage test.	\$	<i>12</i> 170.00	<i>X</i>
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>5</i> 170.00	<i>X</i>
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>5</i> 170.00	<i>X</i>
Towing Fees	\$	150.00	<i>501</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>5</i> 170.00	<i>X</i>
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>5</i> 380.00	<i>X</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	<i>7</i>
To check ABS and brake efficiency, final checking and testing.	\$	<i>5</i> 380.00	<i>X</i>
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>5</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD2003-014**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A

To transfer of front bonnet fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X*

To dismantle and refit engine cross-member and engine mounting.

\$ *4* 380.00 *X*

To remove and renew power steering pump, oil cooler pipe and final checking and testing.

\$ *4* 440.00 *X***TOTAL \$ 19,620.00****Over All Total \$ 62,984.70****LUMP SUM (REPAIR DAY)****~~25~~ DAYS***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: