

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A

AAD2003-014

Not Authorised
61 Pins @ 5,950.00

Vehicle No.:

Chassis No.:

Vehicle Make:

03 MAR 2020

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

SHC 5831A

VF1ABL15AUC281402

RENAULT

LATITUDE

29.2.2020

AIG

6/3/2015

PART**LIST**

1	DOOR PANEL FRT LH	\$	R	2,844.66
1	DOOR HINGE UPPER LH	\$	R	274.50
1	DOOR HINGE LOWER LH	\$	R	300.55
1	DOOR CHECK FRT LH	\$	R	90.90
1	DOOR REGULATOR FRT LH	\$	R	758.10
1	DOOR REGULATOR MOTOR FRT LH	\$	R	501.40
1	DOOR REGULATOR GUIDE FRT LH	\$	R	69.00
1	DOOR WHEATHESTRIIP FRT LH	\$	R	316.00
1	DOOR SEAL FRONT LH	\$	R	69.60
1	DOOR SEAL FRONT LH	\$	R	63.10
1	DOOR SEAL LOWER FRT LH	\$	R	93.90
1	DOOR MOULDING BLACK FRT LH	\$	R	100.50
1	DOOR FINISHER FRT LH	\$	R	258.90
1	DOOR FINISHER CLIP KIT FRT LH	\$	R	94.00
1	DOOR FINISHER INNER FRT LH	\$	R	197.10
1	DOOR GLASS RUNNER SEAL FRONT LH	\$	R	332.00
1	DOOR HANDLE OUTER FRONT LH	\$	R	169.50
1	DOOR HANDLE CAP FRONT LH	\$	R	17.30
1	DOOR HANDLE MODULE FRT LH L70Y	\$	R	133.40
1	DOOR LOCK FRT LH	\$	R	453.80
1	DOOR WAIST SEAL OUTER FRT LH	\$	R	92.20
1	DOOR MIRROR ASSY LH	\$	R	727.90
1	DOOR MIRROR LAMP LH	\$	R	134.10
1	DOOR HARNESS WIRE LH	\$	R	2,670.00
1	ROCKER PANEL INNER GARNISH LH	\$	R	466.51
1	ROCKER PANEL INNER LH	\$	R	1,024.79
1	ROCKER PANEL OUTER LH	\$	R	1,184.99
1	ROCKER PANEL CENTER LH	\$	R	990.25

X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A

AAD2003-014

- 1 FENDER PANEL FRT LH
- 1 WHEELARCH FRT LH
- 1 FENDER BRACKET LOWER LH
- 1 FENDER INSULATOR LH
- 1 FENDER BRACKET FRT LH
- 1 FENDER PANEL INNER FRT LH
- 1 BUMPER COVER FRT
- 1 BUMPER RETAINER FRT LH
- 1 BUMPER SPOILER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER SUPPORT FRT
- 1 BUMPER UNDERTRAY FRT
- 1 BUMPER GRILLE LOWER FRT
- 1 BUMPER FOG LAMP GRILLE LH
- 1 BUMPER BEAM FRT
- 1 HEADLAMP LH
- 1 HEADLAMP PANEL FRT LH
- 1 FRONT BRACE PANEL
- 1 RADIATOR GRILLE
- 1 RADIATOR GRILLE BADGE 'RENAULT'
- 1 RADIATOR GRILLE FRAME
- 1 FRAME FULL SUPPORT PANEL
- 1 FRAME FULL SUPPORT BRACKET
- 1 BONNET
- 1 BONNET INSULATOR
- 1 BONNET STRUT LH
- 1 BONNET HINGE LH
- 1 BONNET LOCK
- 1 SUBFRAME OUTER FRNT
- 1 SUBFRAME BRACKET OUTER LH
- 1 DOOR PANEL REAR LH
- 1 DOOR GUIDE REAR LH
- 1 DOOR HINGE UPPER REAR LH L70Y
- 1 DOOR HINGE LOWER REAR LH L70Y
- 1 DOOR CHECK REAR LH
- 1 DOOR REGULATOR REAR LH L70Y
- 1 DOOR REGULATOR MOTOR REAR LH L70Y

\$	<i>Bz</i>	414.40	✓
\$	<i>Zn</i>	112.30	✓
\$	<i>Mr</i>	11.80	✓
\$	<i>SL</i>	65.50	X
\$	<i>n</i>	38.90	X
\$	<i>n</i>	858.30	X
\$	<i>CM</i>	747.20	✓
\$	<i>CM</i>	101.40	✓
\$	<i>DI</i>	344.70	✓
\$	<i>CM</i>	394.68	✓
\$	<i>SL</i>	10.70	X
\$	<i>SL</i>	292.50	X
\$	<i>SL</i>	147.00	X
\$	<i>SL</i>	207.21	X
\$	<i>n</i>	663.70	X
\$	<i>My Bz</i>	743.60	✓
\$	<i>n</i>	127.70	X
\$	<i>n</i>	177.22	X
\$	<i>SL</i>	969.90	X
\$	<i>SL</i>	225.36	X
\$	<i>SL</i>	686.00	X
\$	<i>SL</i>	592.70	X
\$	<i>n</i>	41.60	X
\$	<i>Bz</i>	1,312.70	✓
\$	<i>SL</i>	294.30	} X
\$	<i>SL</i>	53.30	
\$	<i>n</i>	236.50	
\$	<i>n</i>	152.80	
\$	<i>SL</i>	1,094.20	
\$	<i>SL</i>	49.00	
\$	<i>n</i>	758.70	
\$	<i>SL</i>	136.40	
\$	<i>n</i>	180.70	
\$	<i>n</i>	169.90	
\$	<i>SL</i>	114.90	
\$	<i>SL</i>	657.10	
\$	<i>SL</i>	450.60	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A**AAD2003-014**

1	DOOR HANDLE OUTER REAR LH L70Y	\$	SL	42.10	}	X
1	DOOR HANDLE CAP REAR LH L70Y	\$	SL	57.90		
1	DOOR HANDLE MODULE REAR LH L70Y	\$	SL	133.40		
1	DOOR SEAL REAR LH	\$	SL	119.40		
1	DOOR WHEATHERSTRIP REAR LH	\$	SL	240.50		
1	DOOR LOCK REAR LH L70Y	\$	SL	468.20		
1	FENDER PANEL REAR LH	\$	SL	1,933.20		
1	FENDER PANEL INNER TRIM REAR LH	\$	SL	671.45		
1	WHEELARCH REAR LH	\$	SL	181.60		
1	AIR CLEANER BOX	\$	SL	464.20		
1	AIR CLEANER HOSE	\$	SL	175.85	}	✓
1	AIR CLEANER LOWER	\$	CM	271.26		
1	LOWER ARM LH L70Y	\$		192.70	}	X SVC
1	KNUCKLE ARM LH L70Y	\$	B	481.50		
1	KNUCKLE HUB+BEARING LH/RH	\$	SL	272.30	}	✓
1	ABSORBER FRT LH L70Y	\$		274.10		
1	ABSORBER MOUNTING KIT	\$		273.60	}	X
1	ABSORBER DUST COVER	\$	SL	52.40		
1	DRIVESHAFT LH	\$		1,355.70	}	X
1	FRT STABILIZER BAR	\$	SL	427.90		
1	STABILIZER LINK FRT	\$		69.50	}	X SVC
1	INJECTION COMPUTER	\$		2,706.30		
1	AUTO COMPUTER	\$		1,287.30		
1	STEERING PUMP ELECTRIC	\$		2,026.70		
1	STEERING PINION RACK	\$		3,765.30		

TOTAL	\$	46,008.77
10%	\$	4,600.88
	\$	41,407.90

Special Nett

1	FRONT DOOR STICKER 'Trans-Cab'	\$	SL	80.00	60SL
1	FRONT DOOR STICKER 'Classic'	\$	SL	80.00	15SL
1	REAR DOOR STICKER '6555-3333'	\$	SL	100.00	60SL
1	LH SIDE RENAULT TYRE 215/60/16	\$	SL	300.00	80SL
1	LH SIDE RENAULT TYRE RIM	\$	SL	380.00	✓
1	LH SIDE RENAULT TYRE RIM COVER	\$	SL	60.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A**AAD2003-014**

1 WHEELARCH CLIP FRT LH	\$	30.50	✓
1 FRONT WINDSCREEN MOULDING	\$	160.00	} X
2 WINDSCREEN SEALANT	\$	120.00	
1 FRONT WINDSCREEN INNER SPONGE SEAL	\$	100.00	
1 DOOR CHECK BOLT	\$	10.20	
1 DOOR CHECK NUT	\$	10.20	
1 DOOR GUIDE SCREW	\$	10.85	
1 DOOR HINGE BOLT	\$	10.85	
1 DOOR HINGE NUT LH	\$	7.20	
1 DOOR LOCK SCREW L70Y	\$	3.60	}
1 DOOR SEAL CLIP LH	\$	4.90	
1 BUMPER CLIP FRT	\$	66.00	✓
1 BUMPER BRACKET CLIP FRT LH	\$	12.00	} X
1 BUMPER SUPPORT CLIP FRT LH	\$	10.50	
1 BUMPER GRILLE LOWER CLIP	\$	69.00	
1 FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
1SET FRAME FULL SUPPORT PANEL NUT	\$	20.00	
2 FRAME FULL SUPPORT PANEL STUD	\$	30.00	
1SET RADIATOR GRILLE SCREW	\$	16.00	
1SET RADIATOR GRILLE FRAME CLIP	\$	52.00	
1SET Front licence plate with holder	\$	80.00	}
1 FENDER INNER TRIM CLIP LH	\$	28.00	
1SET FENDER WHEELARCH REAR LH CLIP	\$	35.00	
TOTAL	\$	1,956.81	

TOTAL PARTS \$ 43,364.70**LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 7,500.00 *600*

To check steering geometry and computer wheel alignment

\$ 220.00 *60*

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ 380.00 *X*

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A**AAD2003-014**

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	X
To rust-proofing of the affected areas.	\$		170.00	601
Putty and spray painting of the affected portion.	\$		7,500.00	<i>11001</i>
To transfer of tire, rim and on wheel balancing.	\$		170.00	<i>201</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
To transfer of Front door fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
Towing Fees	\$		150.00	<i>501</i>
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i>	170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>nn</i>	380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$		380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	<i>nn</i>	380.00	X
To transfer of front bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X

Trans-cab Auto Services Pte Ltd**AAD2003-014**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5831A

To transfer of front bonnet fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X*

To dismantle and refit engine cross-member and engine mounting.

\$ *4* 380.00 *X*

To remove and renew power steering pump, oil cooler pipe and final checking and testing.

\$ *4* 440.00 *X***TOTAL \$ 19,620.00****Over All Total \$ 62,984.70****LUMP SUM (REPAIR DAY)****~~25~~ DAYS***5 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: