



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20003566/Bpa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 17-08-2020



ATTN:RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SCM 7602M	Veh. Inspected	SLL 1698A
Policy No.	GA291616	Coverage (\$)	0.00
Claim No.	S0M02HU3	Excess (\$)	0.00
Assign From		Assign Date	04/03/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA HARRIER	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZSU600074795	Colour	RED
Odometer	66990	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/60 R18	BRIDGESTONE	7 mm
L/H Front Tyre	225/60 R18	BRIDGESTONE	7 mm
R/H Rear Tyre	225/60 R18	BRIDGESTONE	7 mm
L/H Rear Tyre	225/60 R18	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	29/02/2020	Inspection Date	04/03/2020
Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------