



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

DATE: 10/06/2020

Survey Details:

Date of loss	29.02.2020
Date of appointment	04.03.2020
Date of survey	04.03.2020
Location of survey	TEAM AUTOPRO PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLL1698A
Make and Model	Toyota Harrier (1986cc)
Date of registration	06.04.2017
Excess	
Market Value/ Book Value	\$ 93,000.00 (est)
Parf/COE Rebate	\$ 60,967.00 (est)
Nett Value/ ERV	\$ 32,033.00 (est)

Repair details:

Initial Estimate	\$ 6,418.08
------------------	-------------

Proposed/Revised repair cost:

Parts	\$ 1,822.37
Check items (estimate)	NIL
Labour	\$ 630.00
Supplementary	NIL
Total	\$ 2,452.37
Lump Sum(if applicable)	\$ 1,950.00

Number of days for repair	<u>4</u>
---------------------------	----------



Remarks:

Of rear-ended third party.

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$ 2,086.50	\$ 2,086.50
Loss of use (6days x \$100)	\$ 600.00	NIL
Loss of rental (6days x \$150.00)(w/GST)	NIL	\$ 963.00
Loss of income	NIL	NIL
LTA/GIA search fees	\$ 7.45	\$ 7.45
Others	NIL	NIL
Proposed Total	\$ 2,693.95	\$ 3,056.95