



CARZ AUTO SERVICES PTE LTD

UEN/ GST 201409457D

1 Kaki Bukit Ave 6 #02-26/35 Autobay@Kaki Bukit Singapore 417883
Email: teric@carzauto.com.sg Tel: 6909 3080 (Teric) Fax: 6909 3081

Insurance Company: **India International Insurance Pte Ltd**

Address: 64 Cecil Street
#04/05 IOB Building
Singapore 049711

Telephone: 6347 6100

Make/ Model : TOYOTA ALTIS

Date: 3/3/2020

Chassis No : MR053ZEE106154758

Vehicle No: SJS 8319 K

Date/Time of Accident : 29/2/2020 01:45PM

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	DESCRIPTION (LIST PARTS)	QTY	LIST PRICE \$	PARTS DISCOUNT	FINAL PRICE \$
1	Front Left Fender <i>requir</i>	1	\$ 684.20	25%	\$ 513.15
2	Front Left Fender VVTI Emblem <i>re</i>	1	\$ 66.70	25%	\$ 50.03
3	Front Left Door <i>4</i>	1	\$ 1,170.40	25%	\$ 877.80
4	Front Left Door Lock <i>X</i>	1	\$ 599.50	25%	\$ 449.63
5	Front Left Door Hinge <i>X</i>	2	\$ 154.10	25%	\$ 115.58
6	Front Left Door Weatherstrip <i>re</i>	1	\$ 109.25	25%	\$ 81.94
7	Front Left Inner Door Weatherstrip <i>re X</i>	1	\$ 111.55	25%	\$ 83.66
8	Front Left Door Protector Garnish <i>de</i>	1	\$ 109.25	25%	\$ 81.94
9	Front Left Door Check <i>X</i>	1	\$ 146.05	25%	\$ 109.54
10	Front Left Door Side Step Cover Garnish <i>X</i>	1	\$ 129.95	25%	\$ 97.46
11	Front Left Door Power Window Motor <i>?</i>	1	\$ 621.50	25%	\$ 466.13
12	Front Left Door Power Window Regulator <i>?</i>	1	\$ 249.55	25%	\$ 187.16
13	Front Left Door Power Window Channel <i>X</i>	1	\$ 155.25	25%	\$ 116.44
14	Front Left Door Glass Moulding <i>re</i>	1	\$ 97.75	25%	\$ 73.31
15	Front Left Door Inner Trim Board <i>?</i>	1	\$ 1,072.50	25%	\$ 804.38
16	Front Left Centre Pillar <i>re</i>	1	\$ 412.50	25%	\$ 309.38
17	Front Left Rocher Panel <i>?</i>	1	\$ 621.50	25%	\$ 466.13
18	Front Left Side Skirt <i>sc</i>	1	\$ 599.50	25%	\$ 449.63
19	Rear Left Door <i>st</i>	1	\$ 1,072.50	25%	\$ 804.38
20	Rear Left Door Lock <i>X</i>	1	\$ 632.50	25%	\$ 474.38
21	Rear Left Door Hinges <i>Top-X/bottom-?</i>	2	\$ 154.10	25%	\$ 115.58
22	Rear Left Door Check <i>X</i>	1	\$ 146.05	25%	\$ 109.54
23	Rear Left Door Weatherstrip <i>re</i>	1	\$ 120.75	25%	\$ 90.56
24	Rear Left Door Glass Moulding <i>re</i>	1	\$ 111.55	25%	\$ 83.66
25	Rear Left Door Protector Garnish <i>re</i>	1	\$ 109.25	25%	\$ 81.94
26	Rear Left Door Side Step Cover Garnish <i>X</i>	1	\$ 129.95	25%	\$ 97.46
27	Rear Left Door Inner Trim Board <i>?</i>	1	\$ 1,072.50	25%	\$ 804.38
28	Rear Left Door Power Window Motor <i>X</i>	1	\$ 621.50	25%	\$ 466.13
29	Rear Left Door Power Window Channel <i>X</i>	1	\$ 155.25	25%	\$ 116.44

30	Rear Left Door Power Window Regulator X	1	\$ 249.55	25%	\$ 187.16
TOTAL LIST COST PRICE & AFTER DISCOUNT					\$ 8,764.84

SPECIAL NETT ITEM

SPECIAL ITEMS	DESCRIPTION (SPECIAL NETT PARTS)	QTY	PRICE \$		FINAL PRICE \$
3	Front Left Door Inner Trim Board Clips <i>re ✓</i>	12	\$ 60.00		\$ 40 60.00
4	Rear Left Door Inner Trim Board Clips <i>re ✓</i>	12	\$ 60.00		\$ 40 60.00
TOTAL SPECIAL NETT ITEM					\$ 120.00

Labour Works / Panel Beating Related Works

Job Scope	Quotation
TO REMOVE AND RENEW DAMAGED PARTS: REPLACE REALIGNED ALL AFFECTED PARTS	\$ 700 1,200.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 800 1,000.00

Labour Works

Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 80 150.00
TO REMOVE/ REFIX INTERIOR UPHOLSTERY	\$ 60 100.00
TO REMOVE/ REFIX WIRING CHECKS	\$ 40 60.00
TO REMOVE/ REPLACE DOOR MECHANISM	\$ 60 100.00
TO COMPUTERISED FOUR WHEEL ALIGNMENT	\$ 60 80.00
OTHER LABOUR COST	\$ 490.00

GRAND TOTAL \$ 11,574.84

CARZ AUTO SERVICES PTE LTD

Person In charge: Mr Teric Chia
Job Title: Motor Claim / Admin
Tel: 6909 3080
Email: teric@carzauto.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
7 days
4/3
04/03/2020
@ 1250
Reg after repair
email: rasul@lkkauto.com