

Date: 03.03.2020
Vehicle No: SMP4555B
Model: HONDA FREED HYBRID 1.5
Chassis: GB71084369 - 2018
Reg.Year: 2019

Third Party Insurer: LONPAC
Third Party Veh No: XE1865D
Date of Accident: 01.03.2020

*Not Authorised
Resurvey B4 pain 5 days*

ESTIMATE

| NO. | DESCRIPTION | QTY | UNIT S\$ | AMOUNT S\$ |
|-------------|------------------------------------|-----|----------|-----------------|
| 1 | FRONT BUMPER | 1 | | CM \$837.50 ✓ |
| 2 | FRONT BUMPER SIDE BRACKET RH | 1 | | Di \$68.60 ✓ |
| 3 | FRONT BUMPER UPPER BRACKET RH | 1 | | \$57.20 7 ✓ |
| 4 | FRONT BUMPER CLIPS | 8 | \$5.50 | na \$44.00 ✓ |
| 5 | FRONT HEADLAMP RH | 1 | | GM \$1,948.60 ✓ |
| 6 | FRONT FENDER RH | 1 | | B2 \$594.00 ✓ |
| 7 | FRONT FENDER "HYBRID" EMBLEM RH | 1 | | na \$65.80 ✓ |
| 8 | FRONT FENDER INNER LINNER RH | 1 | | T1 \$138.00 ✓ |
| 9 | FRONT FENDER INNER LINNER CLIPS RH | 10 | \$5.50 | na \$55.00 ✓ |
| 10 | FRONT DOOR RH | 1 | | B2 \$1,180.00 ✓ |
| 11 | FRONT DOOR INNER TRIM CLIPS RH | 10 | \$6.80 | na \$68.00 X |
| 12 | FRONT BONNET | 1 | | REPAIR |
| 13 | FRONT DOOR SIDE MIRROR COVER RH | 1 | | REPAIR |
| 14 | FRONT SUPPORT PANEL | 1 | | REPAIR |
| SUB TOTAL | | | | \$5,056.70 |
| LESS 20% | | | | -\$1,011.34 |
| PARTS TOTAL | | | | \$4,045.36 |

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST FRONT ACCIDENT ARE \$600.00 *500*

LABOUR CHARGES TO REMOVE, REINSTALLED FRONT DOOR INNER MECHANISM & ETC. TO EFFECT REPLACE OF FRONT DOOR RH & ETC. \$120.00 *60*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRON BONNET, FRONT BUMPER, FRONT FENDER RH, FRONT SUPPORT PANEL, FRONT DOOR RH & ETC. \$1,000.00 *600*

LABOUR CHARGES TO CHECK WIRING & DOOR CENTRAL LOCKING SYSTEM & ETC BACK TO ORIGINAL OPERATIONS. \$80.00 *20*

TO WHEEL ALIGNMENT & BALANCING. *na* \$60.00 *X*

TO TOWING CHARGES *Bill* \$100.00 *50*

TO TOFF KOTE & UNDERSEAL MATERIAL \$150.00 *60*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

LABOUR TOTAL \$2,110.00

ONG

Acknowledged by Repairer
Signature:
Date:

TOTAL \$6,155.36

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

452 Tagore Industrial Avenue Singapore 787823
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

