

RALLY PITSTOP

176 Sin Ming Drive
 #04-17 Sin Ming Autocare
 Singapore 575721
 Tel: 64516985
 Email: tar6985@hotmail.com

Date: 02/03/2020

To: Motor Claims Department
 AIG Insurance

RE: Estimate repair cost of SKG3398R

Your Insured: SKF7887A

Dear Sir/Madam,
 Vehicle No: SKG3398R
 Make Model: Mazda / 6
 Date of accident: 29/02/2020

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Qty	Description	Unit Price	TOTAL	
1	Bonnet	1068.00	1297.40	DDV
1	Bonnet lower lock		123.90	?NDX
1	Front bumper	830.00	895.30	BRV
1	Front bumper retainer (LH)		48.90	NECV
2	Head lamps	987.90	1975.80	?CRAV
1	Front bumper grille		345.20	BRV
2	Front bumper chrome moulding	189.10	378.20	BRV
1	Front bumper logo		89.80	MISV
1	Front numbers plate		40.00	BTV
1	Front bumper reinforcement		-590.20	?NDX
1	Front bumper sponge		88.20	?BRV
1	Front radiator support panel		564.30	?BRV
10	Front bumper clips	3.00	30.00	NECV
1	Front parking camera		560.90	?NDX
1	Bootlid		879.10	DDV
1	Bootlid outer chrome moulding		230.70	BRV
1	MAZDA 6 ' emblem		56.90	NECV
1	Bootlid lamp (LH)		458.20	?CRAV
1	Tail-lamp (LH)		542.10	?CRAV
1	Rear bumper		879.80	BRV
2	Rear parking sensors	239.90	479.80	CUTV
2	Towing cover	33.70	67.40	MISV
1	Rear bumper retainer (LH)		46.90	NECV
1	Rear reinforcement		590.20	?BTV
1	Rear end panel		564.20	?DDV
1	Weather-stripe		178.90	?NDX
1	Rear end panel inner garnish		98.50	?BTV
	Sub-total before discount	9844.30	12231.00	
	Parts percentage discount 20%	1968.80	2446.20	
	PARTS TOTAL		9784.80	
		7875.44		
	LABOUR CHARGES & MISC			
1	Labour to dismantle and change all damaged parts		2000.00	NECV
2	To putty and spray paint		1500.00	BTV
3	To do undercoating		80.00	
4	To check wiring		60.00	
		2680.00		

GIA

	LABOUR TOTAL		3640.00
	LABOUR & PARTS TOTAL		13424.80

Regards,
Terrence Lim

Survey 3/3/2020
Terrence Lim 97361577
Lump sum repair

Parts 7875.44
S/N —
Labour 2680.00

10555.44
@ 20% 2111.09

8444.35

45 8450/2

Terrence Lim
12/3/2020

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: