

22/03/2020

ASS. REC. BY:

REF: CS3/ III 20003581/ Etf3-1

Special Instruction:

Surveyor: ASSIGNMENT (Office)

From (Person): Derrick Tan

of III

Date/Time:

Monday, 1 June, 2020 3:09 PM

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJA 2261H

Insured:

SJA 7773G

at Workshop m/s A - TEC Automotive

Tel:

63845206

of 8 Kaki Bukit Ave 4 #04-20 Premier

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23.2020

CA / REV / REP. / REV 24 HRS

40'

H.O.D. Endorsement:

Date/Time: 4/3/200 5.40 p.m

Person Contacted:

Peggy

Vehicle IN/OUT

Date/Time	Action/Instruction ( X ) Estimate
	SJA 2261H - NA / AIG 20003581/24 ROA - 02/02/2020
	SJA 7773G - NA / AIG 20003581/24 ROA - 02/02/2020
	Submit PRS Report
	Dismantle part : 05/03/2020 03.26 PM
	After repair : 09/03/2020 04.39 PM

various

H-ANN

III

PRS

ASSIGNMENT

Veh No: STN 22614 Reg: 09/20/2009  
Type: Car / IM Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda Fit C.C. 1339  
Colour: white A/C: Insured / Std / NI / NA  
Sp. Resaling: 356189 T/Kodis: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
C/No: GE61/30600

Gen. Cond: Good / Fair / Poor / Burnt  
Steering: Order / Jammed / Leaked / Burnt or  
Brake: Order / Jammed / Leaked / Burnt or  
Mod: Nil / S/Rim / STD A/Rim or

Type Size: F: 195/55/15  
R: 195/65/15  
BS / DUN / EXANOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: R/Bal: 6 R/Bal: 5 Fellon mm  
L/Bal: 6 L/Bal: 5 mm  
D.O.A: 2/3/20 D.O.I: 4/3/20  
Survey field at: A-Ten QUATPM  
Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooflop or

The UIC / Chassis frame / Body Structure allocated due to collision.

Date / Time	Action / Instruction	Vehicle: IN / OUT
	<u>refer to 2.5-3.5/16</u>	
	<u>refer days to 3 day</u>	
	<u>6/3/2020</u>	
	<u>MV - 23000</u>	
	<u>PV - 10078</u>	
	<u>IVV - 17906</u>	

Date/Time, File Pass 1/2:  Prelt. Report  
1) 19/3 Typist  Final Report  
Date/Time, File Return 1/2: \_\_\_\_\_

Add'l Fee:	Site Insp	Int'view	Tech. Insp	Material

Report Formed: PRS

Group 2000 / UIC: \_\_\_\_\_

Survey Fee:	Transport:	Phone:	Others:
<u>120</u>			

5/6/20 5767 J

Front: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: STN 22614  
at Workshop no: A-Ten  
of: Pulvis Bent 4 #04-20

Insured: \_\_\_\_\_  
Policy No: \_\_\_\_\_  
Claims No: \_\_\_\_\_  
Sum Insured: \_\_\_\_\_  
Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

Est. of Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

RECEIVED 10 MAR 2020