

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

Not Authorized
d/s 2600
4 hrs

VEHICLE NO: SGD 6683K

QTY	PARTICULAR
1 PCS	REAR WINDSCREEN MOULDING
1 PCS	TAILGATE
1 PCS	TAILGATE REAR LOGO
1 PCS	TAILGATE 'COLT' EMBLEM
1 PCS	TAILGATE 'PLUS' EMBLEM
1 PCS	TAILGATE C&C LOGO
1 PCS	TAILGATE WEATHERSTRIP
1 PCS	TAILGATE INNER LOCK
1 PCS	REAR BUMPER
2 PCS	REAR BUMPER SIDE RETAINERS @ \$45.00
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER REFLECTOR N/S 38.00
1 PCS	REAR END PANEL 445.00
1 PCS	REAR END PANEL TOP GARNISH 112.00
1 PCS	TAILLAMP N/S

11	\$118.00 X
12	\$981.00 X
11	\$45.00
11	\$48.00
11	\$42.00
11	\$45.00
11	\$191.00
11	\$166.00 X
11	\$745.00
11	\$90.00 X
11	\$50.00
11	\$68.00
11	\$605.00
11	\$185.00
11	\$485.00 X
	\$3,864.00

11	\$50.00 X
11	\$280.00 200
11	\$50.00

1 PCS	S.NETT
1 PCS	REAR WINDSCREEN SEALANT
1 SET	REAR BUMPER REVERSE SENSOR
1 PCS	REAR END PANEL SEALANT

LABOUR CHARGES
TO CHECK WIRING
TO DISMANTLE & REPLACING REVERSE SENSOR
TO DISMANTLE & REFIX REAR WINDSCREEN
TO DISMANTLE & REFIX CUSHION UPHOLSTREY
TO SPRAY RUST PROOFING
LABOUR FOR PANEL BEATING & REPLACING PARTS
TO PUTTY & SPRAY PAINTING

	\$50.00 20
	\$80.00 50
11	\$150.00 X
	\$120.00 80
	\$100.00 30
	\$880.00 600
	\$1,500.00 800
TOTAL	\$7,124.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

7-1708
182
15372
336720
202
2693