

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 31693

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0244/2020/NS
Date	:	5-Mar-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SJQ 8138 B

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Phng Kar Soon
Address	:	Blk 377 Clementi Avenue 5 #12-326 Singapore 120377
Telephone	:	(HP) +65 98397755
Type of Claim	:	Third Party Claims
Policy No.	:	
Vehicle No	:	SLZ 1071 J
Model Code	:	Audi A3 Sedan 1.0 TFSI 8V
Model / Year	:	23/4/2018
Engine No	:	CHZ 905062
Chassis No	:	WAUZZZ8V2J1056287
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	4-Mar-20
Place of Accident	:	PIE Towards Changi Outside Old Police Academy

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SLZ 1071 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To dismantle front bumper and bonnet. To renew bonnet. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00 1000	
3	To respray bonnet.	\$ 1,000.00 550	
4	To carry out diagnostic check.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 3,652.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 1071]

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	RADIATOR GRILLE <i>culd</i>	\$ 1,338.00	✓
2	RADIATOR GRILLE - CLOSING ELEMENT <i>new</i>	\$ 180.00	+
3	AIRCON STICKER <i>2m</i>	NEC \$ 7.00	✓
4	CAUTION SIGN STICKER	NEC \$ 13.00	✓
5	BONNET <i>rented</i>	\$ 2,988.00	✓
6	BONNET ATTACHMENT PARTS <i>?</i>	\$ 155.00	?
7	BONNET EDGE PROTECTION <i>new</i>	\$ 26.00	+
8	FRONT NO PLATE <i>rented</i>	S/N \$ 60.00	✓
9	SUNDRIES <i>?</i>	\$ 200.00	?
TOTAL SPARE PARTS		: \$ 4,967.00	
TOTAL LABOUR CHARGES		: \$ 3,652.00	
GRAND TOTAL		: \$ 8,619.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian 
Surveyed Date : 12/03/20.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant