

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: [Nora.khai@premiumauto.com.sg](mailto:Nora.khai@premiumauto.com.sg) / [claims@premiumauto.com.sg](mailto:claims@premiumauto.com.sg)

**WIP : 31693**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0244/2020/NS  
**Date** : 5-Mar-20

**Vehicle NOT IN workshop. Please arrange for survey.**

**Your insured veh no : SJQ 8138 B**

### **AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Phng Kar Soon  
**Address** : Blk 377 Clementi Avenue 5  
#12-326  
Singapore 120377  
**Telephone** : (HP) +65 98397755  
**Type of Claim** : Third Party Claims  
**Policy No.** :  
**Vehicle No** : **SLZ 1071 J**  
**Model Code** : Audi A3 Sedan 1.0 TFSI 8V  
**Model / Year** : 23/4/2018  
**Engine No** : CHZ 905062  
**Chassis No** : WAUZZZ8V2J1056287  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 4-Mar-20  
**Place of Accident** : PIE Towards Changi Outside Old Police Academy

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SLZ 1071 J

<b>S/n</b>	<b>Nature of Jobs</b>	<b>Estimated Charges</b>	<b>Surveyor's Recommendations</b>
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	
2	To dismantle front bumper and bonnet. To renew bonnet. Re-organise crash management components. Reinstall all parts removed.	\$ 2,100.00	
3	To respray bonnet.	\$ 1,000.00	
4	To carry out diagnostic check.	S/N \$ 192.00	
<b>TOTAL LABOUR CHARGES</b>		<b>: <u>\$ 3,652.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SLZ 1071 J

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	RADIATOR GRILLE	\$	1,338.00
2	RADIATOR GRILLE - CLOSING ELEMENT	\$	180.00
3	AIRCON STICKER	NEC \$	7.00
4	CAUTION SIGN STICKER	NEC \$	13.00
5	BONNET	\$	2,988.00
6	BONNET ATTACHMENT PARTS	\$	155.00
7	BONNET EDGE PROTECTION	\$	26.00
8	FRONT NO PLATE	S/N \$	60.00
9	SUNDRIES	\$	200.00
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 4,967.00</b>
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 3,652.00</b>
<b>GRAND TOTAL</b>		<b>:</b>	<b>\$ 8,619.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant