

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

23/03 9:10-12pm
Survey & repair



GST REG. NO : M2 - 0020081 - X

04 MAR 2020

ESTIMATE

Estimate No. : b1 54670
Date Estimated : 04/03/2020
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Yvonne Heng Wan Shang
101 Huddington Ave

Singapore 557656

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMP8654Y	WBATR12030LS31265	18/10/2019	X3 sDrive20i	0

DESCRIPTION

To replace rear bumper, rear right wheel arch trim and repair rear right fender.

2125 3,400.00

Painting rear right fender, rear bumper and rear right wheel arch trim.

2063 2,293.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To remove and install rear hat-tray, rear seat, carpet and roof top lining to facilitate repairs.

~~(med take photo)~~ 873.00 X

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To replace tyre and wheel rim including balancing. (1x).

80 94.00

To check steering geometry and conduct wheel alignment according to BMW specification (1X)

451 531.00

Sundries.

80 ✓ ? 150.00

Total Labour 1: 7,695.00

DESCRIPTION

Disk wheel, (Rear R/L) - CUT
RH BUMPER GUIDE * R ? X NN
REAR BUMPER PANEL PRIMED (M/PMA) X R
EXPANDING RIVET BLACK / MC
RR RH WHEEL ARCH TRIM PRIMED (M) / CUT

QTY	PRIC	VALUE
1	1,457.45	1,457.45
1	70.30	70.30
1	1,555.40	1,555.40
10	1.40	14.00
1	281.35	281.35

1,603.20

Total Parts : 3,378.50