

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5861M**AAD2003-025***Not Authored
C/Snp @ 2850/-*

Vehicle No.: 04 MAR 2020
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration :

SHC 5861M

VF1ABL15AUC280930

RENAULT

LATITUDE

2.3.2020

III

11/12/2014

PART		LIST	
1	BUMPER COVER REAR	\$ <i>BL</i> 561.70	—
1	BUMPER LOWER REAR	\$ <i>Not ID'd</i> 411.90	—
1	BUMPER BRACKET CTR REAR	\$ <i>SL</i> 98.10	X
1	BUMPER BRACKET SIDE RH REAR	\$ <i>SL</i> 82.10	X
1	BUMPER RETAINER RH REAR	\$ <i>SL</i> 59.80	X
1	BUMPER REFLECTOR RH	\$ <i>SL</i> 16.60	X
1	BUMPER BRACKET SIDE LH REAR	\$ <i>SL</i> 80.80	X
1	BUMPER RETAINER LH REAR	\$ <i>SL</i> 54.20	X
1	BUMPER REFLECTOR LH	\$ <i>SL</i> 16.60	X
1	BUMPER BEAM REAR	\$ <i>BZ</i> 547.80	✓
1	BUMPER BEAM BRACKET LH REAR	\$ <i>K</i> 114.50	X
1	BUMPER BEAM BRACKET RH REAR	\$ <i>Dis</i> 100.90	—
1	OUTER PANEL REAR (End Panel)	\$ <i>BZ</i> 745.80	—
1	OUTER PANEL REAR (End Panel) TRIM	\$ <i>SL</i> 404.56	} X
1	TAILLAMP RH	\$ <i>SL</i> 401.40	
1	TAILLAMP PANEL RH	\$ <i>N</i> 401.40	
1	TAILLAMP LH	\$ <i>SL</i> 401.40	
1	TAILLAMP PANEL LH	\$ <i>N</i> 401.40	
1	BOOT REAR	\$ <i>N</i> 1,677.20	
1	BOOT FINISHER	\$ <i>SL</i> 344.70	
1	BOOT WHEATERSTRIP	\$ <i>SL</i> 178.20	
1	BOOT REFLECTOR LAMP LH	\$ <i>SL</i> 277.70	}
1	BOOT REFLECTOR LAMP RH	\$ <i>SL</i> 277.70	
1	BOOT BADGE 'RENAULT'	\$ <i>nn</i> 82.40	
1	BOOT BADGE	\$ <i>nn</i> 95.80	

Trans-cab Auto Services Pte Ltd**AAD2003-025**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5861M

1	BOOT STRUT LH	\$	Su	145.10	}	X
1	BOOT STRUT RH	\$	Su	145.10		
1	BOOT HINGE LH	\$	N	254.20		
1	BOOT HINGE RH	\$	N	253.80		
2	BOOT RUBBER PLUG	\$	Su	139.90		
2	LICENCE PLATE LAMP	\$	Su	26.30		
1	BOOT LOCK LINKAGE HOLDER	\$	Su	99.50		
1	BOOT INNER TRIM BOARD	\$	Su	611.00		
1	BOOT LOCK	\$	N	246.60		
1	BOOT SWITCH	\$	Su	113.00		
1	SPARE TYRE BOARD L70Y	\$	Su	680.90		
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	1,229.40		
1	SPARE WHEEL PANEL TRIM	\$	Su	612.21		
1	EXHAUST REAR	\$	N	5,263.60		
1	EXHAUST CAP REAR	\$	Su	125.40		
1	KNUCKLE ARM REAR LH	\$	Su	472.10		
1	KNUCKLE HUB+ BEARING LH/RH	\$	Su	272.30		
1	REAR AXLE	\$	Su	3,469.00		
1	LOWER ARM REAR LH	\$	Su	543.50		
1	AXLE SPRING ARM LH	\$	Su	220.60		
1	ABSORBER REAR	\$	Su	217.30		
1	STABILIZER BAR REAR	\$	Su	427.90		
1	STABILIZER LINK REAR	\$	Su	55.20		
1	SUBFRAME ARM REAR	\$	Su	198.33		
1	RODE- LONG REAR	\$	Su	120.16		
TOTAL		\$		23,777.06		
10%		\$		2,377.71		
		\$		21,399.35		

Special Nett

1SET	PARKING AID	\$	Su	700.00	X
1SET	REAR BUMPER CLIP	\$	N	66.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	N	33.00	✓

Trans-cab Auto Services Pte Ltd**AAD2003-025**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5861M

1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
1 BOOT STICKER "Trans-cab"	\$	na	35.00	} X
1 BOOT STICKER "6555-3333"	\$	na	35.00	
2 REAR WINDSCREEN SEALANT	\$	na	100.00	
1 WINDSCREEN MOULDING	\$	na	150.00	
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
1 BOOT INNER TRIM CLIP	\$	na	45.00	
1SET BOOT FINISHER CLIP	\$	na	24.20	} X
1 TAILLAMP CLIP RH	\$	na	5.00	
1 TAILLAMP CLIP LH	\$	na	5.00	
1 Rear Bumper Protector	\$	na	100.00	300.00
1 REAR LEFT TYRE	\$	na	330.00	} X
1 REAR LEFT TYRE RIM	\$	na	385.00	
1 EXHAUST MOUNTING REAR	\$	na	16.00	
1SET Rear licence plate with holder	\$	na	100.00	
1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na	385.00	
1 SPARE TYRE	\$	na	330.00	
TOTAL	\$		3,092.20	

TOTAL PARTS \$ 24,491.55**LABOUR**

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 170.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 7,500.00 6000

Trans-cab Auto Services Pte Ltd**AAD2003-025**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5861M

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	601
To check steering geometry and computer wheel alignment	\$	220.00	nr X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	↪ X
To transfer of tire, rim and on wheel balancing.	\$	170.00	↪ X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	170.00	↪ X
To Rust-Proofing Of The Affected Areas.	\$	170.00	301
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	↪ X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	↪ X
To Check Electrical Lighting Concerned.	\$	170.00	201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	↪ X
To reinstall rear bumper parking sensor.	\$	170.00	601
To check ABS and brake efficiency, final checking and testing.	\$	380.00	↪ X

Trans-cab Auto Services Pte Ltd**AAD2003-025**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5861M

To dismantle and refit rear undercarriage parts, final checking and testing.	\$	<i>na</i> 380.00	<i>X</i>
Putty and spray painting of the affected portion.	\$	7,500.00	<i>4401</i>
To repair and realign rear exhaust pipe.	\$	<i>4</i> 170.00	<i>X</i>
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	<i>4</i> 380.00	<i>X</i>
Towing Fees	\$	<i>4</i> 150.00	<i>X</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>4</i> 380.00	<i>X</i>
TOTAL	\$	19,350.00	
Over All Total	\$	43,841.55	

LUMP SUM (REPAIR DAY)**~~25~~ DAYS***4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: