

Estimate

PRO-JEX V2D MOTOR PTE LTD

Reg. No.: 201600429G

SYNERGY @ KB

25 KAKI BUKIT ROAD 4 #03-94

SINGAPORE 417800

HOTLINE: 6100 7676

FAX : 6841 9698

Vehicle: FBC 374PS

Make & Model : KAWASAKI

Chassis no: _____

Qty	Parts / Labour	Cond	Part \$
1	FRT FENDER <i>cracked</i>	✓	185
2	—— forks @ 650 <i>NE M</i>	✗	1360
1	—— stem ? <i>NE M</i>	✗	285
1	—— bearing ? <i>NE M</i>	✗	80
1	RT FRT signal lamp <i>cracked</i>	✓	85
1	RT Hand bar <i>NE M</i>	✗	135
1	—— grip <i>NE M</i>	✗	38
1	—— balancer <i>ct</i>	✓	35
1	RT side mirror <i>ct</i>	✓	38
1	Faring (set) <i>ct</i>	600	1000
1	rear footrest <i>ct</i>	✓	75
1	—— bracket <i>cracked</i>	✓	195
1	rear swing arm <i>Bent</i>	✓	385
1	—— bushen (set) <i>NE</i>	50	100

Estimate

Vehicle: FRC 3748S

Make & Model: KAWASAKI
kips

Chassis no: _____

PRO-JEX V2D MOTOR PTE LTD

Reg. No.: 201600429G

SYNERGY @ KB

25 KAKI BUKIT ROAD 4 #03-94

25 NANKI DRIVE, #01-01
SINGAPORE 417800

HOTLINE: 6100 7676

FAX : 6841 9698

[illegible]

chassis alignment	200	350
spray paint (original to green)	200	400
labor	200	400

6896.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

L/S 04 Days

06/05/20

total 2227.20

25:1750