LEE HONG & CO MOTOR SERVICE

Blk 9 Sin Ming Road #01-36 Sin Ming Industrial Estate Singapore 575644.

T. (65) 6458 8460 F. (65) 6455 5379 E. leehong36@rocketmail.com

Date	26-Feb-2020	Ref.:	TP Claim		
			-		
	Owner Particulars				
Name	LEE KIT LING STEPHANIE				
# Nos	S8624401B	Mobile No.	90606598		
Address	BIK 482 PASIR RIS DR 4				
	#08-393				
	Singapore 510482				
	Vehicle Particulars				
Number	SMR3127A				
Model	HYUNDAI ELANTRA 1.6 AT ABS D/AB 2WD 4DR	RSR			
Engine	G4FGBU297913				
Chassis	KMHDH41CMCU238587				
Year	28-Jul-11				
. 50.					
	Accident Details				
Date	24 February, 2020				
Time	08.10 HRS				
Place	PASIR RIS DR 4 CAR PARK				
	Insured With				
Insurance	CHINA TAIPING INSURANCE (SINGAPORE) PT	FITD			
Policy No.	DMPCSNW00006142000				
Expiry	7 January, 2021				
<u> Е</u> хріі у	, sandary, 2021				
	Driver Particulars				
Name	AS ABOVE	Date of Birth			
Nric Nos.		Mobile No.			
Address					
	Parts & Labour Costs List Prices		ı		
			-		
	Nett Prices		-		
	Special Nett Prices		-		
	Labour Charges				
	COMMENTS	COMP	COMPANY STAMP		
1 This Fet	imate is based on visual Inspections of visible	_			
	es on the above vehicle.	-			
damaye	SO OTI GIO GEOVO VOTIIOIO.				
2. We will I	keep you informed if further damages are found.	_			
	The first manner of the first state of the found of the first state of				
3. This Es	timate is valid for 30 days only.				
		S	ignature		

QTY	DESCRIPTIONS	UNITS	A	MOUNTS	
рсе	Front bumper fascia / T/V		-	418.30	✓
pce	Front bumper n/s fog lamp \(\sum_{\text{SUR}} \),		-	365.40	220
pce	Front bumper n/s retainer X NN		-	18.80	
рсе	Front bumper energy absober X NN		-	110.70	
рсе	Front bumper reinforcement / NN		-	254.00	
рсе	Front bumper grille X NN		of the same of the	146.10	
рсе	N/s headlamp assy			673.30	\checkmark
1 pce	Radiator grille X NN			155.30	
			\$	2,141.90	1311.6
		Less 20%	\$	428.38	
			\$	1,713.52	1049.28
	Labour		ļ		
	To remove lamps, necessary wirings and				
	Electrical fittings to enable necessary		-		
	repairs.		· c	FO 00	0 00
	repairs.		\$	50.00	₹ 30
	To remove damaged parts, jack and straighten				
	o/s doors' centre pillar, cut up damaged body				na para para para para para para para pa
	panels and repair body parts and fittings, whichever				
	possible and necessary, replace and weld				warrigh, condition to
	necessary damaged parts, refit same.	Annua a comment	\$	360.00	200
	To spray painting replacement parts and	Temperature and the second and the s			
	repaint damaged sections with welded		1		
	portions in and outside, including putty.	rise and ris	\$	500.00	200
	To rust proofing	and the same of th	\$	100.00	× NN
	A 1200 S				1479.28
	. Man 1.		\$	2,723.52	-20%: 1150
	Como Qiomp - 8288 osta (0/2/2020.	the Renairer	sultant	hence notify	
	No. MINIT photos	the Repairer of the following: To resurvey before/after spray painting			
	Maria Company	Ottal prices are subject to confirmation Third party survey is on a "Without Broker back."			a.
	1 3. cm - 8288 0282				
	Omo Will	Supplementary	item/ei m	is allowed	:
	(0/2/2020.	is subject to fina	approva	ust be resurveyed and I from insurance Com	peny
	. 1 '/-	Acknowledged by			
		Signature; Date:			I

Vehicle#

SMR3127A

Estimate Cost Of Repairs