

K'S PERFORMANCE

Repair Estimates

Date: 4/3/20

Make & Model: Toyota Camry 2.0A

Vehicle Number: SKE 3507D

List Price 25%

No.	Description	Marking	Price
Rear			
1	Bumper (Rear) <i>de</i>		700 900
2	Rear Bumper Reflector N/S, O/S <i>cr</i>		180
3	Rear Boot Lid <i>bt</i>		800
4	Boot Lid Tail light N/S, O/S <i>cr</i>		440
5	Boot Lid Lock <i>bt</i>		180
6	Boot Lid Lock Cover <i>cr</i>		60
7	Number Plate Backing with Chrome Boot Garnish <i>bro</i>		320
8	Rear Number Plate Lamp <i>? cr</i>		120
9	Boot Lid Hinge (Pair) <i>bt</i>		160
10	Boot Lid Lining <i>de</i>		140
11	Boot Compartment Rubber seal <i>cr</i>		90
12	End Panel <i>bt</i>		380
13	Rear Lamp Panel N/s, O/S <i>bt</i>		410 410
14	Re-bumper Beam (Re-inforcement bar) <i>bt</i>		450 750
15	Rear Boot Lock Striker <i>bt</i>		110
16	Boot Compartment Side Lining (Left) <i>de</i>		290
17	Rear Taillight (Fender side) N/S, O/S <i>bro</i>		220
18	Boot Compartment Ventilation <i>de</i>		80
19	Spare Tyre Wheel Well <i>bro</i>		470
20	Rear Quarter Fender N/S <i>bro</i>		1520
21	Rear N/S Wheel well panel <i>bro</i>		380
22	Rear N/S wheel well lining <i>cr</i>		320
23	Rear Bumper Lower bracket panel N/S, O/S (Metal) <i>bt</i>		60
Front			
24	Bonnet <i>bt</i>		1100
25	Bonnet Hinge <i>bt</i>		180
26	Bonnet Lock <i>X</i>		190
27	Front Bumper <i>de</i>		850 1100
28	Front Grill (Upper) <i>cr</i>		450
29	Front bumper impact foam <i>? cr</i>		300
30	Headlamp N/S O/S (HID) <i>? cr</i>		2200
31	Front Support Panel <i>X</i>		330
32	Front Bumper Air Guide N/S O/S <i>de</i>		360
Total:			15090
10% Discount:			1509
Price			13581

8380
25%
6285

X 5440
25%
4080

L. parts - 6285.00
L. parts - 4080.00
L. parts - 675.00
S/N - 1170.00
Labour - 4580.00

T- 16,790.00
20%
13,432

4/3 - 13,400

18 days

K'S PERFORMANCE

Special Nett

1	Rear Bumper Clips	new	50	30
2	Rear Bumper Retainer N/S, O/S	new	160	80
3	Rear Bumper Reverse Sensor (1 Set)	new	220	
4	Rear Bumper Bracket N/S, O/S (Below Tail-light)	new	180	100
5	Rear Reverse Camera	7. SUR	300	250
6	"CAMRY" Logo	new	90	60
7	Toyota Logo	new	120	60
8	"2.0" Logo	new	30	
9	Boot Lid Lining Clip	new	30	
10	Number Plate (Front n Rear)	bt	80	70
11	Number Plate Frame (Front n Rear)	new	60	
12	Rear End Panel Plastic Garnish	de - List price	360	
13	Boot Compartment Side Storage	de - List price	220	
14	Front Bumper Clips (1 set)	new	60	40
15	Front Grill Clip (1 set)	new	40	
16	Front Number Plate Bracket	new	120	60
17	Front Bumper Retainer	new	160	100
18	Front Bumper Lower Slash Guard	new - list	320	230 - 240
19	Spare tyre	X	220	X
20	Rear N/S Tyre	X	220	X
Special Nett Total:			3040	

list - 675

Special Nett Total:

Total Parts Price:

16621

B:	Labour	Price
No.	Description	
1	Repair Rear N/S Chassis Main Frame using heavy impact repair tools, Heavy duty wrenches and puller, flame touch and others if nec.	800
2	To remove, repair, replace all damage body panels and garnishes, using heavy duty tools, and ensure all body panels are align	3800
3	To do electrical check on all electrical components which are replaced	60
4	To apply anti-rust coating on all affected panels	180
5	To supply spray painting to all affected panels, including rear n/s door, rear boot, rear bumper, rear quarter fenders, end panels, front bonnet front bumpers ect...	2200
6	To send for diagnostic check	220
Total:		7260

Posul
Hp 900110068

18 days

4S

Repair Cost (A+B): 23881

Lump Sum repair cost: 19104.8

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Prepared by: K'S PERFORMANCE

Acknowledged by Repairer

Signature:

05/03/2020 @ 1740
Resurvey after repair