Estimated Co.	of Gerald poh of Jpc Date/Time: 05/03/2020,
on fir w	STTP RESTOD RESTEVATING INVINVICS
To Inspect Ve	
at Workshop	
cď	110 -11111
Policy No:	Claim No: 19/19/20/V(00/022819
Sum Insured:	EXCESS.
Make of Veh- (Client's Record	THE PROPERTY OF THE PROPERTY O
The malesman	DEED ( Name of the Control of the Co
Date/Times	and and a light
LYMAN A HITE.	
Date/Time	Action/Instruction Tohrands (X Send report by 13/03/2020.
	BUE 68 215-X
	TYPFFAMIC-X . Original veturn LPC
	Submit PRS Report
Maries med in	\$1750 3Doms
	dillo i sissifi. I wholly.

RECEIVED 2 4 MAR 2020



Our Ref

: 19/19/20/VC00/022819

Your Ref

: CS3/LPC19022861/Gtd3s2

2 March 2020

M/s LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Pk Singapore 408933

Dear Sirs/Madam

#### PAPER SURVEY OF GBE6321J

We refer to the above matter.

We enclose the following documents :-

- a) Survey report & photos of GBE6321J
- b) GIA report GBE6321J
- c) GIA report and photos of YP7799C

Kindly study the documents and let us have your report by 13 March 2020.

Yours faithfully

GERALD POH

SENIOR EXECUTIVE

(CLAIMS)

Email: mt\_claim@lonpac.com

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available
  aforesaid.

	ACCIDENT STATEMENT
Date Of Report	23/12/2019 17:17
Date Of Accident	21/12/2019 23:30
Exact Location Of Accident	MANDAI ESTATE
Country/State of Loss	SINGAPORE

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number GBE6321J

Insured/Policyholder

Name Of Registered Owner TS ENGINEERING WORKS PTE LTD

Co Reg No 2XXXXX159K
Email Address NOEMAIL

Mobile Phone No

Alternative Phone No OFFICE-81508915

Vehicle Particulars

Manufacturer TOYOTA

Model DYNA 3.0 DIESEL TURBO M/T 2WD LORRY

Exact Purpose for which vehicle was being used at

time of accident

WORK

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 5113450539

Cover Note Number

Driver

 Name of Driver
 HASAN JAHED

 NRIC No
 GXXXX050T

 Date Of Birth
 15/02/1991

 Occupation
 OUTDOOR

 Date Of Driving Pass
 01/12/2016

Driving Experience 3 YEARS AND 0 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-88702888

Fax Number

Contact Number

EMail Address NOEMAIL

Address

В

Postcode

Was driver an employee of the Insured's Company YES

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

DRY Road Surface

Other Information

Was any foreign vehicle involved in this accident?

Number of vehicles (including own vehicle)

involved in the accident

NO

Was any body injured in the Accident?

NO

CLEAR

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

Refer to sketch plan.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

YP7799C

Vehicle Make/Model/Colour

MIT, FUSO

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ARUMUGAM RAMKUMAR

NRIC/Passport Number

GXXXX387W

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Plaise report correctly the details of the accident to speed up the claim, process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any aimst merepresentation or withholding of material tacts may allow insurance (empanies to reputilate policy liability.
- The torus and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the incurers of the GIA Records Management Centre at tablished by the General insurance Apportation of Singapore (GIA) for archiving and that cooles of the report will for a fee be made available upon application by interested parties
- J. By the lodgment of this report to the insurer, you hereby consent to the archiving of this report at the contrelland to copies of the report being made available aforesaid.
- S. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, act nowledge, agree and consent that:

- (a) My insurer my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to chillent, use, disclore and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my instruct (collectively the "Personal Information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) insulved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively returned to a cline "Insurers"), the insurers' lowyers/law times, the Monetary Authority of Singapore and any relevant government aconcy/authority (such as the police), for the purposets)
  - (ii) processing, handling and/or dealing with my claims including the sattlement of the claims and any necessary investigations relating to the clause.
  - (ii) investigating the accident and/or no +Films;
  - (iii) carrying out and/or dealing with my estructions or couper. In an any enquiries by met
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the
- (b) all incurer(s) who have issured vehicle(s) involved in this accident and the insurers' lawyers/law times, may/are permitted. to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law lims), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will riso be codected and used to compile claims history for the purpose of fried detection. investigation and management in present and all future chains.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud. regulators, law enforcement and government organizer as reasonably required for the purposes stated, or

lying with requirements under any regulations, laws or court orders

Date & Timo

Johed Driver's Signature

(if driver is not the policyholder)


Date & Time:

Reportion Contra Personnel's Signature

NEIC/FIR No:

SKETCH PLAN

A: GRE G3217 B: YP 7799C



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

CIT 21/12/2019 at about 11/30PM along Menselai Estate.

My valitate N (REREGSZIT) was provided at the side of the road.

Twas at my downthony steeping liven I received a call and said he hit my formy ask me ame out. I came out and saw velitate 18' (YPTTANC) stantal and collided oute my volitate A.

Vehicle B applagized Said thook he tuned out and left my long we Exchanged profitalises, and I informed my mornager.

No one were hyporical on the accident scene.

or driver is a distribution of another

MUCTINES

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT
Date Of Report	24/12/2019 10:20
Date Of Accident	21/12/2019 23:30
Exact Location Of Accident	ALONG MANDAI ESTATE
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	YP7799C
Insured/Policyholder	
Name Of Registered Owner	LENG WEE CONSTRUCTION PTE LTD
Co Reg No	201116058N
Email Address	PEILING.KWOK@LENGWEE.COM
Mobile Phone No	(LOCAL) +65-88797837
Alternative Phone No	OFFICE-67342378
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	CANTER-3.0 D FEB21ER4SDEB (CBU) (M)
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/19ZVC00/105364
Cover Note Number	14/11/2019 - 13/11/2020
Driver	

Driver

ARUMUGAM RAMKUMAR Name of Driver

Passport No/FIN G266387W 05/06/1996 Date Of Birth OUTDOOR Occupation Date Of Driving Pass 08/07/2019

0 YEAR AND 5 MONTH Driving Experience

MALE Gender

(LOCAL) +65-88797837 Mobile Number

Fax Number Contact Number

EMail Address NOEMAIL Address

2 YISHUN INDUSTRIAL STREET 1 #06-25

Postcode

S768159

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - U-TURN

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

NO

Was any body injured in the Accident? Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO REPORT ATTACHED.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBE6321J

Vehicle Make/Model/Colour

NA NA

**Details Of Properties** 

COMMERCIAL VEHICLE

Vehicle Category Name of Driver

NA

NRIC/Passport Number

Contact Number

NA

Address

NA NA

Postcode

NA

Insurance Company Name

Nature Of Damage

NA

No. Of Passenger (Including Driver)

Page 2 of 12

#### Accident Sketch Plan Pg. 1

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided most be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
  Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
  interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Oriver's Signature (If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

10 30 AM

De 24/12/2019

# Accident Sketch Plan Pg. 1

SKETCH PLAN	Manda Estat	c lamppost#35
A: 1/ 7779		ten
B: GBE 63		
		ATX
		TA PAR
-		
DESCRIBE CIRCUMSTANCE	S OF THE ACCIDENT	
I driving	the long 22.12.20	019. Night 11:30pm.
that time	long make the	o turn Unfortanous
	he anotherwoodlowny	
that long	y side door glass	all broken.
una door	also bend.	
	***************************************	
	Insurance Co.	Lonpac
	Vehicle XP 7	799 C Date of Accident 27/12/2015
		Reporting Only Own Damace Claim
		Tnird Party Claim
rape-way-		
POLABATION		
ECLARATION  We declare the foregoing part	ciculars are true in every respect.	
(2(40°)	De 24/12/2	019
olicyholder's Signature	Driver's Signature	Reporting Centre Personnel's Signature
ate & Time:	(If driver is not the policyholder) Date & Time: 10: 30 AM	Name:
	10130 711	

MZ300



# LONPAC INSURANCE BHD (598FC5635C)

(Incorporated in Malansia)
Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 199555. Tet: (85) 6250 7388 Fax: (85) 6296 3767 Website: www.ionpac.com.sg GST Reg No.: F0-0009635-C

#### CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION ACT (CAP 189) REPUBLIC OF SINGAPORE. MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE). ROAD TRANSPORT ACT 1987 (MALAYSIA). MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA).

4.

Certificate No. : Z/19/vc00/105364

Type of Cover : COMPREHENSIVE

Index Mark and Vehicle Registration Number

MITSUBISHI CANTER FEB21ER45DEB

- YP 7799C

Name of Policy Holder

LENG WEE CONSTRUCTION PTE LTD

Effective date of the Commencement of Insurance 3. for the purpose of the Act.

14/11/2019

13/11/2020

Date of Expiry of the Insurance Persons or Classes of Persons entitled to drive.

(A) THE POLICYHOLDER. (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/THEIR PERMISSION.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

Limitations as to use

USE IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS. USE FOR THE CARRIAGE OF PASSENGERS (OTHER THAN FOR HIRE OR REWARD) IN CONNECTION WITH THE POLICYHOLDER'S BUSINESS. USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES. THE POLICY DOES NOT COVER: - USE FOR HIRE OR REWARD OR FOR RACING, PACEMAKING, RELIABILITY TRIAL OR SPEED TESTING. USE WHILST DRAWING A TRAILER EXCEPT THE TOWING OF ANY ONE DISABLED MECHANICALLY PROPELLED VEHICLE.

: S\$1400.00 (SECTION 1)

552500.00 (SECTION 1) ADDITIONAL EXCESS FOR YOUNG AND/OR

INEXPERIENCED DRIVERS \$\$100.00 WINDSCREEN EXCESS

(EXCESS WILL BE DOUBLED ON SUBSEQUENT CLAIMS)

Condition

: ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS

Limitations rendered Inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore are not included under

I/We hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore.

H.P. Owner

: DAIMLER FINANCIAL SERVICES AFRICA & ASIA PACIFIC LTD

(Singapore Branch)

User ID

; ambika / nfwong

Date Issued : 04-11-2019

3

Page 1 Of 1















# ANN JOO MOTOR PTE LTD

Blk 176 Sin Ming Drive # 02 -17 Sin Ming Autocare Singapore 575721 Tel No. 64510747 Fax No. 64590747

Email Address: singa\_annjoo@singnet.com.sg Co Reg. No./GST Reg. No. : 200806434E

> M/S TS ENGINEERING WORKS PTE LTD

Cash Bill: SSP1070 Date:17-02-2020 Veh No.: GBE6321J Make/Model: TOY. DYNA

S/N Quantity Particular

Unit Price

Amount S\$

COST OF REPAIR LUMP SUM BASIS

AS PER AEON AUTO CONSULTANTS LLP ASSESSMENT REPORT NO. 0120 / AJ416

\$ 5,100.00

E. & O.E.

Total \$ 5,100.00 GST 7 % \$ 357.00 Amount Due \$ 5,457.00

W

Customer's signature / Co. stamp

for ANN JOO MOTOR PTE LTD

# Enquire Vehicle & Owner Information (Vehicle No. GBE6321J As At 21 Dec 2019 / 00:00:00)

Insurance claim in relation to traffic accident Search Reason:

Law Firm Case No.: 10674

Company Owner ID Type: 201910159K Owner ID:

TS ENGINEERING WORKS PTE. LTD. Owner Name:

Private Residential (Condo Apt or House) / Shopping / Office

Registered Address Type: Complexes

Registered Block/House 6D No.:

Registered Street Name: MANDAI ESTATE

Registered Unit No.:

#01-12

Registered Building

M-SPACE

Name:

ĺ

Registered Postal Code: 729938

Current Vehicle Details

GBE6321J Vehicle No.:

Make Description/Model:TOYOTA / DYNA 3.0 DIESEL TURBO M/T 2WD LORRY

Insurance Company Name:

NTUC INCOME INS CO-OP LTD



Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

24 Dec 2019 / 16:12:28

Receipt Date/Time:

24 Dec 2019 / 16:10:17

Tax Invoice/Receipt

Receipt No.: ITNET-00000-191224-002855

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No. Result of Insurance Enquiry - YP7799C As at 21 Dec 2019/11:30:00		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Insurance Co: LONPAC INSURANCE BHD  1 Insurance Enquiry - YP7799C Enquiry Fee 20191224160844165730		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx7473	Credit Care /Master(		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

#### THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

# Enquire Vehicle & Owner Information (Vehicle No. YP7799C As At 21 Dec 2019 / 00:00:00)

# Law Firm Search Details

Search Reason:

Insurance claim in relation to traffic accident

Law Firm Case No.:

AJ/GBE6321J

# **Current Owner Details**

Owner ID Type:

Company

Owner ID:

201116058N

Owner Name:

LENG WEE CONSTRUCTION PTE. LTD.

Private Residential (Condo Apt or House) / Shopping / Office

Registered Address Type:

Complexes

Registered Block/House

2

No.:

Registered Street Name: YISHUN INDUSTRIAL STREET 1

Registered Unit No.:

#06-25

Registered Building

NORTH POINT BIZHUB

Name:

Registered Postal Code: 768159

# **Current Vehicle Details**


Vehicle No.:

YP7799C

Make Description/Model:MITSUBISHI / CANTER FEB21ER4SDEB

Insurance Company Name:

LONPAC INSURANCE BHD



## INVOICE

TO: TS ENGINEERING WORKS PTE LTD

C/O: ANN JOO MOTOR PTE LTD BLK 176, SIN MING DRIVE #01-17.

SIN MING AUTOCARE SINGAPORE 575721 Invoice No.:

0120/AJ416

Date:

31-Jan-2020

#### **PARTICULARS**

Vehicle Registration No.:

GBE 6321 J

Date of Loss:

21-Dec-2019

Date of Assessment:

02-Jan-2020

SERVICES

FEES

1. Assessment with report Photographs -

Including films, developing, storage and Transport.

\$400.00


TOTAL

\$400.00

# SINGAPORE DOLLARS FOUR HUNDRED ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

### AEON AUTO CONSULTANTS LLP



50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874 Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

### AUTOMOBILE ASSESSMENT REPORT

O: TS ENGINEERING WORKS PTE LTD

:/O: ANN JOO MOTOR PTE LTD

3LK 176, SIN MING DRIVE #01-17.

IN MING AUTOCARE INGAPORE 575721 Our Reference:

0120/AJ416

Date:

31-Jan-2020

ASSESSMENT OF VEHICLE NO. GBE 6321 J

DATE OF LOSS:

21-Dec-2019

We have carried out a physical assessment at ANN JOO MOTOR PTE LTD,

3lk 176, Sin Ming Drive #01-17. Sin Ming Autocare Singapore 575721, according to your instruction

on 02-Jan-2020 and are pleased to submit our report herewith.

#### 1. VEHICLE PARTICULARS

Registration No.:

GBE 6321 J

Make & Model:

TOYOTA DYNA 3.0 DIESEL TURBO M/T 2WD LORRY

Year of Registration:

2016

Engine Capacity:

2982

Chassis No.:

KDY2318022499

Engine No.:

1KD2570844

Colour:

SILVER

### 2. VEHICLE CONDITION

Body Paint:

GOOD

Steering:

SERVICEABLE

Foot Brake:

SERVICEABLE SERVICEABLE

Parking Brake: Modification:

NIL

#### 3. TYRE PARTICULARS & CONDITION

Front

RH Make/Size/Thread:

GT RADIAL 195 R15C - 75%

LH Make/Size/Thread:

GT RADIAL 195 R15C - 75%

Rear

RH Make/Size/Thread:

GT RADIAL 155 R13 - 70%

LH Make/Size/Thread:

GT RADIAL 155 R13 - 70%

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

#### 4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

#### 5. REMARKS

Market Value:

Na

Salvage Value: Repair Limit: Na Na

Estimated Amount:

\$10,297.80

Adjusted Amount:


\$6,382.20

Lump Sum:

\$5,100.00

Estimated Repair Days:

7 days



Pursuant to your instruction, we have NOT AUTHORISED repair.

The assessment was conducted on a "Without Prejudice" basis.

If we are not notified of anything to the contrary within 14 days from the date hereof, this report shall be treated as correct.

#### Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874 Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com Reg. No. LL0701273L (registered with limited liability)

# ASSESSMENT REPORT FOR VEHICLE NO. GBE 6321 J

#### PARTS (LIST ITEMS)

Qtv	Description		Workshop's	Our
		Condition	Estimate	Assessment
1	FRONT RH CORNER GARNISH	Repair	264.00	
1	FRONT RH CORNER PANEL	Repair	342.00	- 2
1	FRONT RH HEADLAMP	Repair	882.50	
1	FRONT RH HEADLAMP LOWER SEAL	Reuse	22.00	
. 1	FRONT BUMPER	Repair	688.50	
2	FRONT BUMPER INNER BRACKET L/R	Repair	184.60	
1.1	FRONT BUMPER INNER REINFORCEMENT	Repair	368.90	-
1	FRONT RH DOOR PILLAR	Repair	435.10	
1	FRONT RH DOOR PILLAR WEATHER STRIP	Cut		5Vr 239.10 X
1	FRONT RH DOOR	Bent		7,57,77
- 1	FRONT RH DOOR SIDE MIRROR	Repair	1,254.10	1,254.10
1	FRONT RH DOOR CHECKER	Bent	735.10	*, ,
1	FRONT RH DOOR GLASS OUTER MOULDING			4 VC 120:10 X
1	FRONT RH DOOR GLASS OUTER VERTICAL GARNISH	Bent	110.35	110.35 /
2	FRONT RH DOOR GLASS OUTER VERTICAL GARNISH CLIPS	Cracked	65.10	65:10 X
2	FRONT RH DOOR HINGES (TOP & LOWER)	Necessary	13.00	
1	FRONT RH DOOR INNER HANDLE	Bent	148.20	148.20 X
1	FRONT RH DOOR INNER LOCK HANDLE	Reuse	211.45	Sove
1	FRONT RH DOOR INNER TRIM BOARD	Reuse	69.10	
1	FRONT RH DOOR LOCK STRIKER	Cracked	690.35	E7 69.0:35 1
1	FRONT RH DOOR LOWER RUBBER SEAL	Bent	43.10	5VC 43/10X
1	FRONT RH DOOR MECHANISM LOCK	Necessary	69.10	69.10
1	FRONT RH DOOR OUTER LOCK HANDLE	Bent	509.10	5 Vc 509:10 X
1	FRONT RH DOOR POWER WINDOW CHANNEL BRACKET	Repair	69.35	
1	FRONT RH DOOR POWER WINDOW CHANNEL BRACKET	Bent	65.10	65.10 X
1	FRONT RH DOOR POWER WINDOW CHANNEL BRACKET WEATHER STRIP	Cracked	165.10	VC   165-10 Y
1	FRONT RH DOOR POWER WINDOW MAIN CONTROL SWITCH	Faulty	435.10	435:10 X
1	FRONT RH DOOR POWER WINDOW MOTOR	Faulty	543.10	543:10 X
1	FRONT RH DOOR POWER WINDOW REGULATOR	Bent	209.10	209.10
1	FRONT RH DOOR RUBBER GUIDE STOPPER	Bent	110.30	110/30 X
1	FRONT RH DOOR SIGNAL LAMP	Cut	65.10	
1	FRONT RH DOOR WEATHER STRIP	Cut	175.10	175.40 X
1	FRONT RH DOOR STEP GARNISH	Repair	210.10	
-	FRONT RH MUD GUARD	Repair	258.10	2

2229.65

9,770.40 5,029.60 Less 25% discount 2,442.60 1,257.40 Parts Total: 7,327.80 3,772.20

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874 Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com Reg. No. LL0701273L (registered with limited liability)

### ASSESSMENT REPORT FOR VEHICLE NO. GBE 6321 J

#### SPECIAL NETT ITEMS

				22
		Special Nett Total :	390.00	390.00
1	FRONT RH DOOR SPEAKER	Faulty	180.00 5	VC 180,00;
1	FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	Necessary	30.00	30.00
1	FRONT RH DOOR COMPANY DETAILS STICKER	Necessary	180.00	25 180:00

LABOU	JR		
S/N	Description	Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing.	120.00	×100.00
2	To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	160.00	60 148.00
3	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.		~ c 90e.co
4	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re- align body structure, body alignments and damaged consistent to the accident.	1,200.00 🤉	LOC 1,000.00
5	To apply anti-rust chemical on repaired and replaced panel.	100.00	× 89.60
	Labour Total :	2,580.00	2,220.00
	TOTAL (PARTS & LABOUR) \$	10,297.80	6,382.20

The workshop has agreed to undertake the repair on a Lump Sum basis. The final adjusted Lump Sum contract amount is

\$5,100.00

(SINGAPORE DOLLARS FIVE THOUSAND ONE HUNDRED ONLY)

Amas Onig Automobile Assessor 20%: 1750 31/mp.

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com
Reg. No. LL0701273L (registered with limited liability)

# ASSESSMENT REPORT FOR VEHICLE NO. GBE 6321 J

### PARTS (LIST ITEMS)

1 Ait I S			Workshop's	Our
Qty	Description	Condition	Estimate	Assessment
0.000	1. 2020/2017/00/2014	Repair	264.00	-
1	FRONT RH CORNER GARNISH FRONT RH CORNER PANEL	Repair	342.00	-
323	FRONT RH HEADLAMP	Repair	882.50	-
1	FRONT RH HEADLAMP LOWER SEAL	Reuse	22.00	100
1	FRONT BUMPER	Repair	688.50	162
2	FRONT BUMPER INNER BRACKET L/R	Repair	184.60	
100	FRONT BUMPER INNER REINFORCEMENT	Repair	368.90	-
1	FRONT BH DOOR PILLAR	Repair	435.10	22.5
1	FRONT RH DOOR PILLAR WEATHER STRIP	Cut	239.10	239.10
- 23	FRONT RH DOOR	Bent	1,254.10	1.254.10
1		Repair	735.10	7675 /190
1	FRONT RH DOOR SIDE MIRROR FRONT RH DOOR CHECKER	Bent	120.10	120.10
1		Bent	110.35	
1	FRONT RH DOOR GLASS OUTER MOULDING FRONT RH DOOR GLASS OUTER VERTICAL GARNISH	Cracked	65.10	
1	FRONT RH DOOR GLASS OUTER VERTICAL GARNISH	Necessary	13.00	773133
2	FRONT RH DOOR GLASS OUTER VERTICAL GARNISH CLIPS	Bent	148.20	
2		Reuse	211.45	
1	FRONT RH DOOR INNER HANDLE FRONT RH DOOR INNER LOCK HANDLE	Reuse	69.10	
1	FRONT RH DOOR INNER TRIM BOARD	Cracked	690.35	
1		Bent	43.10	
1	FRONT BY DOOR LOWER BURBER SEAL	Necessary	69.10	
1	FRONT RH DOOR LOWER RUBBER SEAL	Bent	509.10	
1	FRONT RH DOOR MECHANISM LOCK	Repair	69.35	
1	FRONT RH DOOR OUTER LOCK HANDLE		65.10	
1	FRONT RH DOOR POWER WINDOW CHANNEL BRACKET	Bent Cracked	165.10	
1	FRONT RH DOOR POWER WINDOW CHANNEL BRACKET WEATHER STRIP	Faulty	435.10	
1	FRONT RH DOOR POWER WINDOW MAIN CONTROL SWITCH	0.0000000000000000000000000000000000000	543.10	
1	FRONT RH DOOR POWER WINDOW MOTOR	Faulty	209.10	
1	FRONT RH DOOR POWER WINDOW REGULATOR	Bent Bent	110.30	
1		Cut	65.1	
1	FRONT RH DOOR SIGNAL LAMP	Cut	175.1	
1		Repair	210.1	
1	[1] [1] [1] [1] [1] [1] [2] [2] [2] [3] [3] [3] [4] [4] [4] [4] [4] [4] [4] [4] [4] [4	W.	258.1	
1	FRONT RH MUD GUARD	Repair	250.1	v 3)
			9,770.4	0 5,029.60
		Less 25% discount	2,442.6	0 1,257.40
		Parts Total:	7,327.8	0 3,772.20

n	1	-	-	-2
×				

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874

Telephone +65 97687958 Facsimile +65 68264112 Email info@aeonac.com

Reg. No. LL0701273L (registered with limited liability)

### ASSESSMENT REPORT FOR VEHICLE NO. GBE 6321 J

#### SPECIAL NETT ITEMS

1	FRONT RH DOOR COMPANY DETAILS STICKER	Necessary	180.00	180.00
1	FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	Necessary	30.00	30.00
1	FRONT RH DOOR SPEAKER	Faulty	180.00	180.00
		Special Nett Total :	390.00	390.00

Δ		

LABO	JR	Workshop's	Our
S/N	Description		Assessment
1	To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing.	120.00	100.00
2			140.00 900.00
3			
4	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re- align body structure, body alignments and damaged consistent to the accident.	1,200.00	1,000.00
5	To apply anti-rust chemical on repaired and replaced panel.	100.00	80.00
	Labour Total :	2,580.00	2,220.00
	TOTAL (PARTS & LABOUR) \$	10,297.80	6,382.20

The workshop has agreed to undertake the repair on a Lump Sum basis. The final adjusted Lump Sum contract amount is

\$5,100.00

(SINGAPORE DOLLARS FIVE THOUSAND ONE HUNDRED ONLY)



Amas Ong Automobile Assessor



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

1		Affiliated to Federation Internation	nale Des Experts En Automol	bile
ONE	PAC INSURANCE	BHD	Ref : CS3/LPC1902286	61/Gtd3s2-1
800 E \$17-0	BEACH ROAD 04/07 THE CONC	DURSESINGAPORE 199555	Date: 24-03-2020 Code: LPC2	
		Policy Particulars	:- THIRD PARTY CLAIM	
1000001	Insured Veh.	YP 7799C	Veh. Inspected	GBE 6321J
	Policy No.	Z/19ZVC00/105364	Coverage (\$)	0.00
	Claim No.	19/19/20/VC00/022819	Excess (\$)	0.00
	Assign From	GERALD POH	Assign Date	05/03/2020
2.		Vehicle Parti	culars & Condition	
	Make & Model	TOYOTA DYNA 3.0	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KDY2318022499	Colour	SILVER
	Odometer	169600	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3.	OF STREET	Condit	ions of Tyres	<b>为原作的</b> 对对是不可怜
		Size	Make	Balance
	R/H Front Tyre	195 R15	GT RADIAL	5 mm
	L/H Front Tyre	195 R15	GT RADIAL	5 mm
	R/H Rear Tyre	155 R13	MAXMILER	5 mm
	L/H Rear Tyre	155 R13	MAXMILER	5 mm
4.			ion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S	S FRONT PORTION.	
	DAMAGES SEE D	ETAILS.		
5.		Genera	al Information	
	Accident Date	21/12/2019	Inspection Date	02/01/2020
	Survey held at	ANN JOO MOTOR SERVICES		
		BLK 176, SIN MING DRIVE #01-17 SIN MING AUTOCARE SINGAPORE 575721		
5a.	THE PARTY		Remarks	
	A)THE INSPECTION B)IN ACCORDAN	ON WAS CONDUCTED ON A'WI CE TO YOUR INSTRUCTIONS, V	VE HAVE NOT AUTHORISE	S. ED REPAIRS.
5b.		THE RESIDENCE OF THE PARTY OF T	Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Working Days	3



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

# ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 6321J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT RH CORNER GARNISH	TO REPAIR SEE LABOUR	264.00	15
1	FRONT RH CORNER PANEL	TO REPAIR SEE LABOUR	342.00	85
1	FRONT RH HEADLAMP	TO REPAIR SEE LABOUR	882.50	
1	FRONT RH HEADLAMP LOWER SEAL	REUSE	22.00	-
	FRONT BUMPER	TO REPAIR SEE LABOUR	688.50	-
2	FRONT BUMPER INNER BRACKET L/R	TO REPAIR SEE LABOUR	184.60	12.7
1	FRONT BUMPER INNER REINFORCEMENT	TO REPAIR SEE LABOUR	368.90	
1	FRONT RH DOOR PILLAR	TO REPAIR SEE LABOUR	435.10	
1	FRONT RH DOOR PILLAR WEATHER STRIP	SERVICEABLE	239.10	·
1	FRONT RH DOOR	BENT	1,254.10	1,254.10
1	FRONT RH DOOR SIDE MIRROR	TO REPAIR SEE LABOUR	735.10	-
	FRONT RH DOOR CHECKER	SERVICEABLE	120.10	1
	FRONT RH DOOR GLASS OUTER MOULDING	BENT	110.35	110.35
	FRONT RH DOOR GLASS OUTER VERTICAL GARNISH	SERVICEABLE	65.10	
2	FRONT RH DOOR GLASS OUTER VERTICAL GARNISH CLIPS	SERVICEABLE	13.00	
	FRONT RH DOOR HINGES (TOP & LOWER)	SERVICEABLE	148.20	
	FRONT RH DOOR INNER HANDLE	SERVICEABLE	211.45	5
100	FRONT RH DOOR INNER LOCK HANDLE	SERVICEABLE	69.10	9
3	FRONT RH DOOR INNER TRIM BOARD	CRACKED	690.38	587.00
133	FRONT RH DOOR LOCK STRIKER	SERVICEABLE	43.10	1
	FRONT RH DOOR LOWER RUBBER SEAL	NECESSARY	69.10	69.10
173	FRONT RH DOOR MECHANISM LOCK	SERVICEABLE	509.10	
13	FRONT RH DOOR OUTER LOCK HANDLE	TO REPAIR SEE LABOUR	69.3	5
8	FRONT RH DOOR POWER WINDOW CHANNEL BRACKET	SERVICEABLE	65.10	
	FRONT RH DOOR POWER WINDOW CHANNEL BRACKET WEATHER STRIP	SERVICEABLE	165.10	
	1 FRONT RH DOOR POWER WINDOW MAIN CONTROL SWITCH	SERVICEABLE	435.1	

Report Ref No. CS3/LPC19022861/Gtd3s2-1



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RH DOOR POWER WINDOW MOTOR	SERVICEABLE	543.10	-
	FRONT RH DOOR POWER WINDOW REGULATOR	BENT	209.10	209.10
	FRONT RH DOOR RUBBER GUIDE STOPPER	SERVICEABLE	110.30	10
	FRONT RH DOOR SIGNAL LAMP	SERVICEABLE	65.10	-
0.00	FRONT RH DOOR WEATHER STRIP	SERVICEABLE	175.10	S-
	FRONT RH DOOR STEP GARNISH	TO REPAIR SEE LABOUR	210.10	12
1	FRONT RH MUD GUARD	TO REPAIR SEE LABOUR	258.10	3/2
	LESS 25% DISCOUNT		-2,442.60	-557.42
			7,327.80	1,672.23
	SPECIAL NETT ITEMS		5.000	2705-223
1	FRONT RH DOOR COMPANY DETAILS STICKER (SN)	NECESSARY	180.00	1
1	SET FRONT RH DOOR INNER TRIM BOARD CLIPS (SN)	NECESSARY	30.00	30.00
1	FRONT RH DOOR SPEAKER (SN)	SERVICEABLE	180.00	
	5.50		390.00	55.00
	LABOUR	NAMES OF TAXABLE PROPERTY OF TAXABLE PARTY.		
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING.	NOT NECESSARY	120.00	
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE.		160.00	60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		1,000.00	200.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RECONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT RH CORNER GARNISH, FRONT RH CORNER PANEL, FRONT		1,200.00	200.00
	RH HEADLAMP, FRONT BUMPER, FRONT BUMPER INNER BRACKET L/R, FRONT BUMPER INNER REINFORCEMENT, FRONT RH DOOR PILLAR, FRONT RH DOOR SIDE MIRROR, FRONT RH DOOR OUTER LOCK HANDLE, FRONT RH DOOR STEP GARNISH AND FRONT RH MUD GUARD.			
	TO APPLY ANTI-RUST ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	100.00	(2)
			2,580.0	460.00

Report Ref No. CS3/LPC19022861/Gtd3s2-1



Page No.:3 of 3

GRAND TOTAL	10,297.80	2,187.23
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		1,750.00

Report Ref No. CS3/LPC19022861/Gtd3s2-1

XING GUO QIANG

M.MATAI, AMSAE-A

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Automotive Assessor Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.