

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

14514

04/03/2020

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0078/2020
DATE : 04-MAR-2020

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-05 IOB BUILDING
S(049711)
TEL : 63476100
FAX : 62244174
ATTN:MOTOR CLAIM MANAGER

DIRECT SETTLEMENT
OWNER CLAIMING LOSS OF USE / RENTAL
CAR AT WORKSHOP / CAR NOT AT WORKSHOP
KINDLY REVERT TO ME ASAP
EMAIL : lawrenceteo@tanchong.com
H/P : 94568832 FAX : 64697472

OWNER'S NAME : GOH LU SI
ADDRESS : 58 BAYSHORE ROAD
#02-01
S(469981)
TELEPHONE NO : 98191018

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBH206H
VEHICLE NO : SLK4811A
MODEL CODE : TDWARDZE12EDAY407Z
MODEL/YEAR : NISSAN NOTE 1.2 BASE
ENGINE NO : HR12214766B
CHASSIS NO : JN1TAAE12Z0972566
MILEAGE : 1 KM
DATE IN : 04/03/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 03/03/2020

CAR IN
LKLW

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLK4811A

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	120
2 RRMLB	TO RENEW REAR MULTI LINK BEAM	240.00	X
3 RRUC	REMOVE/REFIX WHOLE UNDERCARRIAGE MECHANICAL PARTS PER SIDE LH REAR	480.00	X
4 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	200
5 WD42	CHECK WHEEL ALIGNMENT, ADJUST WHERE NECESSARY AND TEST DRIVE VEHICLE	103.00	X
6 ZZ/001	REPAIR LH REAR FENDER, LH CENTER PILLAR AND RENEW LH FRONT/REAR DOOR. <i>2 Rear 390 X 2.5</i>	1500.00	975
7 ZZ/002	S/PAINT LH REAR FENDER, LH CENTER PILLAR, LH FRONT/REAR DOOR. <i>1 Rear 250 X 4</i>	1500.00	1000
8 ZZ/003	RENEW LH REAR S/RIM AND CONDUCT WHEEL BALANCING	15.00	X
9 ZZ/004	TRANSFER LH FRONT/REAR DOOR MECHNICAL PARTS TO NEW DOOR \$60/DOOR X 02	120.00	/
10 ZZ/005	SUPPLY AND RENEW LH REAR TYRE CONTI CONTACTS 185/65R15		
TOTAL LABOUR CHARGES		4378.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLK4811A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	MOTOR ASSY-REGU LH REAR X	82730-1VA0A	568.10		
2	REGULATOR-DOOR LH REAR ?	82721-3VA0B	96.20		
3	TAPE-RR DOOR, LH / NK	82817-3VA0A	19.50		
4	TAPE-RR DOOR, LH / NK	82819-3VA0A	25.50		
5	DOOR-REAR LH / DD	H210A-3VAMA	919.60		
6	STRIKER LH FRONT DOOR X	80570-AA10A	59.70		
7	LOCK & REMOTE C LH FRONT / BT	80501-3VA0A	189.50		
8	GASKET HANDLE OUTSIDE LH FRONT / NK	80652-1FA0A			2.40
9	GASKET HANDLE DOOR LH FRONT / NK	80654-1FA1A			4.90
10	GRIP-OUTSIDE LH FRONT / CH	80640-3VA2A	98.40		
11	ESCUT-OUTSIDE HANDLE LH FRONT / CH	82646-3VA4A	19.50		
12	MOTOR ASSY-REG LH FRONT ?	80731-1HH0B	568.10		
13	REGULATOR-DOOR LH FRONT ?	80721-5WH0A	137.30		
14	TAPE-FR DOOR, LH / NK	80817-3VA0B	19.50		
15	TAPE-FR DOOR, LH / NK	80819-3VA0A	19.50		
16	DOOR-FRONT LH / DD	H010A-3VAMA	919.60		
17	BUSH SHOCK ABS X	56217-AX000			16.20
18	TUBE-DISTANCE X	55323-1KA0A			12.80
19	BUSH SHOCK ABS X	56217-1HJ0A			16.20
20	BUMPER-SUSPENS X	55240-5VA0A			91.30
21	ABSORBER-SHOCK X	E6210-3VJ2A			60.30
22	SEAT SPRING UPPER X	55034-1HJ0B			22.90
23	SEAT SPRING LOWER X	55032-1HJ0A			15.60
24	BEAM X	55501-3VA1A			1018.10
25	SPINDLE-REAR X	43042-1HA0A			73.50

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLK4811A

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
26	A BRG RR WHEEL X	43210-1HA1A			88.10	
27	185/65R15OE CONTI-CC5 LH REAR X	185/65R15CC5			160.00	
28	SUNDRIES	NPN		20	100.00	
29	ALLOY RIM LH REAR X	40300-0SK92			280.00	
SUB TOTAL			3660.00	0.00	1962.30	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			732.00	0.00	0.00	
GRAND TOTAL			2928.00	0.00	1962.30	
OVERALL TOTAL			4890.30			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLK4811A

TOTAL LABOUR CHARGES	4378.00
TOTAL SPARE PARTS CHARGES	4890.30
GRAND TOTAL	9268.30 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Steve (LKK)

WHL Phil

5/3/20, 11.45am

P/P

Ry BpL SN

4 dgs

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: