

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: 2 September 2020 5:06 PM
To: 'wonglb4588@gmail.com'
Cc: Admin A; 'doris_lim@cdgtaxi.com.sg'; 'Jason Tea'
Subject: D20001311MFSH CTPL TPD1 JN - CT20030050 SHC2059H DOA: 03/03/2020 Our Reply to Insd Driver
Attachments: Photo 1.JPG; Photo 2.jpg; Photo 3.jpg; Photo 4.jpg; Photo 5.jpg; Photo 6.jpg; Photo 7.jpg

Dear Mr. Wong,

We refer to the above matter and your telephone conversation with our surveyor Mr. Taufikh.

Our surveyor has already seen your accident video footage and accident report and he is of the opinion that the damages to the third party vehicle are consistent to the nature of accident reported.

As requested, we attach here with the damage photos during our inspection and our surveyor's explanation is below:-

- Photo No 3 and 4 shows the screw that was attached to the front bumper was pulled off.
- Photo 4 also shows the hole that was damaged on the front bumper. The number plate was screwed onto the bumper so when your taxi reversed and its side hit onto the front bumper with the number plate, it pulled of the number plate from the front bumper causing the big hole to the third party vehicle.
- Photo No 5 is the radiator grille and Photo No 6 shows closeup that it was a cut graze.

Should you have any queries, kindly let us have them in writing within the next 7 days and we will seek further instruction from M/s First Capital.

Thank you.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: **6841 2360** | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason Tea <JasonTea@msfirstcapital.com.sg>
Sent: 25 August 2020 9:03 AM
To: Wong L B <wonglb4588@gmail.com>; Khanchna (LKK Auto) <khanchna@lkkauto.com>
Cc: Doris Lim Puay Noi <doris_lim@cdgtaxi.com.sg>
Subject: RE: D20001311MFSH CTPL TPD1 JN - CT20030050 SHC2059H DOA: 03/03/2020 Our Reply to Insd Driver

Dear Mr Wong,