

## SERVICE ESTIMATE

92832 - C00001 SL: SERVICE SALES - PC

Ms Lee Yu Ying, Carrie-Ann  
23 Pasir Ris Link  
#11-08

Singapore 518169

Closed by .... : Richmond Ho  
Svc Consultant :  
Remarks ..... : Ms Lee Yu Ying, Carr

GST Reg.No:M28920628X  
Inv.No. . : B&P 0 Page 1  
Inv.date. : 04/03/2020  
WIP No. . : 12291  
Veh.In/Out:  
\*Tel.No. . : Mobile: 97764600  
Reg.No. . : SCQ5599G  
Reg.date . : 25/09/2017  
Mileage ... : 0  
Chassis No: YV1PS10BDH1011515

| Op.No | Description                                                | Mech Qty | Price   | Disc% | Pkg | Amount     | G    |
|-------|------------------------------------------------------------|----------|---------|-------|-----|------------|------|
| 802   | TO REPLACE FRONT BUMPER,FRT BRACKET,FRT GRILL,ETC          | 0        | 2400.00 | 0     |     | 2,400.00 S | 800  |
| R06   | TO INSTALL FRONT NUMBER PLATE INCLUDE HOLDER               | 0        | 60.00   | 0     |     | 60.00 S    | ✓    |
| 800   | TO PUTTY SPRAY PAINT ON FRT BUMPER,ETC                     | 0        | 1400.00 | 0     |     | 1,400.00 S | 700  |
| 280   | TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES | 0        | 495.00  | 0     |     | 495.00 S   | ✓    |
|       | RADIATOR GRILLE T5 S                                       | 1.0 EA   | 893.60  |       |     | 893.60 S   | CR ✓ |
|       | BUMPER COVER FRT SV9                                       | 1.0 EA   | 1789.50 |       |     | 1,789.50 S | de ✓ |
|       | BUMPER SPOILER FRT T                                       | 1.0 EA   | 502.80  |       |     | 502.80 S   | Rx   |
|       | BUMPER FOAM FRT SV9                                        | 1.0 EA   | 393.40  |       |     | 393.40 S   | ?    |
|       | BUMPER BRACKET LHF S                                       | 1.0 EA   | 37.70   |       |     | 37.70 S    | ?    |
|       | BUMPER BRACKET RHF S                                       | 1.0 EA   | 37.70   |       |     | 37.70 S    | ?    |
|       | HINGE WASHER LH T6 S                                       | 1.0 EA   | 53.70   |       |     | 53.70 S    | x    |
|       | HINGE WASHER T6 S90                                        | 1.0 EA   | 53.70   |       |     | 53.70 S    | x    |

2055

X  
nn

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tauhin 97495449

- WP  
30/3/2020

03 days

Resurvey before paint

Tauhin@lkhauto.com

Svc C lkhauto.com

### SERVICE ESTIMATE

92832 - C00001      SL: SERVICE SALES - PC  
 Ms Lee Yu Ying, Carrie-Ann  
 23 Pasir Ris Link  
 #11-08

Singapore 518169

Closed by .... : Richmond Ho  
 Svc Consultant :  
 Remarks ..... : Ms Lee Yu Ying, Carr

GST Reg.No:M28920628X  
 0 Page 2  
 Inv.No. . : B&P  
 Inv.date. : 04/03/2020  
 WIP No. . : 12291  
 Veh.In/Out:  
 \*Tel.No. . : Mobile: 97764600  
 Reg.No. . : SCQ5599G  
 Reg.date. : 25/09/2017  
 Mileage . : 0  
 Chassis No: YV1PS10BDH1011515

| Op.No | Description          | Mech Qty | Price  | Disc% | Pkg | Amount                     | G |
|-------|----------------------|----------|--------|-------|-----|----------------------------|---|
|       | HINGE BRACKET WASHER | 1.0 EA   | 65.60  |       |     | 65.60 S x                  |   |
|       | HINGE BRACKET WASHER | 1.0 EA   | 53.70  |       |     | 53.70 S x                  |   |
|       | BRACKET              | 1.0 EA   | 128.20 |       |     | 128.20 S x                 |   |
|       | BRACKET              | 1.0 EA   | 128.20 |       |     | 128.20 S x                 |   |
|       | BUMPER BRACKET LHF S | 1.0 EA   | 53.70  |       |     | 53.70 S x                  |   |
|       | BUMPER BRACKET RHF S | 1.0 EA   | 156.20 |       |     | 156.20 S x                 |   |
|       | BUMPER BRACKET FRT C | 1.0 EA   | 156.20 |       |     | 156.20 S x                 |   |
|       | RADIATOR GRILLE T5 S | 1.0 EA   | 893.60 |       |     | 893.60 S <i>Replaced X</i> |   |
|       | BRACKET              | 1.0 EA   | 50.70  |       |     | 50.70 S x                  |   |
|       | TOW COVER FRT SV90 1 | 1.0 EA   | 75.40  |       |     | 75.40 S x                  |   |
|       | BUMPER BRACKET LHF S | 1.0 EA   | 151.20 |       |     | 151.20 S x                 |   |
|       | BUMPER BRACKET RHF S | 1.0 EA   | 151.10 |       |     | 151.10 S x                 |   |
|       | PARK HOLDER LH SV90  | 1.0 EA   | 62.40  |       |     | 62.40 S <i>re-</i>         |   |
|       | PARK HOLDER RH SV90  | 1.0 EA   | 62.40  |       |     | 62.40 S <i>re-</i>         |   |
|       | DECOR FRAME COVER XC | 1.0 EA   | 20.50  |       |     | 20.50 S x                  |   |
|       | BUMPER COVER LH T5 S | 1.0 EA   | 93.80  |       |     | 93.80 S x                  |   |
|       | BUMPER COVER RH T5 S | 1.0 EA   | 93.80  |       |     | 93.80 S x                  |   |

### SERVICE ESTIMATE

92832 - C00001 SL: SERVICE SALES - PC  
 Ms Lee Yu Ying, Carrie-Ann  
 23 Pasir Ris Link  
 #11-08

Singapore 518169

Closed by .... : Richmond Ho  
 Svc Consultant :  
 Remarks ..... : Ms Lee Yu Ying, Carr

GST Reg.No:M28920628X  
 Inv.No. . : B&P 0 Page 3  
 Inv.date. : 04/03/2020  
 WIP No. . : 12291  
 Veh.In/Out:  
 \*Tel.No. . : Mobile: 97764600  
 Reg.No. . : SCQ5599G  
 Reg.date. : 25/09/2017  
 Mileage . : 0  
 Chassis No: YV1PS10BDH1011515

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|-------------|----------|-------|-------|-----|--------|---|
|-------|-------------|----------|-------|-------|-----|--------|---|

|                      |         |                      |  |  |  |                 |     |
|----------------------|---------|----------------------|--|--|--|-----------------|-----|
| Front decor frame TR | 1.0 EA  | 114.00               |  |  |  | 114.00 S x nn   |     |
| Front decor frame TR | 1.0 EA  | 114.00               |  |  |  | 114.00 S x nn   |     |
| PARK HOLDER CTR LH S | 1.0 EA  | 48.20                |  |  |  | 48.20 S x nclv  |     |
| PARK HOLDER CTR RH S | 1.0 EA  | 42.20                |  |  |  | 42.20 S x nclv  |     |
| BUMPER GRILLE LOWER  | 1.0 EA  | 232.70               |  |  |  | 232.70 S x }    | nnX |
| BUMPER GRILLE LH S90 | 1.0 EA  | 266.10               |  |  |  | 266.10 S x }    |     |
| BUMPER GRILLE RH S90 | 1.0 EA  | 266.10               |  |  |  | 266.10 S x }    |     |
| CLIP CHROME MOULDING | 10.0 EA | <del>4.70</del> 4.80 |  |  |  | 48 47.00 S nclv |     |
| BUMPER CLIP S80 07-  | 10.0 EA | 4.90                 |  |  |  | 49.00 S nclv    |     |
| BUMPER RAIL (BEAM) F | 1.0 EA  | 1260.80              |  |  |  | 1,260.80 S x nn |     |
| BUMPER CLIP 8x8,5    | 10.0 EA | 5.50                 |  |  |  | 55.00 S nclv    | nn  |
| SIX PT SOCKET SCREW  | 10.0 EA | 7.80                 |  |  |  | 78.00 S x nn    |     |
| EXTERIOR ADHESIVE GL | 2.0 EA  | 145.00               |  |  |  | 290.00 S x nn   |     |

Gross Total. 13,376.90

Labour Total 4,355.00  
 Parts Total 9,021.90  
 Package Total 0.00

Net..... 13,376.90  
 GST @ 7.0% 936.38  
 Total..... 14,313.30  
 Paid..... 0.00  
 Please Pay.. 14,313.30

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

2995.30  
 10% 2695.77

2695.77  
 2055

\$4750.77

03 days #