



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2005549  
INV Date 13/08/2020  
Reference CC4/FCI20003649/Kba3n2  
Code FCI2



### PROFESSIONAL SERVICE FEE

Vehicle No. SMM 1342J  
Insured Veh. SHA 8829Z  
Claim No. D20001300MFSH  
Policy No. D-20094921MFSH  
Accident Date 01/03/2020  
Inspection Date 11/03/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20003649/Kba3n2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-08-2020



Code : FCI2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8829Z	Veh. Inspected	SMM 1342J
Policy No.	D-20094921MFSH	Coverage (\$)	0.00
Claim No.	D20001300MFSH	Excess (\$)	0.00
Assign From	RACHEL WU	Assign Date	05/03/2020

#### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA NOAH (A)	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	ZWR800382120	Colour	METALLIC PEARL WHITE
Odometer	78695	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	GOODYEAR	8 mm
L/H Front Tyre	195/65 R15	GOODYEAR	8 mm
R/H Rear Tyre	195/65 R15	GOODYEAR	8 mm
L/H Rear Tyre	195/65 R15	GOODYEAR	8 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY.

DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	01/03/2020	Inspection Date	11/03/2020
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 1342J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT FENDER 'HYBRID' EMBLEM RH	NECESSARY	78.50	78.50
8	FRONT BUMPER CLIPS @\$5.50	NECESSARY	44.00	44.00
1	FRONT DOOR RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-30.62	-30.62
			91.88	91.88
	<b><u>LABOUR</u></b>			
	LABOUR CHARGES TO REMOVE ,REPLACE ,REPAIR ,REFIX & READJUST ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF FRONT DOOR RH ,FRONT FENDER RH AND FRONT BUMPER.		300.00	200.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER ,FRONT FENDER RH ,FRONT DOOR RH & ETC.		900.00	660.00
			1,200.00	860.00
<b>GRAND TOTAL</b>			<b>1,291.88</b>	<b>951.88</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>951.88</b>

Report Ref No. CC4/FCI20003649/Kba3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMM 1342J

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

